October 23 Change Log

GENERAL INFORMATION

1. The latest **OBD Supported Vehicle** (2023-10-09) lists were updated

- https://wiki.teltonika-gps.com/view/OBD_supported_vehicle_list

2. **TLS/DTLS** implementation for **Flespi** using **OpenSSL** is now available on our public wiki page, you can find the page in our FAQ under a new category **"Encryption"**.

- https://wiki.teltonika-gps.com/view/TLS/DTLS_implementation_for_Flespi_using_OpenSSL
- https://wiki.teltonika-gps.com/view/Frequently_Asked_Questions_-_FAQ

3. **Flespi** has added **DashCam** and **DualCam** support.

- https://wiki.teltonika-gps.com/view/DashCam_Integration_on_platfroms#Integration_on_platforms
- https://wiki.teltonika-gps.com/view/DualCam_Integration_on_platfroms

FIRMWARE ERRATA / CONFIGURATOR

1. New firmware version for the device **FMX640** 01.02.17.Rev.158 was relased

- https://wiki.teltonika-gps.com/view/DSM_Firmware_errata

CREATED PAGES

1. New Wiki pages have been added, describing features that improve battery life of **TAT100** and **TAT140** devices

- https://wiki.teltonika-gps.com/view/Maximize_battery_life_of_asset_trackers

2. Added new page describing how to add log filters and take a log from a device through **FOTA WEB, Terminal.exe, Teltonika Configurator** and etc.

- https://wiki.teltonika-gps.com/view/How_to_capture_direct_log_from_FM_device%3F

3. Wiki page for **FMx650 Beacon List** has been updated.
Changes: deleted information about the new parsing since the new format is not ported on **FMx650** yet. Information about old parsing is left, only the reference to specific firmware was deleted.

- https://wiki.teltonika-gps.com/view/FMC650_Beacon_List
- https://wiki.teltonika-gps.com/view/FMM650_Beacon_List