FMB003 Product Change Notifications

[Main Page](#) > [OBD Trackers](#) > [FMB003](#) > **FMB003 Product Change Notifications**

Product change notifications (**PCN**) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMB003 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

☐

Contents

2024.08.22: Base firmware update

We would like to inform you about the base firmware update for FMB003 starting from September 1st, 2024. New production firmware version will be 03.29.00.Rev.359

Change description

Change type	Firmware update	
	Key improvements from last production firmware are listed in errata: [FMB003_firmware_errata](#)	
Detailed description	Old version: FMB003 03.28.03.Rev.97	New version: FMB003 03.29.00.Rev.359
Change reasons	FMx00x base firmware version update	
Product release date	2024 August	

Affected products

Model	Affected order codes	Order code changes
FMB003	FMB003******* order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

Acknowledgement of PCN receipt	If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2024.05.24: New packaging of OBD devices

We would like to inform you, that packaging of the FMB003 device will be updated in the factory from June 2024.

Change description

Change type	External/visual

Detailed description	Additional spacer was added inside the box (applicable to all order codes with SPQ 1) to secure device in place while shipping and create more pleasant unboxing experience. Old version: New version:
Change reasons	Due to device being too lose in SPQ 1 box, additional spacer has been added.
Product release date	June 2024

Affected products

Model	Affected order codes	Order code changes
FMB003	All order codes with SPQ 1: FMB00377**** FMB003OE****	New packaging

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Change instructions and update promotional material if required.

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2023.04.12: Base firmware update

We would like to inform you about the base firmware update for FMB003 starting from April 12th, 2023. New production firmware version will be 03.28.03.Rev.97

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: [FMB003_firmware_errata](#)	
	Old version: FMB003 03.28.03.Rev.94	New version: FMB003 03.28.03.Rev.97
Change reasons	FMx003 base firmware version update	
Product release date	2023 April	

Affected products

Model	Affected order codes	Order code changes
FMB003	FMB003******* order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.
Acknowledgement of PCN receipt	If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2022.12.12: Base firmware update

We would like to inform you, that laser printing of the FMB003 device was updated in the factory on December 2022.

Change description

Change type	External/visual	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB003_firmware_errata	
	Old version: 	New version:
Change reasons	1. Added ANATEL label and certificate number.	
Product release date	December 2022	

Affected products

Model	Affected order codes		Order code changes
FMB003	FMB003*******		New casing

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

Acknowledgement of PCN receipt — If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2022.04.27: Base firmware update

We would like to inform you about the base firmware update for FMB003 starting from April 27th, 2022. New production firmware version will be 03.27.12.Rev.93

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB003_firmware_errata	
	Old version:	New version:
	FMB003 03.27.07.Rev.94	FMB003 03.27.12.Rev.93
Change reasons	FMB003 base firmware version update	
Product release date	2022 April	

Affected products

Model	Affected order codes	Order code changes
FMB003	FMB003******* order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2021.09.16: Base firmware update

We would like to inform you about the base firmware update for FMB003 starting from September 13th, 2021. New production firmware version will be 03.27.07.Rev.94

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB003_firmware_errata	
	Old version:	New version:
	FMB003 03.25.17.Rev.95	FMB003 03.27.07.Rev.94
Change reasons	FMB003 base firmware version update	
Product release date	2021 September	

Affected products

Model	Affected order codes	Order code changes
FMB003	FMB003******* order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2020.12.11: New FMB003, FMB002, FMB020 casing

Effective December 2020, FMB003, FMB002, FMB020 trackers will be shipped with a new casing.

Change description

Change type	Casing	
	Reduced length to make it even a smaller OBD device.	
Detailed description	Old Version:	New Version:
	[x]	[x]
	Dimensions: 52.6 (L) x 29.1 (W) x 26 (H)	**Dimensions:** 49.6 (L) x 29.1 (W) x 26 (H)

Change reasons	New device casing fits better on some vehicle models where OBD port is obstructed by additional plastic parts from vehicle dashboard front panel.	
Product release date	Devices with new casing will be released in manufacturing from November.	

Affected products

Model	Current codes	New order codes
FMB003, FMB002, FMB020.	FMB003**M7******, FMB002**8M******, FMB020**E1******.	FMB003**OE******, FMB002**Z1******, FMB020**4M******.

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan.	Due to the new look of casing we recommend to update your marketing materials. Because of the new casing, if necessary, update your branding materials (stickers, logo layouts).

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above