# FMM001 Product Change Notifications

[Main Page](#) > [OBD Trackers](#) > [FMM001](#) > **FMM001 Product Change Notifications**

**Product change notifications** (**PCN**) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMM001 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

☐

## Contents

## 2022.04.06: Base firmware update

We would like to inform you about the base firmware update for FMM001 starting from April 6th, 2022. The new production firmware version will be **03.27.13.Rev.01**

| Change description | | |
|---|---|---|
| Change type | Hardware and Firmware change | |
| Detailed description | OBD data processor of an alternative manufacturer is introduced in the production process. Key improvements from last production firmware are listed in errata: [https://wiki.teltonika-gps.com/view/FMM001_firmware_errata](https://wiki.teltonika-gps.com/view/FMM001_firmware_errata) | |
| | Old version:<br>FMM001 03.27.12.Rev.00 | New version:<br>FMM001 03.27.13.Rev.01 |
| Change reasons | Manufacture process optimization | |
| Product release date | 2022 April | |
| **Affected products** | | |
| Model | Affected order codes | Order code changes |
| FMM001 | FMM001******* order codes with base Firmware | Update firmware |
| **Affected products** | | |
| Model | Affected order codes | Order code changes |
| FMB010 | FMB010******* order codes with base Firmware | Update firmware |
| **Change impact** | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | |
| | Current CE and E-mark certificates are valid. Also, current purchase codes remain the same. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |

## 2022.02.09: Base firmware update

We would like to inform you about the base firmware update for FMM001 starting from February 9th, 2022. The new production firmware version will be **03.27.12.Rev.00**

| Change description | | |
|---|---|---|
| Change type | Hardware and Firmware change | |
| Detailed description | OBD data processor of an alternative manufacturer is introduced in the production process. Key improvements from last production firmware are listed in errata: [https://wiki.teltonika-gps.com/view/FMM001_firmware_errata](https://wiki.teltonika-gps.com/view/FMM001_firmware_errata) | |
| | Old version:<br>FMM001 03.27.07.Rev.00 | New version:<br>FMM001 03.27.12.Rev.00 |

| | | |
|---|---|---|
| Change reasons | Response to the global situation in component market and streamlining our product portfolio. | |
| Product release date | 2022 February | |
| **Affected products** | | |
| Model | Affected order codes | Order code changes |
| FMM001 | FMM001******* order codes with base Firmware | OBD processor analog |
| **Change impact** | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.<br><br>Current CE and E-mark certificates are valid. Also, current purchase codes remain the same. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |

# 2021.08.19: Base firmware update

We would like to inform you about the base firmware update for FMM001 starting from August 19th, 2021. New production firmware version will be **03.27.07.Rev.00**

| | | |
|---|---|---|
| **Change description** | | |
| Change type | Firmware update | |
| Detailed description | Key improvements from last production firmware are listed in errata: [https://wiki.teltonika-gps.com/view/FMB_firmware_errata](https://wiki.teltonika-gps.com/view/FMB_firmware_errata) | |
| | Old version:<br>FMM001 03.25.15.Rev.88 | New version:<br>FMM001 03.27.07.Rev.00 |
| Change reasons | FMM001 base firmware version update | |
| Product release date | 2021 August | |
| **Affected products** | | |
| Model | Affected order codes | Order code changes |
| FMM001 | FMM001******* order codes with base Firmware | Update firmware |
| **Change impact** | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |