FMU130 Product Change Notifications

[Main Page](#) > [EOL Products](#) > [FMU130](#) > **FMU130 Product Change Notifications**

Product change notifications (**PCN**) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMU130 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

☐

Contents

2021.08.19: Base firmware update

We would like to inform you about the base firmware update for FMU130 starting from August 19th, 2021. New production firmware version will be **03.27.07.Rev.00**

Change description		
Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMU130_firmware_errata	
	Old version: FMU130 03.27.04.Rev.01	New version: FMU130 03.27.07.Rev.00
Change reasons	FMU130 base firmware version update	
Product release date	2021 August	
Affected products		
Model	Affected order codes	Order code changes
FMU130	FMU130******* order codes with base Firmware	Update firmware
Change impact		
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2021.03.16: Base firmware update

We would like to inform you about the base firmware update for FMU130 starting from March 16th, 2021. The new production firmware version will be **03.27.04.Rev.01**.

Change description		
Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMU130_firmware_errata	
	Old version: FMU130 03.27.03.Rev.02	New version: FMU130 03.27.04.Rev.01
Change reasons	FMU130 base firmware version update	
Product release date	2021 March 16th.	
Affected products		
Model	Affected order codes	Order code changes

FMU130	FMU130******* order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically.
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2021.01.28: Base firmware update

We would like to inform you about the base firmware update for FMU130 starting from January 28th, 2021. The new production firmware version will be **03.27.03.Rev.02**.

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMU130_firmware_errata	
	Old version: FMU130 03.27.02.Rev.00	New version: FMU130 03.27.03.Rev.02
Change reasons	FMU130 base firmware version update	
Product release date	2021 January 28th.	

Affected products

Model	Affected order codes	Order code changes
FMU130	FMU130******* order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2020.09.16: Base firmware update

We would like to inform you about the base firmware update for FMU130 starting from September 16th, 2020. The new production firmware version will be **03.27.02.Rev.00**.

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMU130_firmware_errata	
	Old version: FMU130 03.25.10.Rev.175	New version: FMU130 03.27.02.Rev.00
Change reasons	FMU130 base firmware version update	
Product release date	2020 September 16th.	

Affected products

Model	Affected order codes	Order code changes
FMU130	FMBU130******* order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2019.11.28: Top Device Marking Changes

We would like to inform you, that tampography of the FMU130 device was updated to engraving in the factory.

Change description

Change type	External/visual	
Detailed description	Device marking changed from tampography to laser printing. Information provided on module will remain the same	
	Old Version: 	New Version:
Change reasons	To improve manufacturing speed, efficiency and reliability To increase quality, precision and durability of marking.	
Product release date	Planned date: 2019 December	

Affected products

Model	all codes with standard marking	Order code changes
FMU125	FMU130*******	No changes

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	No implementation plan needed

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above