Template:MSP500 firmware errata

☐

Contents

Introduction

We are always improving our devices performance, stability and reliability. That's why Teltonika is one of the leading GNSS trackers manufacturers in the world.
This document describes **MSP500** device firmware improvements, changes, new features implementations as well as current firmware release version.

FIRMWARE VERSION	SUPPORTED HARDWARE
03.25.XX	MSP500

Firmware versioning

- Structure

FMB(T).VER.[XX].[YY].[ZZ].Rev.[##] _[ID###]

- Syntax description
    - XX – major FW version.
    - YY – branch number, shows major changes in firmware, i.e. new module support added or new major feature added.
    - ZZ – major changes like bigger fixes, improvements and new features addition.
    - ## – minor changes like small fixes and improvements.
    - ID[###] – Spec ID KEY – Client specific FW changes.

Firmware versions

FIRMWARE VERSION	RELEASE DATE	CHANGES
FMB.Ver.03.25.05.Rev.127	2019.11.22	• Stability improvements • General Fixes • Initial release