https://wiki.teltonika-gps.com/view/DSM\_Firmware\_errata

# **DSM Firmware errata**

 $\frac{\text{Main Page}}{\square} > \frac{\text{Video Solutions}}{\square} > \frac{\text{DSM}}{\square} > \text{DSM Firmware errata}$ 

## Contents

- <u>1 DSM Firmware Version</u>
- <u>2 Firmware for FMC650</u>

### **DSM Firmware Version**

We are always improving our device's performance, stability, and reliability. This document describes **DSM platform** devices' firmware improvements, changes, new features implementations as well as current firmware release version.

#### Firmware download for FMx6 device series

Link: Firmware

Password: cU22XsBu

## **Firmware for FMC650**

FIRMWARE VERSION	RELEASE DATE	CHANGES
03.00.14.Rev.116	2024-04-05	• NEW: ADAS support.
03.00.14.Rev.114	2024-03-01	<ul><li>Added DSM support for FMC650.</li><li>NEW: Two camera support.</li></ul>
FMX640 FIRMWARE VERSION	RELEASE DATE	CHANGES
<b>01.02.17.Rev.158</b> (Latest firmware release version for FMX640)	2023-10-09	• Event timeout settings support via CFG
<b>01.02.17.Rev.157</b> (Latest firmware release version for FMX640)	2023-06-05	<ul> <li>DSM protocol update to 1.4 version</li> <li>Prevent modifying files after DSM Ready state is set</li> <li>IF file corrupted, DSM will return to ready state</li> </ul>

<b>01.02.17.Rev.156</b> (Latest firmware release version for FMX640)	2023-05-02	<ul> <li>Increased event sound max value for voice setting</li> <li>Snapshot retransmit capability is added (periodic and by request)</li> <li>Prevent premature dsm state change from uploading to ready</li> <li>Reject unsolicited snapshot if upload buffer is full</li> <li>Multiple accsess to SD prevention</li> <li>Yawning sensitivity fixed value</li> <li>Increased UART buffer sizes</li> </ul>
<b>01.02.17.Rev.155</b> (Latest firmware release version for FMX640)	2023-03-16	<ul><li>Initial firmware release</li><li>Added DSM support</li></ul>

DSM FIRMWARE VERSION	RELEASE DATE	CHANGES
2.3.0	2024-05-20	<ul> <li>Added support for Snapshot OSD</li> <li>Updated the algorithm to version 1.1.0045</li> <li>Fixed an issue where certain characters were not capitalized in French settings</li> <li>Fixed an issue where the device would not reboot after inserting an SD card.</li> </ul>
2.2.0	2023-12-04	<ul><li>Stable work</li><li>Seat belt detection update</li></ul>
2.2.0.TR1	2023-08-31	<ul><li>Stable work</li><li>New calibration page 30.0.0.1:18087</li></ul>
2.0.1	2023-06-26	<ul> <li>Fixed issues related to SD retransmission function</li> <li>Fixed Timestamp values in UTC</li> <li>Fixed GPS coordinates changed to signed int</li> <li>Fixed Snapshot retransmission packet size</li> </ul>
2.0.0	2023-03-07	• stable DSM work