

December 23 Change Log

FIRMWARE ERRATA / CONFIGURATOR

1. A new firmware version for the device **DSM 2.2.0** was added:
 - https://wiki.teltonika-gps.com/view/DSM_Firmware_errata
2. Base firmware version **03.29.00.Rev.13** is now recommended for hardwares:
 - **FMC130 with MeiG SLM320, FMC230 with MeiG SLM320, FMC920 with EG915U-EU, FMC920 with EG915U-LA.**
 - Firmware files, configurator and release note download links are now updated in Wiki: https://wiki.teltonika-gps.com/view/Firmware_versions
3. Base firmware version **03.29.00.Rev.14** is now recommended for hardwares:
 - **FMB120, FMB130, FMB140, FMB125, FMM130 with BG95-M3, FMM230, FMB920, FMT100, FMB910, FMB204, FMC125 with MeiG SLM320, FMC225, FMC13A.**
 - Firmware files, configurator and release note download links are now updated in Wiki: https://wiki.teltonika-gps.com/view/Firmware_versions

CREATED PAGES

1. The instructions for **the FMX640 BLE** firmware update task have been renewed
 - https://wiki.teltonika-gps.com/view/FMM640_BLE_module_update
 - https://wiki.teltonika-gps.com/view/FMC640_BLE_module_update
2. Updated the WIKI page and added a disclaimer regarding **FOTA WEB** support for **TLS certificate** upload.
 - https://wiki.teltonika-gps.com/view/FOTA_WEB_Devices#Task_Types