

# ADAS Firmware errata

[Main Page](#) > [Video Solutions](#) > [Teltonika ADAS](#) > **ADAS Firmware errata**



## Contents

- [1 Firmware for FMC650](#)
- [2 FMX125/FMX225 FIRMWARE VERSION](#)
- [3 ADAS Firmware Version](#)

We are always improving our device's performance, stability, and reliability. This document describes **ADAS platform** devices' firmware improvements, changes, new features implementations as well as current firmware release version.

### Firmware download for FMX:125/225/640/FMC650

Link: [Firmware](#)

Password: LXKOpGlu

## Firmware for FMC650

<b>FIRMWARE VERSION</b>	<b>RELEASE DATE</b>	<b>CHANGES</b>
<b>03.00.16.Rev.104</b>	2024-11-12	<ul style="list-style-type: none"><li>• Support DSM FW 2.4.0 added.</li><li>• Port tacho border crossing IO.</li></ul>
<b>03.00.16.Rev.101</b>	2024-08-06	<ul style="list-style-type: none"><li>• Geofence functionality pictures receiving fix.</li><li>• Green Driving pictures receiving fix.</li><li>• File transfer modem rebooting state fix.</li><li>• Additional verbal information by request/download/upload pictures.</li></ul>
<b>03.00.16.Rev.100</b>	2024-06-12	<ul style="list-style-type: none"><li>• Port Tacho Border Crossing IO.</li><li>• VDO Counter functionality fix.</li><li>• Full Base Support</li></ul>
<b>03.00.14.Rev.116</b>	2024-04-05	<ul style="list-style-type: none"><li>• <b>NEW:</b> ADAS support.</li></ul>

<b>FMX640 FIRMWARE VERSION</b>	<b>RELEASE DATE</b>	<b>CHANGES</b>
<b>01.02.22.Rev.105</b>	2024-04-15	<ul style="list-style-type: none"><li>• Video download improvements</li><li>• Overlay functions improvements</li><li>• Save to SD settings improvements</li><li>• Improve stable work</li></ul>

<b>01.02.22.Rev.102</b>	2023-03-13	<ul style="list-style-type: none"> <li>• CRC calculation from a proper location not from a hardcoded Flash area</li> <li>• Wrong server used with consecutive uploads</li> <li>• Metadata request type changed for periodic snapshot</li> <li>• Periodic image request by date instead of the current snapshot</li> <li>• Fixed auto baud rate functionality unpausing scheduled jobs</li> <li>• Prevent SD card access when downloading from MDAS</li> <li>• Remount SD card when a disk error occurs</li> <li>• Camera resolution configuration</li> <li>• Default server\port in SMS requests</li> <li>• Setting the overlay when it is disabled</li> <li>• MDAS speed source selection</li> <li>• Record sending with file details</li> </ul>
<b>01.02.22.Rev.101</b>	2022-10-21	<ul style="list-style-type: none"> <li>• Crash in DDD files sending</li> <li>• ADAS base update</li> </ul>
<b>01.02.10.Rev.103_ID1039</b>	2022-07-05	<ul style="list-style-type: none"> <li>• Firmware for FMC640 and FMB640</li> <li>• Base update to latest version</li> <li>• Video/photo by request</li> <li>• Periodic photo sending</li> </ul>

## FMX125/FMX225 FIRMWARE VERSION

### FMX125/FMX225 FIRMWARE VERSION

FIRMWARE VERSION	RELEASE DATE	CHANGES
<b>03.29.00.Rev.1090</b>	2024-08-05	<ul style="list-style-type: none"> <li>• Base update</li> <li>• FIX: IO elements parameter ranges according to documentation</li> </ul>
<b>03.27.13.Rev.370</b>	2022-07-26	<ul style="list-style-type: none"> <li>• Base update to latest version Meig Support</li> <li>• Accessory monitoring port to MDAS9</li> <li>• Firmware for FMX125 and FMX225 also for Meig</li> </ul>
<b>03.27.07.Rev.370</b>	2021-10-18	<ul style="list-style-type: none"> <li>• Base update to latest version</li> <li>• Minor configurator fixes</li> <li>• Improved system stability and fixed general bugs</li> <li>• Firmware for FMX125 and FMX225</li> </ul>
<b>03.27.01.Rev.242</b>	2021-01-06	<ul style="list-style-type: none"> <li>• FPW and FVSA bug fixes</li> <li>• Minor improvements</li> </ul>
<b>03.27.01.Rev.240</b>	2020-10-26	<ul style="list-style-type: none"> <li>• Added ADAS camera support</li> <li>• Initial release</li> </ul>

## ADAS Firmware Version

ADAS FIRMWARE VERSION	RELEASE DATE	CHANGES
<b>0.6.33</b>	2024-07-17	<ul style="list-style-type: none"> <li>• [FIX] File transfer resume multiple presents for the same request</li> <li>• [FIX] Packet index number in transfer resume CMD according to argument 2023.12.05</li> <li>• [FIX] Packet index number in transfer resume</li> <li>• [FIX] Video and snapshot transfer resume</li> </ul>

<b>0.6.15</b>	2023-06-15	<ul style="list-style-type: none"> <li>• Fix Video and snapshot transfer resume</li> <li>• Fix OSD ON/OFF functionality</li> </ul>
<b>0.6.10</b>	2022-10-14	<ul style="list-style-type: none"> <li>• Fixed malfunction of Lock Volume function</li> <li>• Fix on vehicle file not applied properly via FMS command</li> </ul>
<b>0.6.03</b>	2022-07-22	<ul style="list-style-type: none"> <li>• Fixed miss usage of HEX values instead of DEC</li> </ul>
<b>0.6.01</b>	2022-07-12	<ul style="list-style-type: none"> <li>• Fix where protocol version changed to 13 or 0x13</li> <li>• Fix for wrong GPS coordinates offset</li> </ul>
<b>0.5.99</b>	2022-07-10	<ul style="list-style-type: none"> <li>• Added video compression quality change via 0x7D</li> <li>• Added file transfer resume via 0x9F</li> <li>• Fixed abnormal packet communication during fw update</li> <li>• Fixed speed value display on overlay</li> <li>• Fixed option to use only FMx GPS data via 0x9C</li> </ul>
<b>0.5.95</b>	2022-06-01	<ul style="list-style-type: none"> <li>• Support 128 Gb SD card</li> <li>• Video/photo by request</li> <li>• Periodic photo sending</li> </ul>
<b>0.5.78</b>	2021-07-21	<ul style="list-style-type: none"> <li>• Configurable video size supported</li> </ul>
<b>0.5.68</b>	2021-04-19	<ul style="list-style-type: none"> <li>• Russian language added</li> </ul>
<b>0.5.12</b>	2019-07-19	<ul style="list-style-type: none"> <li>• LDW activation speed (mph) changed</li> </ul>