

# December 23 Change Log

## FIRMWARE ERRATA / CONFIGURATOR

1. A new firmware version for the device **DSM 2.2.0** was added:
  - [https://wiki.teltonika-gps.com/view/DSM\\_Firmware\\_errata](https://wiki.teltonika-gps.com/view/DSM_Firmware_errata)
2. Base firmware version **03.29.00.Rev.13** is now recommended for hardwares:
  - **FMC130 with MeiG SLM320, FMC230 with MeiG SLM320, FMC920 with EG915U-EU, FMC920 with EG915U-LA.**
  - Firmware files, configurator and release note download links are now updated in Wiki: [https://wiki.teltonika-gps.com/view/Firmware\\_versions](https://wiki.teltonika-gps.com/view/Firmware_versions)
3. Base firmware version **03.29.00.Rev.14** is now recommended for hardwares:
  - **FMB120, FMB130, FMB140, FMB125, FMM130 with BG95-M3, FMM230, FMB920, FMT100, FMB910, FMB204, FMC125 with MeiG SLM320, FMC225, FMC13A.**
  - Firmware files, configurator and release note download links are now updated in Wiki: [https://wiki.teltonika-gps.com/view/Firmware\\_versions](https://wiki.teltonika-gps.com/view/Firmware_versions)

## CREATED PAGES

1. The instructions for **the FMX640 BLE** firmware update task have been renewed
  - [https://wiki.teltonika-gps.com/view/FMM640\\_BLE\\_module\\_update](https://wiki.teltonika-gps.com/view/FMM640_BLE_module_update)
  - [https://wiki.teltonika-gps.com/view/FMC640\\_BLE\\_module\\_update](https://wiki.teltonika-gps.com/view/FMC640_BLE_module_update)
2. Updated the WIKI page and added a disclaimer regarding **FOTA WEB** support for **TLS certificate** upload.
  - [https://wiki.teltonika-gps.com/view/FOTA\\_WEB\\_Devices#Task\\_Types](https://wiki.teltonika-gps.com/view/FOTA_WEB_Devices#Task_Types)