

# July 23 Change Log

## FIRMWARE ERRATA / CONFIGURATOR

1. New firmware version for the device **TAT140** 5.00.16.Rev.558 was released:
  - [https://wiki.teltonika-gps.com/view/TAT140\\_Stable\\_firmware](https://wiki.teltonika-gps.com/view/TAT140_Stable_firmware)
2. New firmware version for the device **DashCam/DualCam** 03.27.13.Rev.663 was released:
  - [https://wiki.teltonika-gps.com/view/DualCam\\_Firmware\\_errata](https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata)
  - [https://wiki.teltonika-gps.com/view/DashCam\\_Firmware\\_errata](https://wiki.teltonika-gps.com/view/DashCam_Firmware_errata)

## CREATED PAGES

1. New wiki page has been created to help with **OBD Log collecting, OBD OEM Basic configuration** and other specific **information** that might help.
  - [https://wiki.teltonika-gps.com/view/OBD\\_Device\\_Debugging](https://wiki.teltonika-gps.com/view/OBD_Device_Debugging)
2. **FOTA** Web wiki page has been fully updated with up to date information.
  - [https://wiki.teltonika-gps.com/view/FOTA\\_WEB](https://wiki.teltonika-gps.com/view/FOTA_WEB)
3. **DashCam** and **DualCam** data sending parameters ID wiki pages were updates to match latest FW features.
  - [https://wiki.teltonika-gps.com/view/DualCam\\_Data\\_Sending\\_Parameters\\_ID#Camera\\_Feature\\_Settings\\_Parameters\\_ID](https://wiki.teltonika-gps.com/view/DualCam_Data_Sending_Parameters_ID#Camera_Feature_Settings_Parameters_ID)
  - [https://wiki.teltonika-gps.com/view/DashCam\\_Data\\_Sending\\_Parameters\\_ID#Camera\\_Feature\\_Settings\\_Parameters\\_ID](https://wiki.teltonika-gps.com/view/DashCam_Data_Sending_Parameters_ID#Camera_Feature_Settings_Parameters_ID)