

# MSP500 firmware errata

[Main Page](#) > [EOL Products](#) > [MSP500](#) > **MSP500 firmware errata**



## Contents

- [1 Introduction](#)
- [2 Firmware versioning](#)
- [3 Firmware versions](#)

## Introduction

We are always improving our devices performance, stability and reliability. That's why Teltonika is one of the leading GNSS trackers manufacturers in the world.

This document describes **MSP500** device firmware improvements, changes, new features implementations as well as current firmware release version.

FIRMWARE VERSION	SUPPORTED HARDWARE
03.25.XX	MSP500

## Firmware versioning

- Structure

FMB(T).VER.[XX].[YY].[ZZ].Rev.[##]\_[ID###]

- Syntax description
  - XX – major FW version.
  - YY – branch number, shows major changes in firmware, i.e. new module support added or new major feature added.
  - ZZ – major changes like bigger fixes, improvements and new features addition.
  - ## – minor changes like small fixes and improvements.
  - ID[###] – Spec ID KEY – Client specific FW changes.

## Firmware versions

FIRMWARE VERSION	RELEASE DATE	CHANGES
FMB.Ver.03.25.05.Rev.127	2019.11.22	<ul style="list-style-type: none"><li>• Stability improvements</li><li>• General Fixes</li><li>• Initial release</li></ul>