

March 22 Change Log

[Teltonika wiki change log](#) > **March 22 Change Log**

GENERAL INFORMATION

1. Added additional information on RS232 / RS485 electrical voltage requirements and absolute maximum voltage requirements:

https://wiki.teltonika-gps.com/view/FMB125_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FMC125_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FMM125_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FMU125_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FMB640_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FMC640_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FMM640_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FMB641_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FM6300_General_description#Electrical_characteristics

https://wiki.teltonika-gps.com/view/FMC650_General_description#Electrical_characteristics

2. Updated DUAL CAM web page, added firmware version for DUAL CAM and FMX125:

https://wiki.teltonika-gps.com/view/Teltonika_DualCam#Firmware_Version

3. Updated DUAL CAM web page, added DUAL CAM update procedure

https://wiki.teltonika-gps.com/view/Teltonika_DualCam#DualCam_update_procedure

4. *Beacon list* has been updated, *Beacon Flag* and *Battery voltage* configuration and parsing examples added:

https://wiki.teltonika-gps.com/view/FMB120_Beacon_List#EYE_Beacon_Capturing_Configuration

CERTIFICATES

5. Uploaded *Anatel* certificates for *EYE Beacon* and *EYE Sensor* (BTSID and BTSMP):

https://wiki.teltonika-gps.com/view/BTSID_ANATEL

https://wiki.teltonika-gps.com/view/BTSMP_ANATEL

6. *UKCA certificate* has been added for *FMB641* device:

https://wiki.teltonika-gps.com/view/FMB641_CE/RED

Product Change Notifications (PCN)

7. FMC130 Wiki, Firmware errata (SLM320-L, SLM320-E2) and PCN (Product change notifications) has been updated:

https://wiki.teltonika-gps.com/view/FMC130_firmware_errata

https://wiki.teltonika-gps.com/view/FMC130_Product_Change_Notifications

CREATED PAGES

8. New wiki page has been created *IP67 Case*:

https://wiki.teltonika-gps.com/view/IP67_Case

9. New device FMB965 added to Wiki:

<https://wiki.teltonika-gps.com/view/FMB965>