

May 23 Change Log

[Teltonika wiki change log](#) > **May 23 Change Log**

General information

1. Added reworked movement logic functionality description for TAT140:

https://wiki.teltonika-gps.com/view/TAT140_Tracking_settings#Tracking_Scenarios_-_FW_version_after_X.4.7

2. Added TAT140 FW that can now be downloaded:

https://wiki.teltonika-gps.com/view/TAT140_Stable_firmware

3. *Barcode Scanner* was added to the *Main Wiki Page Accessory Lists*:

https://wiki.teltonika-gps.com/view/Main_Page

4. A brief explanation/clarification was added to the *Avg Const* section:

https://wiki.teltonika-gps.com/view/FMB125_I/O_settings#Avg_Const

AVL/parameter ID updates

1. There is some change for TAT100 *Scheduler*:

https://wiki.teltonika-gps.com/view/TAT100_Parameter_list#Scheduler

Default value - 1

Value range - Min 1, Max 6

Value - 1 2 3 4 5 6

Certificates

1. A new wiki page has been created for the **TAT140 CITC** Approval:

https://wiki.teltonika-gps.com/view/TAT140_CITC

Firmware errata / Configurator

1. New firmware version for the device FMX640 (01.02.17.Rev.156) released:

https://wiki.teltonika-gps.com/view/DSM_Firmware_errata

FAQ

1. FMx6 tacho logging instructions were added to the *FAQ* page:

https://wiki.teltonika-gps.com/view/How_to_capture_remote_Tacho_log_from_FM_device%3F

2. **Advanced Beacon Capturing Configuration** has been added to the **FAQ wiki page**, under **Bluetooth® Solutions**:

https://wiki.teltonika-gps.com/view/Frequently_Asked_Questions_-_FAQ

3. This page has been added to the **FAQ** page under the **OBD section**:

https://wiki.teltonika-gps.com/view/Frequently_Asked_Questions_-_FAQ

4. You can find this page in our FAQ wiki under the new category **Serial Interface Solutions**:

https://wiki.teltonika-gps.com/view/Frequently_Asked_Questions_-_FAQ

Created pages

1. A new page has been created *CloudView*, our software platform for testing video and photo receiving from our devices - DualCam, ADAS, and DSM:

https://wiki.teltonika-gps.com/view/CloudView_Platform

2. A new wiki page has been created for **Inateck BCST-70 Barcode Scanner**:

https://wiki.teltonika-gps.com/view/Inateck_BCST-70_Barcode_Scanner

3. A new wiki page has been created for **MSP500+ETC Speed Limiting Solution**:

https://wiki.teltonika-gps.com/view/Speed_Limiting_Solution_MSP500%2BETC

4. A new wiki page has been created for **BLE broadcast service ID configuration**:

https://wiki.teltonika-gps.com/view/BLE_broadcast_service_ID_configuration

5. *BLE broadcast service ID configuration* page added to *FAQ Bluetooth® solutions* section:

https://wiki.teltonika-gps.com/view/Frequently_Asked_Questions_-_FAQ

6. A new WIKI page has been created for **OEM Parameters** in OBD devices:

https://wiki.teltonika-gps.com/view/OEM_Parameters

7. A new wiki page has been created for **Modbus slave integration with FMX125/FMX640**:

https://wiki.teltonika-gps.com/view/Modbus_slave_integration_with_FMX125/FMX640