

# September 22 Change Log

[Teltonika wiki change log](#) > **September 22 Change Log**

## General Information

1. FMB, FMC and FMM640 configurator version and configurator itself have been updated:

[https://wiki.teltonika-gps.com/view/Teltonika\\_Configurator\\_versions](https://wiki.teltonika-gps.com/view/Teltonika_Configurator_versions)

2. Updated information for FM6 *iButton* read notification:

[https://wiki.teltonika-gps.com/view/FMB641\\_Features\\_settings#iButton\\_Read\\_Notification](https://wiki.teltonika-gps.com/view/FMB641_Features_settings#iButton_Read_Notification)

[https://wiki.teltonika-gps.com/view/FMB640\\_Features\\_settings#iButton\\_Read\\_Notification](https://wiki.teltonika-gps.com/view/FMB640_Features_settings#iButton_Read_Notification)

[https://wiki.teltonika-gps.com/view/FMC640\\_Features\\_settings#iButton\\_Read\\_Notification](https://wiki.teltonika-gps.com/view/FMC640_Features_settings#iButton_Read_Notification)

[https://wiki.teltonika-gps.com/view/FMM640\\_Features\\_settings#iButton\\_Read\\_Notification](https://wiki.teltonika-gps.com/view/FMM640_Features_settings#iButton_Read_Notification)

3. Updated frequency bands under FAQ section:

[https://wiki.teltonika-gps.com/wikibase/index.php?title=Frequency\\_Bands&oldid=76136](https://wiki.teltonika-gps.com/wikibase/index.php?title=Frequency_Bands&oldid=76136)

4. The structure of the ADAS wiki page was changed:

[https://wiki.teltonika-gps.com/view/Teltonika\\_ADAS](https://wiki.teltonika-gps.com/view/Teltonika_ADAS)

## AVL/parameter ID updates

5. FMX640 project devices now available to use Eco driving in Wialon application and AVL ID 258 is now could be used:

[https://wiki.teltonika-gps.com/view/How\\_to\\_set\\_up\\_Eco\\_Driving\\_in\\_Wialon\\_app](https://wiki.teltonika-gps.com/view/How_to_set_up_Eco_Driving_in_Wialon_app)

## Firmware errata / Configurator

6. Added 03.27.13.Rev.03 FW to FMM130 firmware errata:

[https://wiki.teltonika-gps.com/view/FMM130\\_firmware\\_errata](https://wiki.teltonika-gps.com/view/FMM130_firmware_errata)

## Product Change Notifications (PCN)

7. FMB640, FMC640 and FMM640 firmware errata and PCN has been updated:

[https://wiki.teltonika-gps.com/view/FMB640\\_firmware\\_errata](https://wiki.teltonika-gps.com/view/FMB640_firmware_errata)

[https://wiki.teltonika-gps.com/view/FMC640\\_firmware\\_errata](https://wiki.teltonika-gps.com/view/FMC640_firmware_errata)

[https://wiki.teltonika-gps.com/view/FMM640\\_firmware\\_errata](https://wiki.teltonika-gps.com/view/FMM640_firmware_errata)

[https://wiki.teltonika-gps.com/view/FMM640\\_Product\\_Change\\_Notifications](https://wiki.teltonika-gps.com/view/FMM640_Product_Change_Notifications)

[https://wiki.teltonika-gps.com/view/FMC640\\_Product\\_Change\\_Notifications](https://wiki.teltonika-gps.com/view/FMC640_Product_Change_Notifications)

[https://wiki.teltonika-gps.com/view/FMB640\\_Product\\_Change\\_Notifications](https://wiki.teltonika-gps.com/view/FMB640_Product_Change_Notifications)