DualCam Product Change Notifications

<u>Main Page</u> > <u>Video Solutions</u> > <u>Teltonika DualCam</u> > **DualCam Product Change Notifications**

Product change notifications (PCN) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. **This page stores information regarding changes to the DualCam video/photo recording device and FMX125/FMX225 tracking device since they are closely developed to work with each other.** Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

Contents

- <u>1 2023.01.20: Dualcam HW changes</u>
- 2 2022.11.29: FMX125 Base firmware update for MEIG support
- <u>3 2022.05.20: DualCam watch dog implementation update</u>
- 4 2022.03.17: FMX125 Base firmware update
- <u>5 2022.01.06: DualCam base update</u>
- <u>6 2021.09.17: FMX125 Minor update</u>
- <u>7 2021.08.30: FMX125 Base firmware update</u>
- <u>8 2021.07.15: DualCam base update</u>
- 9 2021.06.18: FMX125 Base firmware update
- 10 2021.06.02: DualCam base update
- <u>11 2021.02.19: FMX125 Initial firmware release</u>
- <u>12 2021.02.19</u>: <u>DualCam firmware initial release</u>

2023.01.20: Dualcam HW changes

We would like to inform you about the HW change for Dualcam hardware. The old DualCam voltage converter (white box) has been integrated into the camera hardware.

Change description

Change type

DualCam Hardware Change

Old version: Dualcam with the voltage converter (in the white box)



New version: New DualCam without a voltage converter (white box) it has been integrated into the camera hardware.



Detailed description

Change reasons

Product release date
Affected products
Model

The change was made according of client feedback that sometimes the voltage converter (white box) is hard to hide in the car during installation, so we integrated the voltage converter into DualCam hardware. 2023-01-20

Affected order codes

Order code changes

DUALCAM***** all order codes

DualCam Hardware Change

During the transition period, clients might receive DualCam with the previous hardware version that has a voltage converter (white box).

Suggested implementation plan DualCam is still the same so not need any additional movement to make.

2022.11.29: FMX125 Base firmware update for MEIG support

We would like to inform you about the base firmware update for FMX125 starting from 17th of June 2022. New tracking device production firmware version will be 03.27.13.Rev.367.

| Change description | | | |
|-------------------------------|--|-------------------------|--|
| Change type | Firmware update | | |
| | Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata | | |
| Detailed description | Old version: | New version: | |
| | FMX125 03.27.07.Rev.365 | FMX125 03.27.13.Rev.367 | |
| Change reasons | FMX125 base firmware version update | | |
| Product release date | 2022 November | | |
| Affected products | | | |
| Model | Affected order codes | Order code changes | |
| FMX125 | FMX125************************************ | Update firmware | |
| Change impact | | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | | |

2022.05.20: DualCam watch dog implementation update

We would like to inform you about the base firmware update for DualCam starting from 20th of May 2022. New production firmware version will be V2.2.3.

| Change description | | |
|-------------------------------|--|--------------------|
| Change type | Firmware update | |
| | Key improvements from last production firmware are listed in errata: <u>https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata</u> | |
| Detailed description | Old version: | New version: |
| | DualCam V2.2.2 | DualCam V2.2.3 |
| Change reasons | DualCam base firmware version update | |
| Product release date | 2022 May | |
| Affected products | | |
| Model | Affected order codes | Order code changes |
| DualCam | DUALCAM***** order codes with base Firmware | Update firmware |
| Change impact | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |

2022.03.17: FMX125 Base firmware update

We would like to inform you about the base firmware update for FMX125 starting from 17th of June 2022. New tracking device production firmware version will be 03.27.07.Rev.365.

Change description Change type

Detailed description

Change reasons Product release date Affected products Model FMX125 Change impact Firmware update
Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata
Old version:
FMX125 03.27.07.Rev.361
FMX125 03.27.07.Rev.365
FMX125 base firmware version update
2022 June

 Order code changes Update firmware Risk assessment

Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. Suggested implementation plan If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2022.01.06: DualCam base update

We would like to inform you about the base firmware update for DualCam starting from 6th of January 2022. New production firmware version will be V2.2.2.

| Change description | | |
|-------------------------------|--|--------------------------------|
| Change type | Firmware update | |
| | Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata | |
| Detailed description | Old version: DualCam V1.9.3 | New version: DualCam V2.2.2 |
| Change reasons | DualCam base firmware version update | |
| Product release date | 2022 January | |
| Affected products | | |
| Model | Affected order codes | Order code changes |
| DualCam | DUALCAM****** order codes with base Firmware | Update firmware |
| Change impact | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |

2021.09.17: FMX125 Minor update

We would like to inform you about the base firmware update for FMX125 starting from 17th of September 2021. New tracking device production firmware version will be 03.27.07.Rev.361.

| Change description | | | |
|-------------------------------|--|---|--|
| Change type | Firmware update | | |
| | Key improvements from last production firmware are listed in err | Key improvements from last production firmware are listed in errata: <u>https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata</u> | |
| Detailed description | Old version: | New version: | |
| | FMX125 03.27.07.Rev.360 | FMX125 03.27.07.Rev.361 | |
| Change reasons | FMX125 base firmware version update | | |
| Product release date | 2021 September | | |
| Affected products | | | |
| Model | Affected order codes | Order code changes | |
| FMX125 | FMX125************************************ | Update firmware | |
| Change impact | | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | | |

2021.08.30: FMX125 Base firmware update

We would like to inform you about the base firmware update for FMX125 starting from 30th of August 2021. New tracking device production firmware version will be 03.27.07.Rev.360.

| Change description | | |
|-------------------------------|--|-------------------------|
| Change type | Firmware update | |
| | Key improvements from last production firmware are listed in errata: <u>https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata</u> | |
| Detailed description | Old version: | New version: |
| | FMX125 03.27.03.Rev.104 | FMX125 03.27.07.Rev.360 |
| Change reasons | FMX125 base firmware version update | |
| Product release date | 2021 August | |
| Affected products | | |
| Model | Affected order codes | Order code changes |
| FMX125 | FMX125********* order codes with base Firmware | Update firmware |
| Change impact | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |

2021.07.15: DualCam base update

We would like to inform you about the base firmware update for DualCam starting from 15th of July 2021. New production firmware version will be V1.9.3.

| Change description | | | |
|-------------------------------|--|--------------------------------|--|
| Change type | Firmware update | | |
| | Key improvements from last production firmware are listed in errata: <u>https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata</u> | | |
| Detailed description | Old version: DualCam V1.9.2 | New version: DualCam V1.9.3 | |
| Change reasons | DualCam base firmware version update | | |
| Product release date | 2021 July | | |
| Affected products | | | |
| Model | Affected order codes | Order code changes | |
| DualCam | DUALCAM***** order codes with base Firmware | Update firmware | |
| Change impact | | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | | |

2021.06.18: FMX125 Base firmware update

We would like to inform you about the base firmware update for FMX125 starting from 18th of June 2021. New tracking device production firmware version will be 03.27.03.Rev.104.

| Change description | | |
|-------------------------------|--|-------------------------|
| Change type | Firmware update | |
| | Key improvements from last production firmware are listed in errata: <u>https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata</u> | |
| Detailed description | Old version: | New version: |
| | FMX125 03.27.00.Rev.100 | FMX125 03.27.03.Rev.104 |
| Change reasons | FMX125 base firmware version update | |
| Product release date | 2021 June | |
| Affected products | | |
| Model | Affected order codes | Order code changes |
| FMX125 | FMX125********* order codes with base Firmware | Update firmware |
| Change impact | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |

2021.06.02: DualCam base update

We would like to inform you about the base firmware update for DualCam starting from 2nd of June 2021. New production firmware version will be V1.9.2.

| Change description | | |
|-------------------------------|--|--------------------|
| Change type | Firmware update | |
| | Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata | |
| Detailed description | Old version: | New version: |
| | DualCam V1.9.0 | DualCam V1.9.2 |
| Change reasons | DualCam base firmware version update | |
| Product release date | 2021 June | |
| Affected products | | |
| Model | Affected order codes | Order code changes |
| DualCam | DUALCAM***** order codes with base Firmware | Update firmware |
| Change impact | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |

2021.02.19: FMX125 Initial firmware release

We would like to inform you about the new base firmware release for FMX125 starting from 19th of February 2021. New tracking device production firmware version will be 03.27.00.Rev.100.

| Change description | | | |
|----------------------|--|---|--|
| Change type | Firmware update | | |
| | Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata | | |
| Detailed description | Old version: New vers N/A FMX125 | ion: 03.27.00.Rev.100 | |
| Change reasons | FMX125 base firmware version update | | |
| Product release date | 2021 February | | |
| Affected products | | | |
| Model | Affected order codes | Order code changes | |
| FMX125 | FMX125************************************ | New firmware release | |
| Change impact | | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | | |
| | . If you are using special firmware version and would | ike an upgrade to new features of latest base firmware, please contact your | |

Suggested implementation plan If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2021.02.19: DualCam firmware initial release

We would like to inform you about the base firmware update for DualCam starting from 19th of February 2021. New production firmware version will be V1.9.0.

| Change description | | |
|-------------------------------|--|--------------------------|
| Change type | Firmware update | |
| | Key improvements from last production firmware are listed in errata: <u>https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata</u> | |
| Detailed description | Old version: | New version: |
| | N/A | DualCam V1.9.0 |
| Change reasons | DualCam base firmware version update | |
| Product release date | 2021 February | |
| Affected products | | |
| Model | Affected order codes | Order code changes |
| DualCam | DUALCAM***** order codes with base Firmware | Initial firmware release |
| Change impact | | |
| Risk assessment | Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. | |
| Suggested implementation plan | If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. | |