# FMM150 Product Change Notifications

Main Page > CAN Trackers & Adapters > FMM150 > FMM150 Product Change Notifications

**Product change notifications (PCN)** is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMM150 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

## 2023.12.07: Base firmware update

We would like to inform you about the base firmware update for FMM150 starting from December 7th, 2023. New production firmware version will be 03.28.07.Rev.159

Change description

Change type Firmware update

Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMM150\_firmware\_errata

New version:

Detailed description Old version:

FMM150 03.28.07.Rev.159 FMM150 03.28.07.Rev.152

Change reasons FMM150 base firmware version update

Product release date 2023 December

Affected products

Model Affected order codes Order code changes FMM150 FMM150\*\*\*\*\*\* order codes with base Firmware Update firmware

#### 2022.05.04: Base firmware update

We would like to inform you about the base firmware update for FMM150 starting from May 4th, 2023. New production firmware version will be 03.28.07.Rev.152

Change description

Change type Firmware update

 $Key improvements from \ last production firmware \ are \ listed \ in \ errata: \ \underline{https://wiki.teltonika-gps.com/view/FMM150\_firmware\_errata}$ New version:

Detailed description Old version:

FMM150 03.28.06.Rev.152 FMM150 03.28.07.Rev.152

Change reasons FMM150 base firmware version update

2023 May Product release date

Affected products

Order code changes Model Affected order codes FMM150 FMM150\*\*\*\*\*\* order codes with base Firmware Update firmware

### 2023.02.02: Changes in side frame for the battery placement

We would like to inform you that the side frame for the battery placement is included, helping to determine the exact location of the battery. Also, minor design changes are made to improve both case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices. The updates in the factory are being implemented in February, 2023.

Change description

Change type

The side frame for the battery placement is included, helping to determine the exact location of the battery. Also, minor design changes are made to improve both case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125,

FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices.

Detailed description Old Version:

New Version:

The battery placement is improved with a side frame, helping to determine the exact location of the battery. Minor design changes are made for case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices. Change reasons

Updated the battery placement with the side frame as well as

Product release date February, 2023

Affected products

Model Affected order codes Order code changes

FMB110, FMB120, FMB122,

FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150,

FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, minor design changes for case production and assembly FMM150 all codes FMM150

Change impact

 $During \ the \ transition \ period \ clients \ might \ receive \ devices \ with \ old \ case \ design \ used \ in \ manufacture$ Risk assessment

Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process. Suggested implementation plan

#### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has tactically accepted and can implement the change as indicated above.