

June 23 Change Log

AVL/PARAMETER ID UPDATES

1. Wrong example given for **Codec 13 In Codec** wiki page was removed.
 - https://wiki.teltonika-gps.com/view/Codec#Codec_13
2. Fixed description for Data Sending Parameter "**Ignition On Counter**" updated, ID - 449. Change made for all devices except Autonomous and Professional.
 - https://wiki.teltonika-gps.com/view/FMB122_Teltonika_Data_Sending_Parameters_ID

CERTIFICATES

1. **DSM Certificate** page was edited, and updated with the latest information:
 - https://wiki.teltonika-gps.com/view/DSM_Certifications_%26_Approvals

FIRMWARE ERRATA / CONFIGURATOR

1. New firmware version for the device FMX640 **01.02.17.Rev.157** was released:
 - https://wiki.teltonika-gps.com/view/DSM_Firmware_errata
2. New firmware version for the device FMX125 **03.27.13.Rev.662** was released:
 - https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata#Firmware_for_FMX125
3. New firmware version for **ADAS** was added **0.6.15**
 - https://wiki.teltonika-gps.com/view/ADAS_Firmware_errata#ADAS_Firmware_Version
4. New DSM FW version **2.0.01 TR1** was released:
 - https://wiki.teltonika-gps.com/view/DSM_Firmware_errata

CREATED PAGES

1. **Truphone Top-up usage instructions** Wiki page was created:
 - [https://wiki.teltonika-gps.com/view/How_to_check_Top-up_usage_with_IoT_Platform_\(Truphone\)](https://wiki.teltonika-gps.com/view/How_to_check_Top-up_usage_with_IoT_Platform_(Truphone))
2. Bluetooth® 4.0 page has been updated with additional section – **FMB+FMB Backup Tracker**.
 - https://wiki.teltonika-gps.com/view/FMB130_Bluetooth®_4.0_settings#FMB.2BFMB_Backup_T

[racker](#)

- https://wiki.teltonika-gps.com/view/FMB%2BFMB_Backup_Tracker

3. **EYE FUNCTIONALITIES** Wiki page was created:

- https://wiki.teltonika-gps.com/view/EYE_FUNCTIONALITIES

4. A new wiki page has been created for **TeraCom TSH202** 1-wire humidity and temperature sensor
- TeraCom-TSH202 - with Videos for an easy knowledge.

This page contains the following information:

- Technical parameters - https://wiki.teltonika-gps.com/view/TeraCom-TSH202#Technical_parameters
- Installation - <https://wiki.teltonika-gps.com/view/TeraCom-TSH202#Installation>
- Connections with FMB120 & FMC130 - <https://wiki.teltonika-gps.com/view/TeraCom-TSH202#Connections>
- Configuration - <https://wiki.teltonika-gps.com/view/TeraCom-TSH202#Configuration>
- Demonstration in Flespi platform - https://wiki.teltonika-gps.com/view/TeraCom-TSH202#Demonstration_in_Flespi_platform

5. **DSM Calibration** page was created:

- https://wiki.teltonika-gps.com/view/DSM_Calibration

6. A new wiki page has been created for new product, **Teltonika DashCam**.

- https://wiki.teltonika-gps.com/view/Teltonika_DashCam

7. Connection scheme updated (**connection through RS232 instead of USB**); ALL-CAN300 and CAN-CONTROL adapters support removed (will be added if new order codes for RS232 ALL-CAN300 & CAN-CONTROL are created):

- https://wiki.teltonika-gps.com/view/FMB641_CAN_adapters
- https://wiki.teltonika-gps.com/view/FMC650_CAN_adapters
- https://wiki.teltonika-gps.com/view/FMM650_CAN_adapters