FMB010 Product Change Notifications

Main Page > Fast & Easy Trackers > FMB010 > FMB010 Product Change Notifications

Product change notifications (PCN) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMB010 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

Contents

- 1 2024.03.08: Top Laser Printing Changes
- 2 2023.04.21: Top Laser Printing Changes
- 3 2022.08.01: Base firmware update
- 4 2021.08.13: Base firmware update
- <u>5 2021.01.01</u>: Top Laser Printing Changes
- <u>6 2020.01.22</u>: Base firmware update
- 7 2019.07.22: new no brand Eco friendly boxes

2024.03.08: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB010 device was updated in the factory in March, 2024.

Change description

Change type

External/visual

Top laser printing design changed

Old version:



Change reasons

1. Serial number, IMEI QR codes will now be laser engraved

2. Stiplers containing porial number, IMEI QR codes will not be

2. Stickers containing serial number, IMEI QR codes will no longer be present on the casing.

Product release date March 2024

Affected products

Model Affected order codes Order code changes

FMB010 FMB010******* New casing

Change impact

Risk assessment No risk factors encountered with this change

Suggested Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays

plan in customs clearance process

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2023.04.21: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB010 device was updated in the factory from April 2023.

Change description

Change type External/visual

Top laser printing design was changed, additional IMEI/SN QR sticker on the

Detailed top part of the casing was added

description Old version: New version:

×

Change reasons

In order to improve the effectiveness of QR scanning additional IMEI/SN QR

sticker on the top part of casing was added

Product release

date April 2023

Affected products

Model Affected order codes Order code changes

FMB010 FMB010******* New casing

Change impact

Risk assessment No risk factors encountered with this change

Suggested Due to changes in device appearance we strongly recommend to contact your implementation customs agent with our change log information, to avoid any unexpected delays

plan in customs clearance process

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2022.08.01: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from August 1st, 2022. New production firmware version will be 03.27.13.Rev.03

Change type Firmware update

Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010_firmware_errata

Old version: New version: FMB010 03.27.13.Rev.03

Change reasons FMB010 base firmware version update

2022 August Product release date

Affected products

Detailed description

Model Affected order codes Order code changes FMB010 FMB010****** order codes with base Firmware Update firmware

2021.08.13: Base firmware update

FMB010 03.27.07.Rev.00

We would like to inform you about the base firmware update for FMB010 starting from August 13th, 2021. New production firmware version will be 03.27.07.Rev.00

Change description

Change type Firmware update

Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010_firmware_errata

Detailed description Old version:

FMB010 03.27.07.Rev.00 FMB010 03.25.18.Rev.08

Change reasons FMB010 base firmware version update

Product release date 2021 August

Affected products

Model Affected order codes Order code changes FMB010****** order codes with base Firmware FMB010 Update firmware

Change impact

Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. Risk assessment

During the transition period clients might receive devices with previous Firmware version used in manufacture.

If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Suggested implementation plan Teltonika sales manager.

2021.01.01: Top Laser Printing Changes


We would like to inform you, that laser printing of the FMB010 device was updated in the factory from January 2021.

Change description

Change type External/visual

Top laser printing design changed

Old version:



1. Updated Emark certificate number.

Change reasons

2. Added UKCA label.

3. Updated Teltonika brand to Teltonika Telematics.

Product release date January 2021

Affected products

Model Affected order codes Order code changes

FMB010 FMB010***** New casing

Change impact

Risk assessment No risk factors encountered with this change

Suggested Due to changes in device appearance we strongly recommend to contact your implementation customs agent with our change log information, to avoid any unexpected delays

in customs clearance process plan

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2020.01.22: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from January 22th, 2020. New production firmware version will be **03.25.15.Rev.01**.

Change description

Change type Firmware update

Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010_firmware_errata

Detailed description Old version:

FMB010 03.25.05.Rev.00 FMB010 03.25.15.Rev.01

FMB010 base firmware version update Change reasons

Product release date 2020 January 22th.

Affected products

Model Affected order codes Order code changes FMB010 FMB010****** order codes with base Firmware Update firmware

Change impact

Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically Risk assessment If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Suggested implementation plan Teltonika sales manager.

2019.07.22: new no brand Eco friendly boxes

Effective September 2019, FMB010 trackers with no brand packaging will be shipped with a **new no** brand eco-friendly box.

Change description

Change type

Improved and more environmentally friendly packaging box

Old single packaging version:

Detailed description **Dimensions:** 165 (W) x 145 (D) x 35 (H)

Old group packaging version:

Dimensions: 355 (W) x 175 (D) x 60 (H)

Dimensions: 355 (W) x 175 (D) x 60 (H)

New single packaging version:

New group packaging version:

Dimensions: 175 (W) x 150 (D) x 35 (H)

Change reasons The new box is better for the environment

Devices with new packaging will be released in manufacturing from September with 2 months of transition period. Over this period Product release date

devices with white packaging can be delivered as well as devices with the new eco boxes.

Affected products

Model Affected order codes Order code changes

```
FMB001, FMB010, FMB100, FMB100, FMB120, FMB122, FMB120, FMB204, FMB900, FMB920, FMB964, FMT100, FMB130, MTB100.

FMB001******, FMB010******, FMB100******, FMB100******, FMB202******, FMB202******, FMB900******, FMB900*******, FMB900******, FMB900******, FMB900******, FMB900******, FMB900******, FMB900******, FMB900******, FMB900******, FMB900*******, FMB900********, FMB900*******, FMB900********, FMB900*******, FMB900********, FMB900*******, FMB900*******, FMB900********, FMB900********, FMB900*******, FMB900********, FMB900*********, FMB900********, FMB900********, FMB900********, FMB900********, FMB900*******, FMB900*******, FMB900********, FMB900*********, FMB900********, FMB900********, FMB900********, FMB900********, FMB900********, FMB900*********,
```

Change impact

Risk assessment No risk factors encountered with this change

Suggested implementation plan Due to the new look of boxes we strongly recommend to update your marketing materials. Because of the new color of the packaging box, if necessary, update your branding materials (stickers, logo layouts).

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above