

https://wiki.teltonika-gps.com/view/FMB_lvcanhorn

FMB lvcanhorn

Toggle CAN-CONTROL to activate single horn sound

Possible answers

CAN-CONTROL Not connected!

CAN-CONTROL CMD executing error!

CAN-CONTROL CMD executed successfully