

FMC150 Product Change Notifications

[Main Page](#) > [CAN Trackers & Adapters](#) > [FMC150](#) > **FMC150 Product Change Notifications**

Product change notifications (PCN) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMC150 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).



Contents

- [1 2023.12.07: Base firmware update](#)
- [2 2022.05.04: Base firmware update](#)
- [3 2023.02.02: Changes in side frame for the battery placement](#)

2023.12.07: Base firmware update

We would like to inform you about the base firmware update for FMC150 starting from December 7th, 2023. New production firmware version will be 03.28.07.Rev.159

Change description

Change type	Firmware update	
	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMC150_firmware_errata	
Detailed description	Old version: FMC150 03.28.07.Rev.152	New version: FMC150 03.28.07.Rev.159
Change reasons	FMC150 base firmware version update	
Product release date	2023 December	
Affected products		
Model	Affected order codes	Order code changes
FMC150	FMC150***** order codes with base Firmware	Update firmware

2022.05.04: Base firmware update

We would like to inform you about the base firmware update for FMC150 starting from May 4th, 2023. New production firmware version will be 03.28.07.Rev.152

Change description

Change type	Firmware update	
	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMC150_firmware_errata	
Detailed description	Old version: FMC150 03.28.06.Rev.152	New version: FMC150 03.28.07.Rev.152
Change reasons	FMC150 base firmware version update	
Product release date	2023 May	
Affected products		
Model	Affected order codes	Order code changes
FMC150	FMC150***** order codes with base Firmware	Update firmware

2023.02.02: Changes in side frame for the battery placement

We would like to inform you that the side frame for the battery placement is included, helping to determine the exact location of the battery. Also, minor design changes are made to improve both case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices. The updates in the factory are being implemented in February, 2023.

Change description

Change type

Internal

The side frame for the battery placement is included, helping to determine the exact location of the battery. Also, minor design changes are made to improve both case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices.

Detailed description

Old Version:



New Version:



Change reasons

The battery placement is improved with a side frame, helping to determine the exact location of the battery. Minor design changes are made for case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices.

Product release date

February, 2023

Affected products

Model

Affected order codes

Order code changes

FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, FMM150

FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, FMM150 all codes

Updated the battery placement with the side frame as well as minor design changes for case production and assembly

Change impact

Risk assessment

During the transition period clients might receive devices with old case design used in manufacture

Suggested implementation plan

Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process.

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification – Teltonika may accept that this change has tactically accepted and can implement the change as indicated above.