

June 22 Change Log

[Teltonika wiki change log](#) > **June 22 Change Log**

GENERAL INFORMATION

1. Adjusted FMB640/641 device weight:

https://wiki.teltonika-gps.com/view/FMB640_General_description#Technical_features

https://wiki.teltonika-gps.com/view/FMB641_General_description#Technical_features

2. EYE BEACON and EYE SENSOR page has been updated – GATT characteristics were added:

https://wiki.teltonika-gps.com/view/EYE_BEACON_/BTSID1#GATT_Characteristics

https://wiki.teltonika-gps.com/view/EYE_SENSOR_/BTSMP1#GATT_Characteristics

3. Corrected list of supported devices and firmware version with Auto APN functionality:

https://wiki.teltonika-gps.com/view/Auto_APN_feature_for_FM_trackers

Was added a video on how to update DualCam firmware:

https://wiki.teltonika-gps.com/view/Teltonika_DualCam#DualCam_update_procedure

4. Was added a new firmware version for the device, which support Meig modem (03.27.13.Rev.362):

https://wiki.teltonika-gps.com/view/Teltonika_DualCam#Firmware_Version

5. Updated BTSID/BTSMP MAC Characteristic:

https://wiki.teltonika-gps.com/view/EYE_BEACON_/BTSID1#GATT_Characteristics

https://wiki.teltonika-gps.com/view/EYE_SENSOR_/BTSMP1#GATT_Characteristics

6. Updated (GPRS Settings):

https://wiki.teltonika-gps.com/view/FMB910_GPRS_settings

https://wiki.teltonika-gps.com/view/FMC130_GPRS_settings

https://wiki.teltonika-gps.com/view/FMM130_GPRS_settings

https://wiki.teltonika-gps.com/view/FMB209_GPRS_settings

https://wiki.teltonika-gps.com/view/FMB640_GPRS_settings

https://wiki.teltonika-gps.com/view/FMB641_GPRS_settings

AVL/PARAMETER ID UPDATES

7. Added additional information on new AVL ID's for MSP500 device (bottom of the Permanent I/O elements table):

https://wiki.teltonika-gps.com/view/MSP500_Teltonika_Data_Sending_Parameters_ID#Permanent_I.2_FO_elements

CERTIFICATES

8. Updated FMC125 and FMC225 *CITC* certification:

https://wiki.teltonika-gps.com/view/FMC125_CITC

https://wiki.teltonika-gps.com/view/FMC225_CITC