DSM Firmware errata

 $\underline{\text{Main Page}} > \underline{\text{Video Solutions}} > \underline{\text{DSM}} > \mathbf{DSM}$ Firmware errata

Contents

- 1 DSM Firmware Version
- 2 Firmware for FMC650

DSM Firmware Version

We are always improving our device's performance, stability, and reliability. This document describes **DSM platform** devices' firmware improvements, changes, new features

implementations as well as current firmware release version.

Firmware download for FMx6 device series

Link: Firmware

Password: cU22XsBu

Firmware for FMC650

FIRMWARE VERSION	RELEASE DATE	CHANGES
03.00.16.Rev.104	2024-11-12	Support DSM FW 2.4.0 added.Port tacho border crossing IO.
03.00.16.Rev.101	2024-08-06	 Geofence functionality pictures receiving fix. Green Driving pictures receiving fix. File transfer modem rebooting state fix. Additional verbal information by request/download/upload pictures.
03.00.16.Rev.100	2024-06-12	Port Tacho Border Crossing IO.VDO Counter functionality fix.Full Base Support
03.00.14.Rev.116	2024-04-05	• NEW: ADAS support.
03.00.14.Rev.114	2024-03-01	Added DSM support for FMC650.NEW: Two camera support.
FMX640 FIRMWARE VERSION	RELEASE DATE	CHANGES
01.02.17.Rev.158 (Latest firmware release version for FMX640)	2023-10-09	• Event timeout settings support via CFG

01.02.17.Rev.157 (Latest firmware release version for FMX640)	2023-06-05	 DSM protocol update to 1.4 version Prevent modifying files after DSM Ready state is set IF file corrupted, DSM will return to ready state
01.02.17.Rev.156 (Latest firmware release version for FMX640)	2023-05-02	 Increased event sound max value for voice setting Snapshot retransmit capability is added (periodic and by request) Prevent premature dsm state change from uploading to ready Reject unsolicited snapshot if upload buffer is full Multiple access to SD prevention Yawning sensitivity fixed value Increased UART buffer sizes
01.02.17.Rev.155 (Latest firmware release version for FMX640)	2023-03-16	Initial firmware releaseAdded DSM support

DSM FIRMWARE VERSION	RELEASE DATE	CHANGES
2.4.0	2024-11-13	 Stable work Distraction Bus/Truck feature added Language error fixed(Spanish): Seat belt warning sound changed from English to Spanish Added features: Calibration timeout function Event processing starting from the second yawn event Added new snapshot and driver absence warning options
2.2.0	2023-12-04	Stable workSeat belt detection update
2.2.0.TR1	2023-08-31	Stable workNew calibration page 30.0.0.1:18087
2.0.1	2023-06-26	 Fixed issues related to SD retransmission function Fixed Timestamp values in UTC Fixed GPS coordinates changed to signed int Fixed Snapshot retransmission packet size
2.0.0	2023-03-07	• stable DSM work