

DSM Firmware errata

[Main Page](#) > [Video Solutions](#) > [DSM](#) > **DSM Firmware errata**



Contents

- [1 DSM Firmware Version](#)
- [2 Firmware for FMC650](#)

DSM Firmware Version

We are always improving our device's performance, stability, and reliability. This document describes **DSM platform** devices' firmware improvements, changes, new features implementations as well as current firmware release version.

Firmware download for FMx6 device series

Link: [Firmware](#)

Password: cU22XsBu

Firmware for FMC650

FIRMWARE VERSION	RELEASE DATE	CHANGES
03.00.16.Rev.101	2024-08-06	<ul style="list-style-type: none">• Geofence functionality pictures receiving fix.• Green Driving pictures receiving fix.• File transfer modem rebooting state fix.• Additional verbal information by request/download/upload pictures.
03.00.16.Rev.100	2024-06-12	<ul style="list-style-type: none">• Port Tacho Border Crossing IO.• VDO Counter functionality fix.• Full Base Support
03.00.14.Rev.116	2024-04-05	<ul style="list-style-type: none">• NEW: ADAS support.
03.00.14.Rev.114	2024-03-01	<ul style="list-style-type: none">• Added DSM support for FMC650.• NEW: Two camera support.
FMX640 FIRMWARE VERSION	RELEASE DATE	CHANGES
01.02.17.Rev.158 (Latest firmware release version for FMX640)	2023-10-09	<ul style="list-style-type: none">• Event timeout settings support via CFG

01.02.17.Rev.157 (Latest firmware release version for FMX640)	2023-06-05	<ul style="list-style-type: none"> • DSM protocol update to 1.4 version • Prevent modifying files after DSM Ready state is set • IF file corrupted, DSM will return to ready state
01.02.17.Rev.156 (Latest firmware release version for FMX640)	2023-05-02	<ul style="list-style-type: none"> • Increased event sound max value for voice setting • Snapshot retransmit capability is added (periodic and by request) • Prevent premature dsm state change from uploading to ready • Reject unsolicited snapshot if upload buffer is full • Multiple access to SD prevention • Yawning sensitivity fixed value • Increased UART buffer sizes
01.02.17.Rev.155 (Latest firmware release version for FMX640)	2023-03-16	<ul style="list-style-type: none"> • Initial firmware release • Added DSM support

DSM FIRMWARE VERSION	RELEASE DATE	CHANGES
2.3.0	2024-05-20	<ul style="list-style-type: none"> • Added support for Snapshot OSD • Updated the algorithm to version 1.1.0045 • Fixed an issue where certain characters were not capitalized in French settings • Fixed an issue where the device would not reboot after inserting an SD card.
2.2.0	2023-12-04	<ul style="list-style-type: none"> • Stable work • Seat belt detection update
2.2.0.TR1	2023-08-31	<ul style="list-style-type: none"> • Stable work • New calibration page 30.0.0.1:18087
2.0.1	2023-06-26	<ul style="list-style-type: none"> • Fixed issues related to SD retransmission function • Fixed Timestamp values in UTC • Fixed GPS coordinates changed to signed int • Fixed Snapshot retransmission packet size
2.0.0	2023-03-07	<ul style="list-style-type: none"> • stable DSM work