

December 21 Change Log

[Teltonika wiki change log](#) > **December 21 Change Log**

GENERAL INFORMATION

1. Devices added to Solution applies category (FMB003, FMB002, FMB020, MSP500, FMB209, FMU126, FMM001, FMC001, FMB910, MTB100):

https://wiki.teltonika-gps.com/view/How_to_debug_FMB_device_over_Android_smartphone%3F

2. Update FMX125 RS232/485 pages, removed duplicate information, added video guides:

https://wiki.teltonika-gps.com/view/FMB125_RS-232_and_RS-485

https://wiki.teltonika-gps.com/view/FMM125_RS-232_and_RS-485

3. New chapter added to the FOTA WEB Dashboard page *Cancelling tasks using Batches area*:

https://wiki.teltonika-gps.com/view/FOTA_WEB_Dashboard#Cancelling_tasks_using_Batches_area

4. Added Advanced Beacon Parsing Example to Beacons List:

https://wiki.teltonika-gps.com/view/FMB120_Beacon_List#Parsing_Advanced_Beacon_data_from_record_.28AVL_ID_548.29

5. Fixed CSV file structure for importing tracking units to WEB Tacho:

https://wiki.teltonika-gps.com/view/WEB_Tacho_Vehicles#Importing_vehicle_data_from_.2A.CSV_file

6. Updated FMM130 TAC codes:

https://wiki.teltonika-gps.com/view/FMM130_TAC_codes

7. Updated and uploaded Declaration if IMEI assignment for FMM130:

[FMM130_Declaration_of_IMEI_assignment](#)

8. CAN adapter update Wiki page updated (Added new .GIF and CAN adapter update steps):

[CAN_Adapter_update](#)

9. Updated Beacon List page – added new section EYE Sensor Capturing Configuration:

[FMB120_Beacon_List](#)

10. A relay has been added to the What you need for a solution section of the SECO description:

https://wiki.teltonika-gps.com/view/Secure_vehicle_disabling#What_you_need_for_a_solution.3F

AVL/PARAMETER ID UPDATES

11. Corrected FMX640 sms configuration RS232/485 baudrate settings:

https://wiki.teltonika-gps.com/view/FMB640_Parameter_list

12. Added new section Advanced Beacon Capturing to Beacon list:

https://wiki.teltonika-gps.com/view/FMB120_Beacon_List#Advanced_Beacon_Capturing_Configuration

CERTIFICATES

13. Updated FMM130 CE/RED, EU and UK description:

https://wiki.teltonika-gps.com/view/FMM130_CE/_RED

14. Updated FMB010 CE/RED, EU and UK description:

https://wiki.teltonika-gps.com/view/FMB010_CE/_RED

15. Added NTBC certificate to FMU130 (applied only to the devices with UG96):

https://wiki.teltonika-gps.com/view/FMU130_NBTC

FIRMWARE ERRATA / CONFIGURATOR

16. FM*1YX firmware errata updated - 03.27.07.Rev.252 firmware that is used by FMC130 with MeiG SLM320 modems added to the table:

https://wiki.teltonika-gps.com/view/FMC130_firmware_errata

17. Errata updated, recommended Firmware versions marked to the devices link:

https://wiki.teltonika-gps.com/view/FMB920_firmware_errata

CREATED PAGES

18. Relay page created:

https://wiki.teltonika-gps.com/view/Automotive_Relay

19. Created page FMX Accelerometer Features settings, which describes the accelerometer features settings in all products:

https://wiki.teltonika-gps.com/view/FMB010_Accelerometer_Features_settings

PROMOTIONAL MATERIAL

20. Updated tracking unit illustrations:

https://wiki.teltonika-gps.com/view/FMB125_Promotional_Material

https://wiki.teltonika-gps.com/view/FMM125_Promotional_Material

https://wiki.teltonika-gps.com/view/FMM130_Promotional_Material