

FMB001 Product Change Notifications

[Main Page](#) > [OBD Trackers](#) > [FMB001](#) > **FMB001 Product Change Notifications**

Product change notifications (PCN) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMB001 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

□

Contents

- [1 2024.05.24: New packaging of OBD devices](#)
- [2 2023.04.21: Top Laser Printing Changes](#)
- [3 2022.08.01: Base firmware update](#)
- [4 2022.04.07: Base firmware update](#)
- [5 2022.02.09: Base firmware update](#)
- [6 2021.08.13: Base firmware update](#)
- [7 2021.01.01: Top Laser Printing Changes](#)
- [8 2020.01.22: Base firmware update](#)
- [9 2019.07.22: new no brand Eco friendly boxes](#)
- [10 2019.06.14: Device module information display changes](#)
- [11 2019.05.02: new eco friendly box](#)
- [12 2019.04.10: IMEI/SN display on device Changes](#)
- [13 2019.03.01: new eco friendly box](#)
- [14 2019.02.20: Top Tampography Changes](#)

2024.05.24: New packaging of OBD devices

We would like to inform you, that packaging of the FMB001 device will be updated in the factory from June 2024.

Change description

Change type	External/visual
Detailed description	Additional spacer was added inside the box (applicable to all order codes with SPQ 1) to secure device in place while shipping and create more pleasant unboxing experience.
Change reasons	Due to device being too loose in SPQ 1 box, additional spacer has been added.
Product release date	June 2024



Affected products

Model	Affected order codes	Order code changes
-------	----------------------	--------------------

FMB001 All order codes with SPQ 1:
FMB001H3****
FMB001H5****
FMB001SD****
New packaging

Change impact

Risk assessment No risk factors encountered with this change
Suggested implementation Change instructions and update promotional material if required.
plan



Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2023.04.21: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB001 device was updated in the factory from April 2023.

Change description

Change type External/visual
Detailed description Top laser printing design was changed, additional IMEI/SN QR sticker on the top part of the casing was added
Old version:  New version: 
Change reasons In order to improve the effectiveness of QR scanning additional IMEI/SN QR sticker on the top part of casing was added
Product release date April 2023

Affected products

Model	Affected order codes	Order code changes
FMB001	FMB001 ****	New casing

Change impact

Risk assessment No risk factors encountered with this change
Suggested implementation Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process
plan

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2022.08.01: Base firmware update

We would like to inform you about the base firmware update for FMB001 starting from August 1st, 2022. The new production firmware version will be **03.27.13.Rev.03**

Change description

Change type Hardware and Firmware change
Detailed description OBD data processor of an alternative manufacturer is introduced in the production process. Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB001_firmware_errata
Old version: FMB001 03.27.13.Rev.01
New version: FMB001 03.27.13.Rev.03

Change reasons	Response to the global situation in component market and streamlining our product portfolio.	
Product release date	2022 August	
Affected products		
Model	Affected order codes	Order code changes
FMB001	FMB001***** order codes with base Firmware	OBD processor analog
Change impact		
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. Current CE and E-mark certificates are valid. Also, current purchase codes remain the same.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2022.04.07: Base firmware update

We would like to inform you about the base firmware update for FMB001 starting from March 7th, 2022. The new production firmware version will be **03.27.13.Rev.01**

Change description

Change type	Hardware and Firmware change	
Detailed description	OBD data processor of an alternative manufacturer is introduced in the production process. Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB001_firmware_errata	
	Old version: FMB001 03.27.12.Rev.00	New version: FMB001 03.27.13.Rev.01
Change reasons	Response to the global situation in component market and streamlining our product portfolio.	
Product release date	2022 March	
Affected products		
Model	Affected order codes	Order code changes
FMB001	FMB001***** order codes with base Firmware	OBD processor analog
Change impact		
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. Current CE and E-mark certificates are valid. Also, current purchase codes remain the same.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2022.02.09: Base firmware update

We would like to inform you about the base firmware update for FMB001 starting from February 9th, 2022. The new production firmware version will be **03.27.12.Rev.00**

Change description

Change type	Hardware and Firmware change	
Detailed description	OBD data processor of an alternative manufacturer is introduced in the production process. Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB001_firmware_errata	
	Old version: FMB001 03.27.07.Rev.00	New version: FMB001 03.27.12.Rev.00
Change reasons	Response to the global situation in component market and streamlining our product portfolio.	
Product release date	2022 February	
Affected products		
Model	Affected order codes	Order code changes
FMB001	FMB001***** order codes with base Firmware	OBD processor analog
Change impact		
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture. Current CE and E-mark certificates are valid. Also, current purchase codes remain the same.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2021.08.13: Base firmware update

We would like to inform you about the base firmware update for FMB001 starting from August 13th, 2021. New production firmware version will be 03.27.07.Rev.00

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB001_firmware_errata	
	Old version: FMB001 03.25.18.Rev.08	New version: FMB001 03.27.07.Rev.00

Change reasons	FMB001 base firmware version update	
Product release date	2021 August	
Affected products		
Model	Affected order codes	Order code changes
FMB001	FMB001***** order codes with base Firmware	Update firmware
Change impact		
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2021.01.01: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB001 device was updated in the factory from January 2021.

Change description

Change type	External/visual
	Top laser printing design changed
	Old version:

Detailed description



New version:

Change reasons	1. Updated Emark certificate number. 2. Added UKCA label. 3. Updated Teltonika brand to Teltonika Telematics.
Product release date	January 2021

Affected products

Model	Affected order codes	Order code changes
FMB001	FMB001*****	New casing

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2020.01.22: Base firmware update

We would like to inform you about base firmware update for FMB001 starting from January 22th, 2020. New production firmware version will be **03.25.15.Rev.01**.

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB001_firmware_errata	
Change reasons	Old version: FMB001 03.25.05.Rev.00	New version: FMB001 03.25.15.Rev.01
Product release date	FMB001 base firmware version update 2020 January 22th.	

Affected products

Model	Affected order codes	Order code changes
FMB001	FMB001***** order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2019.07.22: new no brand Eco friendly boxes

Effective September 2019, FMB001 trackers with no brand packaging will be shipped with a **new no brand eco-friendly box**.

Change description

Change type	Packaging Improved and more environmentally friendly packaging box	
Detailed description	Old single packaging version: <input type="checkbox"/>	New single packaging version: <input type="checkbox"/>
	Dimensions: 165 (W) x 145 (D) x 35 (H)	Dimensions: 175 (W) x 150 (D) x 35 (H)
	Old group packaging version: <input type="checkbox"/>	New group packaging version: <input type="checkbox"/>
	Dimensions: 355 (W) x 175 (D) x 60 (H)	Dimensions: 355 (W) x 175 (D) x 60 (H)
Change reasons	The new box is better for the environment	
Product release date	Devices with new packaging will be released in manufacturing from September with 2 months of transition period. Over this period devices with white packaging can be delivered as well as devices with the new eco boxes.	
Affected products	Affected order codes	
Model	FMB001*****, FMB010*****, FMB100*****, FMB110*****, FMB120*****, FMB122*****, FMB125*****, FMB202*****, FMB204*****, FMB900*****, FMB920*****, FMB964*****, FMT100*****, FMB130*****, MTB100*****,	Order code changes No changes
Change impact	No risk factors encountered with this change	
Risk assessment	No risk factors encountered with this change	
Suggested implementation plan	Due to the new look of boxes we strongly recommend to update your marketing materials. Because of the new color of the packaging box, if necessary, update your branding materials (stickers, logo layouts).	

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2019.06.14: Device module information display changes

We would like to inform you, that the information display on device module TM2500 will be updated in the factory from July 2019.

Change description

Change type	External/visual	
Detailed description	Information display on TM2500 module will change from sticker to laser print. Information provided on module will remain the same.	
Change reasons	Old Version: <input type="checkbox"/>	New Version: <input type="checkbox"/>
Product release date	Laser printing will increase reliability, speed, and will reduce paper waste. Devices with new module marking will be released in manufacturing from July with 2 months of transition period. Over this period devices with sticker can be delivered as well as devices with laser print.	

Affected products

Model	Affected order codes	Order code changes
FMB001, FMB010, FMB100, FMB110, FMB120, FMB122, FMB125, FMB202, FMB204, FMB900, FMB920, FMB964, FMT100, FMB640, FMB130, MTB100, TMT250, GH5200.	FMB001*****, FMB010*****, FMB100*****, FMB110*****, FMB120*****, FMB122*****, FMB125*****, FMB202*****, FMB204*****, FMB900*****, FMB920*****, FMB964*****, FMT100*****, FMB640*****, TMT250*****, FMB130*****, MTB100*****, GH5200*****.	No changes

Change impact

Risk assessment	The change will not affect clients. All the module characteristics will remain unchanged. The only sticker on module will be changed to laser print. The displayed information will remain the same.
Suggested implementation plan.	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in the customs clearance process.

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download the pdf version of this notification, [click here](#).

2019.05.02: new eco friendly box

Effective May 2019 week 20, FMB001 trackers will be packed with a **new eco-friendly box**.

Change description

Change type	Packaging
Detailed description	Improved and more environmentally friendly packaging box Old version: <input type="checkbox"/> New version: <input checked="" type="checkbox"/>
Change reasons	The new box is better for the environment
Product release date	May 2019, week 20

2019.04.10: IMEI/SN display on device Changes

We would like to inform you, that IMEI/SN info display on the FMB001 device will be updated in the factory from June 2019.

Change description

Change type	External/visual
Detailed description	IMEI/SN info on device display change from barcode to QR Old Version: <input checked="" type="checkbox"/> New Version: <input checked="" type="checkbox"/> This change will not affect device packing and logistic lists. It will remain as barcode.

Detailed description



Change reasons

QR format will increase reliability and minimize error rate, because of the error correction feature and improved reading in low contrast.

Product release date

Devices with new QR Code format will be released in manufacturing from June with 2 months of transition period. Over this period devices with barcode can be delivered as well as devices with QR code.

Affected products

Model	Affected order codes	Order code changes
FMB001	FMB001*****	No changes

Change impact

Risk assessment	Risk assessment for devices management required
Suggested implementation plan	Due to changes in device information display we strongly recommend to check, and prepare your tools to read QR codes.

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download the pdf version of this notification, [click here](#).

2019.03.01: new eco friendly box

Effective March 2019, FMB001 trackers will be shipped with a **new eco-friendly box**.

Change description

Change type	Packaging	
Detailed description	Improved and more environmentally friendly packaging box	
Change reasons	Old version: <input type="checkbox"/>	New version: <input type="checkbox"/>
Product release date	The new box is better for the environment	
	March 2019	

Affected products

Model	Affected order codes	Order code changes
FMB001	FMB001*****	No changes

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2019.02.20: Top Tampography Changes

We would like to inform you, that tampography of the FMB001 device was updated in the factory on the 20th of February.

Change description

Change type	External/visual	
Detailed description	Top tampography design changed	
Change reasons	Old Version: <input type="checkbox"/>	New Version: <input type="checkbox"/>
Product release date	1. Updated Teltonika address to Saltoniskiu st. 9B-1 2. Added WEEE label. (WEEE - Waste from Electrical and Electronic Equipment)	
	Updated tampographs will be used from the time when the stock will be sold all leftovers. Planned date: week 9	

Affected products

Model	Affected order codes	Order code changes
FMB001	FMB001*****	No changes

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

To download the pdf version of this notification, [click here](#).