# FMB010 Product Change Notifications

<u>Main Page</u> > <u>Fast & Easy Trackers</u> > <u>FMB010</u> > **FMB010 Product Change Notifications** 

**Product change notifications (PCN)** is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMB010 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

### **Contents**

- 1 2024.06.30: Base firmware update
- 2 2024.06.03: New packaging of OBD devices
- 3 2024.03.08: Top Laser Printing Changes
- 4 2023.04.21: Top Laser Printing Changes
- <u>5 2022.08.01</u>: Base firmware update
- 6 2021.08.13: Base firmware update
- 7 2021.01.01: Top Laser Printing Changes
- 8 2020.01.22: Base firmware update
- 9 2019.07.22: new no brand Eco friendly boxes

# 2024.06.30: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from July, 2024. New production firmware version will be **03.29.00.Rev.554** 

Change description

Change type Firmware update

Key improvements from last production firmware are listed in errata: FMB010 firmware errata

Detailed description Old version: New version: 03.27.13.Rev.03 03.29.00.Rev.554

Change reasons FMB010 base firmware version update

Product release date 2024 July

Affected products

Model Affected order codes Order code changes
FMB010 All order codes New firmware version

Change impact

Risk assessment Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically.

During the transition period clients might receive devices with previous Firmware version used in manufacture.

Suggested implementation plan If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

# 2024.06.03: New packaging of OBD devices

We would like to inform you, that packaging of the FMB010 device will be updated in the factory from June 2024.

#### Change description

Change type External/visual

Additional spacer was added inside the box (applicable to all order codes with

SPQ 1) to secure device in place while shipping and create more pleasant

Detailed unboxing experience.

description Old remains

Old version: New version:

×

Change reasons Due to device being too lose in SPQ 1 box, additional spacer has been added.

Product release

date June 2024

Affected products

Model Affected order codes Order code changes

Standard and Sample order codes with

FMB010 SPQ 1: New packaging

FMB010\*\*\*\*\*

Change impact

Risk assessment No risk factors encountered with this change

Suggested

implementation Change instructions and update promotional material if required.

plan

# 2024.03.08: Top Laser Printing Changes


We would like to inform you, that laser printing of the FMB010 device was updated in the factory in March, 2024.

#### **Change description**

Change type External/visual

Top laser printing design changed

Old version:



Change reasons

1. Serial number, IMEI QR codes will now be laser engraved

2. Stickers containing serial number, IMEI QR codes will no longer be present on the casing.

Product release date March 2024

### **Affected products**

Model Affected order codes Order code changes

FMB010\*\*\*\*\* FMB010 New casing

Change impact

Risk assessment No risk factors encountered with this change

Due to changes in device appearance we strongly recommend to contact your Suggested implementation customs agent with our change log information, to avoid any unexpected delays

in customs clearance process plan

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

# 2023.04.21: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB010 device was updated in the factory from April 2023.

### Change description

External/visual Change type

Top laser printing design was changed, additional IMEI/SN QR sticker on the

top part of the casing was added Detailed

description Old version: New version:

×

In order to improve the effectiveness of OR scanning additional IMEI/SN OR Change reasons

sticker on the top part of casing was added

Product release

April 2023 date

#### **Affected products**

Model Affected order codes Order code changes

FMB010\*\*\*\*\* FMB010 New casing

Change impact

No risk factors encountered with this change Risk assessment

Suggested Due to changes in device appearance we strongly recommend to contact your implementation customs agent with our change log information, to avoid any unexpected delays

plan in customs clearance process

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

# 2022.08.01: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from August 1st, 2022. New production firmware version will be 03.27.13.Rev.03

Change description

Change type Firmware update

Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010\_firmware\_errata

Detailed description

New version: FMB010 03.27.13.Rev.03 FMB010 03.27.07.Rev.00

Change reasons FMB010 base firmware version update Product release date

2022 August

Affected products

Model Affected order codes Order code changes FMB010 FMB010\*\*\*\*\*\* order codes with base Firmware Update firmware

# 2021.08.13: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from August 13th, 2021. New production firmware version will be 03.27.07.Rev.00

Change description

Change type Firmware update

Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010\_firmware\_errata

Detailed description New version: FMB010 03.27.07.Rev.00 Old version:

FMB010 03.25.18.Rev.08

FMB010 base firmware version update Change reasons

Product release date 2021 August

Affected products

Model Affected order codes Order code changes FMB010\*\*\*\*\*\* order codes with base Firmware FMB010 Update firmware

Change impact

Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. Risk assessment

During the transition period clients might receive devices with previous Firmware version used in manufacture.

If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. Suggested implementation plan

2021.01.01: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB010 device was updated in the factory from January 2021.

#### **Change description**

Change type

External/visual

Top laser printing design changed

Old version:



1. Updated Emark certificate number.

Change reasons

- 2. Added UKCA label.
- 3. Updated Teltonika brand to Teltonika Telematics.

Product release date January 2021

### Affected products

Model Affected order codes Order code changes

FMB010\*\*\*\*\* FMB010 New casing

Change impact

Risk assessment No risk factors encountered with this change

Due to changes in device appearance we strongly recommend to contact your Suggested implementation customs agent with our change log information, to avoid any unexpected delays

plan in customs clearance process

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

# 2020.01.22: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from January 22th, 2020. New production firmware version will be **03.25.15.Rev.01**.

Change description

Change type Firmware update

Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010\_firmware\_errata

New version:

Detailed description Old version:

FMB010 03.25.05.Rev.00 FMB010 03.25.15.Rev.01

Change reasons FMB010 base firmware version update

Product release date 2020 January 22th.

Affected products

Model Affected order codes Order code changes FMB010 FMB010\*\*\*\*\*\* order codes with base Firmware Update firmware

Change impact

Risk assessment Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager. Suggested implementation plan

# 2019.07.22: new no brand Eco friendly boxes

Effective September 2019, FMB010 trackers with no brand packaging will be shipped with a **new no** brand eco-friendly box.

Change description

Detailed description

Change type Packaging

Improved and more environmentally friendly packaging box

Old single packaging version:

×

**Dimensions:** 165 (W) x 145 (D) x 35 (H)

Old group packaging version:

Dimensions: 175 (W) x 150 (D) x 35 (H)

New single packaging version:

Dimensions: 355 (W) x 175 (D) x 60 (H)

**Dimensions:** 355 (W) x 175 (D) x 60 (H)

Change reasons The new box is better for the environment

Devices with new packaging will be released in manufacturing from September with 2 months of transition period. Over this period Product release date

devices with white packaging can be delivered as well as devices with the new eco boxes.

Affected products

Model Affected order codes Order code changes

FMB001, FMB010, FMB100, FMB001\*\*\*\*\*, FMB010\*\*\*\*\*, FMB100\*\*\*\*\*, FMB110\*\*\*\*\*\*, FMB110, FMB120, FMB122,

FMB125, FMB202, FMB204, No changes FMB900, FMB920, FMB964,

FMT100\*\*\*\*\*\*\* FMB130\*\*\*\*\*\* MTB100\*\*\*\*\*\* FMT100, FMB130, MTB100.

Change impact

No risk factors encountered with this change Risk assessment

Suggested implementation plan Due to the new look of boxes we strongly recommend to update your marketing materials. Because of the new color of the packaging box, if necessary, update your branding materials (stickers, logo layouts).

#### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above