# **FMC800 Product Change Notifications**

<u>Main Page</u> > <u>Fast & Easy Trackers</u> > <u>FMC800</u> > **FMC800 Product Change Notifications** 

**Product change notifications (PCN)** is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMC800 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

### Contents

- <u>1 2024.08.13: Base firmware update</u>
- 2 2024.06.03: New packaging of OBD devices
- <u>3 2024.05.03: Base firmware update</u>
- <u>4 2024.03.08: Top Laser Printing Changes</u>
- <u>5 2023.09.29: Base firmware update</u>
- <u>6 2023.04.10: Base firmware update</u>
- 7 2023.02.17: Base firmware update

### 2024.08.13: Base firmware update

We would like to inform you about the base firmware update for FMC800 starting from August, 2024. New production firmware version will be 03.29.00.rev.458

Change description			
Change type	Firmware update		
Key improvements from last production firmware are listed in errata: <u>https://wiki.teltonika-gps.com/view/FMC80</u>		ata: <u>https://wiki.teltonika-gps.com/view/FMC800_firmware_errata</u>	
Detailed description	Old version:	New version:	
	FMC800 03.28.07.Rev.457	FMC800 03.29.00.rev.458	
Change reasons	FMC800 base firmware version update		
Product release date	2024 August		
Affected products			
Model	Affected order codes	Order code changes	
FMC800	FMC800******* order codes with base Firmware	Update firmware	
Change impact			
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically.		
	During the transition period clients might receive devices with previous Firmware version used in manufacture.		
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.		

## 2024.06.03: New packaging of OBD devices

We would like to inform you, that packaging of the FMC800 device will be updated in the factory from June 2024.

#### **Change description**

Change type External/visual

Detailed description	Additional spacer was added inside the box (applicable to all order codes with SPQ 1) to secure device in place while shipping and create more pleasant unboxing experience.		
	Old version:	New version:	
Change reasons	Due to device being too lose in SPQ 1 box, additional spacer has been added.		
Product release date	June 2024		
Affected products			
Model	Affected order codes	Order code changes	
FMC800	Standard and Sample order codes with SPQ 1: FMC800*****	New packaging	
Change impact			
Risk assessment	No risk factors encountered with this change		
Suggested implementation plan	Change instructions and update promotional material if required.		
Acknowledgement of PCN receipt			

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

### 2024.05.03: Base firmware update

We would like to inform you about the base firmware update for FMC800 starting from May, 2024. New production firmware version will be 03.29.00.rev.457

Change description		
Change type	Firmware update	
	Key improvements from last production firmware are listed in errata: <u>https://wiki.teltonika-gps.com/view/FMM800_firmware_er</u>	
Detailed description	Old version:	New version:
	FMC800 03.28.07.Rev.353	FMC800 03.29.00.rev.457
Change reasons	FMC800 base firmware version update	
Product release date	2024 May	
Affected products		
Model	Affected order codes	Order code changes
FMC800	FMC800******* order codes with base Firmware	Update firmware
Change impact		
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your <sup>1</sup> Teltonika sales manager.	

### 2024.03.08: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMC800 device was updated in the factory in March, 2024.

#### **Change description**

Change type

External/visual

Detailed description

Top laser printing design changed Old version:

New version:

Change reasons	<ol> <li>Serial number, IMEI QR codes will now be laser engraved</li> <li>Stickers containing serial number, IMEI QR codes will no longer be present on the casing.</li> </ol>	
Product release date	March 2024	
Affected products		
Model	Affected order codes	Order code changes
FMC800	FMC800*****	New casing
Change impact		
Risk assessment	No risk factors encountered with this change	
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process	
Acknowledgement of PCN receipt		

#### **Acknowledgement of PCN receipt**

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

### 2023.09.29: Base firmware update

We would like to inform you about the base firmware update for FMC800 starting from September 29th, 2023. New production firmware version will be 03.28.07.Rev.353

#### Change description

change acscription		
Change type	Firmware update	
Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FM		ta: https://wiki.teltonika-gps.com/view/FMC800_firmware_errata
Detailed description		New version: FMC800 03.28.07.Rev.353
Change reasons	FMC800 base firmware version update	
Product release date	2023 September	
Affected products		
Model	Affected order codes	Order code changes
FMC800	FMC800******* order codes with base Firmware	Update firmware
Change impact		
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

### 2023.04.10: Base firmware update

We would like to inform you about the base firmware update for FMC800 starting from April 10th, 2023. New production firmware version will be 03.28.02.Rev.143

#### **Change description** Change type Firmware update Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMC800\_firmware\_errata Detailed description Old version: New version: FMC800 03.28.02.Rev.143 FMC800 03.28.02.Rev.142 Manufacture testing optimization. Change reasons Product release date 2023 - April Affected products Model Affected order codes Order code changes FMC800 FMC800\*\*\*\*\*\*\* standard order codes with base firmware Update firmware

### 2023.02.17: Base firmware update

We would like to inform you about the base firmware update for FMC800 starting from February

### 17th, 2023. New production firmware version will be 03.28.02.Rev.142

Change description

Change type

Detailed description

Change reasons Product release date **Affected products** Model FMC800 Firmware update
Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMC800\_firmware\_errata
Old version:
FMC800 03.28.02.Rev.126
Manufacture testing optimization and addition of network jamming support for FMC800 hardware.
2023 - February Firmware Update with network jamming support

Affected order codes FMC800\*\*\*\*\*\*\* standard order codes with base firmware

Order code changes Update firmware