

# FMU125 Product Change Notifications

[Main Page](#) > [EOL Products](#) > [FMU125](#) > **FMU125 Product Change Notifications**

**Product change notifications (PCN)** is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMU125 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

□

## Contents

- [1 2021.08.19: Base firmware update](#)
- [2 2021.03.16: Base firmware update](#)
- [3 2021.02.18: Base firmware update](#)
- [4 2019.11.28: Top Device Marking Changes](#)

## 2021.08.19: Base firmware update

We would like to inform you about the base firmware update for FMU125 starting from August 19th, 2021. New production firmware version will be **03.27.07.Rev.00**

### Change description

Change type	Firmware update	
	Key improvements from last production firmware are listed in errata: <a href="https://wiki.teltonika-gps.com/view/FMU125_firmware_errata">https://wiki.teltonika-gps.com/view/FMU125_firmware_errata</a>	
Detailed description	Old version: FMU125 03.27.04.Rev.01	New version: FMU125 03.27.07.Rev.00
Change reasons	FMU125 base firmware version update	
Product release date	2021 August	

### Affected products

Model	Affected order codes	Order code changes
FMU125	FMU125***** order codes with base Firmware	Update firmware

### Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

## 2021.03.16: Base firmware update

We would like to inform you about the base firmware update for FMU125 starting from March 16th, 2021. The new production firmware version will be **03.27.04.Rev.01**.

### Change description

Change type	Firmware update	
	Key improvements from last production firmware are listed in errata: <a href="https://wiki.teltonika-gps.com/view/FMU125_firmware_errata">https://wiki.teltonika-gps.com/view/FMU125_firmware_errata</a>	
Detailed description	Old version: FMU125 03.27.03.Rev.02	New version: FMU125 03.27.04.Rev.01
Change reasons	FMU125 base firmware version update	
Product release date	2021 March 16th.	

### Affected products

Model	Affected order codes	Order code changes
FMU125	FMU125***** order codes with base Firmware	Update firmware

**Change impact**

Risk assessment Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically  
 Suggested implementation plan If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

## 2021.02.18: Base firmware update

We would like to inform you about the base firmware update for FMU125 starting from February 18th, 2021. The new production firmware version will be **03.27.03.Rev.02**.

**Change description**

Change type Firmware update  
 Key improvements from last production firmware are listed in errata: [https://wiki.teltonika-gps.com/view/FMU125\\_firmware\\_errata](https://wiki.teltonika-gps.com/view/FMU125_firmware_errata)  
 Detailed description Old version: FMU125 03.27.02.Rev.00 New version: FMU125 03.27.03.Rev.02  
 Change reasons FMU125 base firmware version update  
 Product release date 2021 February 18th.

**Affected products**

Model Affected order codes Order code changes  
 FMU125 FMU125\*\*\*\*\* order codes with base Firmware Update firmware

**Change impact**

Risk assessment Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically  
 Suggested implementation plan If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

## 2019.11.28: Top Device Marking Changes

We would like to inform you, that tampography of the FMU125 device was updated to engraving in the factory.

**Change description**

Change type External/visual  
 Device marking changed from tampography to laser printing. Information provided on module will remain the same  
 Detailed description Old Version:  New Version:   
 Change reasons To improve manufacturing speed, efficiency and reliability  
 To increase quality, precision and durability of marking.  
 Product release date Planned date: 2019 December

**Affected products**

Model all codes with standard marking Order code changes  
 FMU125 FMU125\*\*\*\*\* No changes

**Change impact**

Risk assessment No risk factors encountered with this change  
 Suggested implementation plan No implementation plan needed

**Acknowledgement of PCN receipt**

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above