

MSP500 firmware errata

[Main Page](#) > [EOL Products](#) > [MSP500](#) > **MSP500 firmware errata**



Contents

- [1 Introduction](#)
- [2 Firmware versioning](#)
- [3 Firmware versions](#)

Introduction

We are always improving our devices performance, stability and reliability. That's why Teltonika is one of the leading GNSS trackers manufacturers in the world.

This document describes **MSP500** device firmware improvements, changes, new features implementations as well as current firmware release version.

FIRMWARE VERSION	SUPPORTED HARDWARE
03.25.XX	MSP500

Firmware versioning

- Structure

FMB(T).VER.[XX].[YY].[ZZ].Rev.[##]_[ID###]

- Syntax description
 - XX - major FW version.
 - YY - branch number, shows major changes in firmware, i.e. new module support added or new major feature added.
 - ZZ - major changes like bigger fixes, improvements and new features addition.
 - ## - minor changes like small fixes and improvements.
 - ID[###] - Spec ID KEY - Client specific FW changes.

Firmware versions

FIRMWARE VERSION	RELEASE DATE	CHANGES
FMB.Ver.03.25.05.Rev.127	2019.11.22	<ul style="list-style-type: none">• Stability improvements• General Fixes• Initial release