

March 23 Change Log

[Teltonika wiki change log](#) > **March 23 Change Log**

General information

1. New feature description added:

https://wiki.teltonika-gps.com/view/TFT100_Features_settings#Ignition_On_Counter

„Ignition on counter“ section added.

2. DualCam’s **File Transfer priority** configuration description was added:

https://wiki.teltonika-gps.com/view/DualCam_Configuration#File_Transfer_priority

AVL/parameter ID updates

1. TFT100 Parameter list updated:

https://wiki.teltonika-gps.com/view/TFT100_Parameter_list#Manual_CAN_Settings_2

New Manual CAN baudrate option (800k) added.

Firmware errata / Configurator

1. New firmware version for the device FMX640 was released:

https://wiki.teltonika-gps.com/view/ADAS_Firmware_errata

2. New short-term FW (**55.01.13.Rev.00**) was uploaded for the TFT100 device:

https://wiki.teltonika-gps.com/view/TFT100_Short-term_firmware

3. New short-term FW (**55.01.13.Rev.00**) was uploaded for the TST100 device:

https://wiki.teltonika-gps.com/view/TST100_Short-term_firmware

4. New firmware version for the device FMX125 released:

https://wiki.teltonika-gps.com/view/DualCam_Firmware_errata#Firmware_for_FMX125

Product Change Notifications (PCN)

1. New general PCN regarding GSM/LTE antenna bridge colour difference was added:

https://wiki.teltonika-gps.com/view/General_PCN#2023.03.07:_GSM.2FLTE_antenna_bridge_color_difference

2. New PCN was added to Wiki projects FMC920, FMM920, FMB920, FMB900:

https://wiki.teltonika-gps.com/view/FMC920_Product_Change_Notifications

3. Added new **GH5200** Product Change Notification **2023.03.17: New no brand Eco friendly boxes:**

[https://wiki.teltonika-gps.com/GH5200_Product_Change_Notifications#2022.03.17: New no brand Eco friendly boxes](https://wiki.teltonika-gps.com/GH5200_Product_Change_Notifications#2022.03.17:New_no_brand_Eco_friendly_boxes)

FAQ

1. Created new FAQ page **What to do if the FM device shows old program number instead of new configured one?**

https://wiki.teltonika-gps.com/view/What_to_do_if_the_FM_device_shows_old_program_number_instead_of_new_configured_one%3F

2. Updated wiki page:

https://wiki.teltonika-gps.com/view/EYE_FAQ#Do_I_need_to_configure_UUID_.2F_Instance_ID.2C_how_is_UUID_.2F_MAC_generated.3F

Created pages

1. Created a new wiki page *FISHING BOATS TRACKING WITH IP67 RATING GPS DEVICES:*

https://wiki.teltonika-gps.com/view/FISHING_BOATS_TRACKING_WITH_IP67_RATING_GPS_DEVICES

2. New wiki page was created:

https://wiki.teltonika-gps.com/view/EYE_APP_errata