

September 22 Change Log

[Teltonika wiki change log](#) > **September 22 Change Log**

General Information

1. FMB, FMC and FMM640 configurator version and configurator itself have been updated:

https://wiki.teltonika-gps.com/view/Teltonika_Configurator_versions

2. Updated information for FM6 *iButton* read notification:

https://wiki.teltonika-gps.com/view/FMB641_Features_settings#iButton_Read_Notification

https://wiki.teltonika-gps.com/view/FMB640_Features_settings#iButton_Read_Notification

https://wiki.teltonika-gps.com/view/FMC640_Features_settings#iButton_Read_Notification

https://wiki.teltonika-gps.com/view/FMM640_Features_settings#iButton_Read_Notification

3. Updated frequency bands under FAQ section:

https://wiki.teltonika-gps.com/wikibase/index.php?title=Frequency_Bands&oldid=76136

4. The structure of the ADAS wiki page was changed:

https://wiki.teltonika-gps.com/view/Teltonika_ADAS

AVL/parameter ID updates

5. FMX640 project devices now available to use Eco driving in Wialon application and AVL ID 258 is now could be used:

https://wiki.teltonika-gps.com/view/How_to_set_up_Eco_Driving_in_Wialon_app

Firmware errata / Configurator

6. Added 03.27.13.Rev.03 FW to FMM130 firmware errata:

https://wiki.teltonika-gps.com/view/FMM130_firmware_errata

Product Change Notifications (PCN)

7. FMB640, FMC640 and FMM640 firmware errata and PCN has been updated:

https://wiki.teltonika-gps.com/view/FMB640_firmware_errata

https://wiki.teltonika-gps.com/view/FMC640_firmware_errata

https://wiki.teltonika-gps.com/view/FMM640_firmware_errata

https://wiki.teltonika-gps.com/view/FMM640_Product_Change_Notifications

https://wiki.teltonika-gps.com/view/FMC640_Product_Change_Notifications

https://wiki.teltonika-gps.com/view/FMB640_Product_Change_Notifications