

Template:TAT141 stable FW&SW changelog

VERSION	RELEASE DATE	CONFIGURATOR CHANGES	FIRMWARE CHANGES
Firmware version: 55.00.16.Rev.564 BlueNRG version: 0.4.12 Configurator version: 1.7.74_B.TAT1_R.6	2024.03.12	<ul style="list-style-type: none">• Fixed configurator crash after firmware update.• Added cell ID I/O elements	<ul style="list-style-type: none">• Fixed periodic timer starting in Recovery mode.• Improved backup tracker scan procedure.• Fixed issue with GPS fix with First Power On record.• Improved energy management in sleep mode when device is in motion.• Fixed crash on BLE sensor alarm.• Bluetooth scanning and data parsing optimization.• DNS resolve improvements.• Fixed periodic timer starting when tracking scenario selected as None.• Added cell ID I/O elements
Firmware version: 55.00.16.Rev.558 BlueNRG version: 0.4.8 Configurator version: 1.7.16_B.TAT1_R.3	2023.07.18	<ul style="list-style-type: none">* Removed non configurable elements	<ul style="list-style-type: none">• [FIX] Improved EYE sensor data detection to be suitable for all sensor modes• [FIX] Fixed Periodic timer still running when Recovery mode is activated in sleep from Backup tracker• [FIX] Hotfix for EG915ULA modem status commands
Firmware version: 55.00.16.Rev.557 BlueNRG version: 0.4.7 Configurator version: 1.7.16_B.TAT1_R.1	2023.05.10	Initial release	Initial release