

ADAS Firmware errata

[Main Page](#) > [Video Solutions](#) > [Teltonika ADAS](#) > **ADAS Firmware errata**



Contents

- [1 Firmware for FMC650](#)
- [2 ADAS Firmware Version](#)

We are always improving our device's performance, stability, and reliability. This document describes **ADAS platform** devices' firmware improvements, changes, new features implementations as well as current firmware release version.

Firmware download for FMX:125/225/640/FMC650

Link: [Firmware](#)

Password: lXKOpgIu

Firmware for FMC650

FIRMWARE VERSION	RELEASE DATE	CHANGES
03.00.14.Rev.116	2024-04-05	• NEW: ADAS support.

ADAS Firmware Version

FMX640 FIRMWARE VERSION	RELEASE DATE	CHANGES
01.02.22.Rev.105	2024-04-15	• Video download improvements • Overlay functions improvements • Save to SD settings improvements • Improve stable work
01.02.22.Rev.102	2023-03-13	• CRC calculation from a proper location not from a hardcoded Flash area • Wrong server used with consecutive uploads • Metadata request type changed for periodic snapshot • Periodic image request by date instead of the current snapshot • Fixed auto baud rate functionality unpausing scheduled jobs • Prevent SD card access when downloading from MDAS • Remount SD card when a disk error occurs • Camera resolution configuration • Default server\port in SMS requests • Setting the overlay when it is disabled • MDAS speed source selection • Record sending with file details

01.02.22.Rev.101	2022-10-21	• Crash in DDD files sending • ADAS base update
01.02.10.Rev.103_ID1039	2022-07-05	• Firmware for FMC640 and FMB640 • Base update to latest version • Video/photo by request • Periodic photo sending

FMX125/FMX225 FIRMWARE VERSION

RELEASE DATE	CHANGES
03.27.13.Rev.370	2022-07-26
	• Base update to latest version Meig Support • Accessory monitoring port to MDAS9 • Firmware for FMX125 and FMX225 also for Meig
03.27.07.Rev.370	2021-10-18
	• Base update to latest version • Minor configurator fixes • Improved system stability and fixed general bugs • Firmware for FMX125 and FMX225
03.27.01.Rev.242	2021-01-06
	• FPW and FVSA bug fixes • Minor improvements
03.27.01.Rev.240	2020-10-26
	• Added ADAS camera support • Initial release

ADAS FIRMWARE VERSION

RELEASE DATE	CHANGES
0.6.32	2023-04-17
	• [FIX] File transfer resume multiple presents for the same request • [FIX] Packet index number in transfer resume CMD according to argument 2023.12.05 • [FIX] Packet index number in transfer resume • [FIX] Video and snapshot transfer resume
0.6.15	2023-06-15
	• Fix Video and snapshot transfer resume • Fix OSD ON/OFF functionality
0.6.10	2022-10-14
	• Fixed malfunction of Lock Volume function • Fix on vehicle file not applied properly via FMS command
0.6.03	2022-07-22
	• Fixed miss usage of HEX values instead of DEC
0.6.01	2022-07-12
	• Fix where protocol version changed to 13 or 0x13 • Fix for wrong GPS coordinates offset
0.5.99	2022-07-10
	• Added video compression quality change via 0x7D • Added file transfer resume via 0x9F • Fixed abnormal packet communication during fw update • Fixed speed value display on overlay • Fixed option to use only FMx GPS data via 0x9C
0.5.95	2022-06-01
	• Support 128 Gb SD card • Video/photo by request • Periodic photo sending

0.5.78	2021-07-21	• Configurable video size supported
0.5.68	2021-04-19	• Russian language added
0.5.12	2019-07-19	• LDW activation speed (mph) changed