FMB003 Product Change Notifications

<u>Main Page</u> > <u>OBD Trackers</u> > <u>FMB003</u> > **FMB003 Product Change Notifications**

Product change notifications (PCN) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMB003 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

Contents

- <u>1 2023.04.12: Base firmware update</u>
- 2 2022.12.12: Base firmware update
- <u>3 2022.04.27: Base firmware update</u>
- <u>4 2021.09.16: Base firmware update</u>
- 5 2020.12.11: New FMB003, FMB002, FMB020 casing

2023.04.12: Base firmware update

We would like to inform you about the base firmware update for FMB003 starting from April 12th, 2023. New production firmware version will be 03.28.03.Rev.97

Change description			
Change type	Firmware update		
	Key improvements from last production firmware are listed in errata: FMB003_firmware_errata		
Detailed description	Old version: FMB003 03.28.03.Rev.94	New version: FMB003 03.28.03.Rev.97	
Change reasons	FMx003 base firmware version update		
Product release date	2023 April		
Affected products			
Model	Affected order codes	Order code changes	
FMB003	FMB003******* order codes with base Firmware	Update firmware	
Change impact			
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.		

Suggested implementation plan If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

Acknowledgement If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2022.12.12: Base firmware update

We would like to inform you, that laser printing of the FMB003 device was updated in the factory on December 2022.

Change description		
Change type	External/visual	
	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB003_firmware_errata	
Detailed description	Old version:	New version:
	×	×
Change reasons	1. Added ANATEL label and certificate number.	
Product release date	December 2022	

Affected order codes FMB003******

No risk factors encountered with this change

Order code changes New casing

Suggested implementation plan Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

Acknowledgement If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2022.04.27: Base firmware update

We would like to inform you about the base firmware update for FMB003 starting from April 27th, 2022. New production firmware version will be 03.27.12.Rev.93

Change description Change type Firmware update Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB003_firmware_errata Detailed description Old version: New version: FMB003 03.27.07.Rev.94 FMB003 03.27.12.Rev.93 Change reasons FMB003 base firmware version update Product release date 2022 April Affected products Model Affected order codes Order code changes FMB003******* order codes with base Firmware FMB003 Update firmware **Change** impact Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. Risk assessment During the transition period clients might receive devices with previous Firmware version used in manufacture. If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Suggested implementation plan Teltonika sales manager.

2021.09.16: Base firmware update

We would like to inform you about the base firmware update for FMB003 starting from September 13th, 2021. New production firmware version will be 03.27.07.Rev.94

Change description			
Change type	Firmware update		
	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB003_firmware_errata		
Detailed description	Old version:	New version:	
	FMB003 03.25.17.Rev.95	FMB003 03.27.07.Rev.94	
Change reasons	FMB003 base firmware version update		
Product release date	2021 September		
Affected products			
Model	Affected order codes	Order code changes	
FMB003	FMB003******* order codes with base Firmware	Update firmware	
Change impact			
Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.		
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your ¹ Teltonika sales manager.		

2020.12.11: New FMB003, FMB002, FMB020 casing

Effective December 2020, FMB003, FMB002, FMB020 trackers will be shipped with a new casing.

Change description Change type

Detailed description

Casing Reduced length to make it even a smaller OBD device. Old Version:

×

Dimensions: 52.6 (L) x 29.1 (W) x 26 (H)

Change reasons	New device casing fits better on some vehicle models where OBD port is obstructed by additional plastic parts from vehicle dashboard front panel.		
Product release date	Devices with new casing will be released in manufacturing from November.		
Affected products			
Model	Current codes	New order codes	
FMB003, FMB002, FMB020.	FMB003 M7 ****, FMB002 8M ****, FMB020 E1 ****.	FMB003 0E**** , FMB002 Z1**** , FMB020 4M**** .	
Change impact			
Risk assessment	No risk factors encountered with this change		
Suggested implementation plan.	Due to the new look of casing we recommend to update your marketing materials. Because of the new casing, if necessary, update your branding materials (stickers, logo layouts).		

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above