

FMB010 Product Change Notifications

[Main Page](#) > [Fast & Easy Trackers](#) > [FMB010](#) > **FMB010 Product Change Notifications**

Product change notifications (PCN) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMB010 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

□

Contents

- [1 2024.06.30: Base firmware update](#)
- [2 2024.06.03: New packaging of OBD devices](#)
- [3 2024.03.08: Top Laser Printing Changes](#)
- [4 2023.04.21: Top Laser Printing Changes](#)
- [5 2022.08.01: Base firmware update](#)
- [6 2021.08.13: Base firmware update](#)
- [7 2021.01.01: Top Laser Printing Changes](#)
- [8 2020.01.22: Base firmware update](#)
- [9 2019.07.22: new no brand Eco friendly boxes](#)

2024.06.30: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from July, 2024. New production firmware version will be **03.29.00.Rev.554**

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: FMB010 firmware errata	
Change reasons	FMB010 base firmware version update	
Product release date	2024 July	

Affected products

Model	Affected order codes	Order code changes
FMB010	All order codes	New firmware version



Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2024.06.03: New packaging of OBD devices

We would like to inform you, that packaging of the FMB010 device will be updated in the factory from June 2024.

Change description

Change type	External/visual
Detailed description	Additional spacer was added inside the box (applicable to all order codes with SPQ 1) to secure device in place while shipping and create more pleasant unboxing experience.
	Old version:  New version: 
Change reasons	Due to device being too loose in SPQ 1 box, additional spacer has been added.
Product release date	June 2024

Affected products

Model	Affected order codes	Order code changes
FMB010	Standard and Sample order codes with SPQ 1: FMB010*****	New packaging

Change impact



Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Change instructions and update promotional material if required.

2024.03.08: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB010 device was updated in the factory in March, 2024.

Change description

Change type	External/visual
	Top laser printing design changed
	Old version:

Detailed description		New version: 
----------------------	--	--

Change reasons	1. Serial number, IMEI QR codes will now be laser engraved 2. Stickers containing serial number, IMEI QR codes will no longer be present on the casing.
Product release date	March 2024

Affected products

Model	Affected order codes	Order code changes
FMB010	FMB010*****	New casing

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process



Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2023.04.21: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB010 device was updated in the factory from April 2023.

Change description

Change type	External/visual
Detailed description	Top laser printing design was changed, additional IMEI/SN QR sticker on the top part of the casing was added Old version:  New version: 
Change reasons	In order to improve the effectiveness of QR scanning additional IMEI/SN QR sticker on the top part of casing was added
Product release date	April 2023

Affected products

Model	Affected order codes	Order code changes
FMB010	FMB010*****	New casing

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2022.08.01: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from August 1st, 2022. New production firmware version will be 03.27.13.Rev.03

Change description

Change type	Firmware update
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010_firmware_errata Old version: FMB010 03.27.07.Rev.00 New version: FMB010 03.27.13.Rev.03
Change reasons	FMB010 base firmware version update

Product release date	2022 August	
Affected products		
Model	Affected order codes	Order code changes
FMB010	FMB010***** order codes with base Firmware	Update firmware

2021.08.13: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from August 13th, 2021. New production firmware version will be 03.27.07.Rev.00

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010_firmware_errata	
Change reasons	Old version: FMB010 03.25.18.Rev.08	New version: FMB010 03.27.07.Rev.00
Product release date	FMB010 base firmware version update 2021 August	

Affected products

Model	Affected order codes	Order code changes
FMB010	FMB010***** order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2021.01.01: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB010 device was updated in the factory from January 2021.

Change description

Change type	External/visual
	Top laser printing design changed
	Old version:

Detailed description



New version:

Change reasons	1. Updated Emark certificate number. 2. Added UKCA label. 3. Updated Teltonika brand to Teltonika Telematics.
Product release date	January 2021

Affected products

Model	Affected order codes	Order code changes
FMB010	FMB010*****	New casing

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

2020.01.22: Base firmware update

We would like to inform you about the base firmware update for FMB010 starting from January 22th, 2020. New production firmware version will be **03.25.15.Rev.01**.

Change description

Change type	Firmware update
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMB010_firmware_errata
Change reasons	Old version: FMB010 03.25.05.Rev.00 New version: FMB010 03.25.15.Rev.01
Product release date	FMB010 base firmware version update 2020 January 22th.

Affected products

Model	Affected order codes	Order code changes
FMB010	FMB010***** order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

2019.07.22: new no brand Eco friendly boxes

Effective September 2019, FMB010 trackers with no brand packaging will be shipped with a **new no brand eco-friendly box**.

Change description

Change type	Packaging Improved and more environmentally friendly packaging box	
Detailed description	Old single packaging version: <input type="checkbox"/>	New single packaging version: <input type="checkbox"/>
	Dimensions: 165 (W) x 145 (D) x 35 (H)	Dimensions: 175 (W) x 150 (D) x 35 (H)
	Old group packaging version: <input type="checkbox"/>	New group packaging version: <input type="checkbox"/>
	Dimensions: 355 (W) x 175 (D) x 60 (H)	Dimensions: 355 (W) x 175 (D) x 60 (H)
Change reasons	The new box is better for the environment	
Product release date	Devices with new packaging will be released in manufacturing from September with 2 months of transition period. Over this period devices with white packaging can be delivered as well as devices with the new eco boxes.	

Affected products

Model	Affected order codes	Order code changes
FMB001, FMB010, FMB100, FMB110, FMB120, FMB122, FMB125, FMB202, FMB204, FMB900, FMB920, FMB964, FMT100, FMB130, MTB100.	FMB001*****, FMB010*****, FMB100*****, FMB110*****, FMB120*****, FMB122*****, FMB125*****, FMB202*****, FMB204*****, FMB900*****, FMB920*****, FMB964*****, FMT100*****, FMB130*****, MTB100*****	No changes

Change impact

Risk assessment	No risk factors encountered with this change
-----------------	--

Suggested implementation plan Due to the new look of boxes we strongly recommend to update your marketing materials. Because of the new color of the packaging box, if necessary, update your branding materials (stickers, logo layouts).

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above