

# FMB910 Product Change Notifications

[Main Page](#) > [Basic Trackers](#) > [FMB910](#) > **FMB910 Product Change Notifications**

**Product change notifications (PCN)** is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMB910 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

□

## Contents

- [1 2024.05.13: Base firmware update](#)
- [2 2023.07.31: TOP and BOT casing changes](#)
- [3 2022.08.01: Base firmware update](#)
- [4 2021.09.24: Base firmware update](#)
- [5 2021.05.17: Base firmware update](#)
- [6 2021.04.16: Top Laser Printing Changes](#)
- [7 2021.03.03: Top Laser Printing Changes](#)
- [8 2021.03.02: Base firmware update](#)
- [9 2020.03.23: New MTB100 Case Design and Standard Pack Quantity \(SPQ\) Changes](#)
- [10 2019.07.22: new no brand Eco friendly boxes](#)

## 2024.05.13: Base firmware update

We would like to inform you about the base firmware update for FMB910 starting from June, 2024. New production firmware version will be **03.29.00.Rev.18**

### Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: <a href="#">FMB910 firmware errata</a>	
Change reasons	Old version:	New version:
Product release date	03.29.00.Rev.13	03.29.00.Rev.18
	FMB910 base firmware version update	
	2024 June	

### Affected products

Model	Affected order codes	Order code changes
FMB910	Order codes with base Firmware	New firmware version



### Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

## 2023.07.31: TOP and BOT casing changes

We would like to inform you, TOP and BOT casing part is updated for FMB910 starting from 2023 October.

### Change description

Change type	Internal/visual	
Detailed description	TOP and BOT casing parts inner design updated in order to manufacture devices in automatic assembly line	
Changes	TOP part:	BOT part:
	 TOP casing part: 1 and 2 - Added diagonally placed cutouts on both sides of the casing.	 BOT casing part: 1 and 2 - Added diagonally placed snap hooks on both sides.
Product release date	October 2023	

### Affected products

Models	Affected order codes	Order code changes
FMB910	All order codes	No changes for the order codes

### Change impact

Risk assessment	During the transition period clients might receive devices with old type casing.
Suggested implementation plan	No implementation plan needed

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika Telematics may accept that this change has been tacitly accepted and can implement the change as indicated above

## 2022.08.01: Base firmware update

We would like to inform you about the base firmware update for FMB910 starting from August 1st, 2022. New production firmware version will be 03.27.13.Rev.03

#### Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: <a href="https://wiki.teltonika-gps.com/view/FMB910_firmware_errata">https://wiki.teltonika-gps.com/view/FMB910_firmware_errata</a>	
Change reasons	Old version: FMB910 03.27.07.Rev.00	New version: FMB910 03.27.13.Rev.03
Product release date	FMB910 base firmware version update 2022 August	

#### Affected products

Model	Affected order codes	Order code changes
FMB910	FMB910***** order codes with base Firmware	Update firmware

## 2021.09.24: Base firmware update

We would like to inform you about the base firmware update for FMB910 starting from September 24th, 2021. New production firmware version will be **03.27.07.Rev.00**.

#### Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: <a href="https://wiki.teltonika-gps.com/view/FMB910_firmware_errata">https://wiki.teltonika-gps.com/view/FMB910_firmware_errata</a>	
Change reasons	Old version: 03.25.18.Rev.08	New version: 03.27.07.Rev.00
Product release date	FMB910 base firmware version update 2021 September.	

#### Affected products

Model	Affected order codes	Order code changes
FMB910	FMB910***** order codes with base Firmware	Update firmware

#### Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

## 2021.05.17: Base firmware update

We would like to inform you about the base firmware update for FMB910 starting from May 17th, 2021. New production firmware version will be **03.25.18.Rev.08**.

### Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: <a href="https://wiki.teltonika-gps.com/view/FMB910_firmware_errata">https://wiki.teltonika-gps.com/view/FMB910_firmware_errata</a>	
Change reasons	Old version: 03.25.18.Rev.05	New version: 03.25.18.Rev.08
Product release date	FMB910 base firmware version update 2021 May.	

### Affected products

Model	Affected order codes	Order code changes
FMB910	FMB910***** order codes with base Firmware	Update firmware

### Change impact


Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

## 2021.04.16: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB910 device was updated in the factory in April 2021.

### Change description

Change type	External/visual Top laser printing design changed
Detailed description	Old version:



Change reasons	1. Added UKCA label. 2. Added ANATEL label and certificate number.
----------------	-----------------------------------------------------------------------

Product release date April 2021

### Affected products

Model	Affected order codes	Order code changes
FMB910	FMB910*****	New laser engraving

### Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

# 2021.03.03: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMB910 device was updated in the factory in March 2021.

### Change description

Change type External/visual  
Top laser printing design changed

New version:



Detailed description Old version:

Change reasons 1. Updated Emark certificate number.  
Product release date March 2021

### Affected products

Model	Affected order codes	Order code changes
FMB910	FMB910*****	New laser engraving

### Change impact

Risk assessment No risk factors encountered with this change  
Suggested implementation Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process  
plan

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

# 2021.03.02: Base firmware update

We would like to inform you about the base firmware update for FMB910 starting from March 03th, 2021. New production firmware version will be **03.25.18.Rev.05**.

### Change description

Change type Firmware update  
Detailed description Key improvements from last production firmware are listed in errata: [https://wiki.teltonika-gps.com/view/FMB910\\_firmware\\_errata](https://wiki.teltonika-gps.com/view/FMB910_firmware_errata)  
Old version: 03.25.18.Rev.02  
New version: 03.25.18.Rev.05  
Change reasons FMB910 base firmware version update  
Product release date 2021 March.

### Affected products

Model	Affected order codes	Order code changes
FMB910	FMB910***** order codes with base Firmware	Update firmware

### Change impact

Risk assessment Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically  
Suggested implementation plan If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.

# 2020.03.23: New MTB100 Case Design and Standard Pack Quantity (SPQ) Changes

Effective April 2020, MTB100 trackers will be shipped with **new case design**

Standard Pack Quantity (SPQ) for MTB100 will also be changed from April.

## Change description

Change type	Case	
	New case design	
Detailed description	Old version: <input type="checkbox"/>	New version: <input type="checkbox"/>
	<b>Dimensions:</b> 79 mm x 43 mm x 27,5 mm	<b>Dimensions:</b> 78,37 mm x 42,57 mm x 21,3 mm
Change type	Packaging	
Detailed description	Changed Standard Pack Quantity (SPQ) from 10 to 20	
Change reasons	The new MTB100 case is smaller and allows for higher Standard Pack Quantity (SPQ)	
Product release date	April 2020	

## Affected products

Model	Affected order codes	Order code changes
MTB100	MTB10093IN01 MTB10093INC6	SPQ 20

## Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

## Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

# 2019.07.22: new no brand Eco friendly boxes

Effective September 2019, MTB100 trackers with no brand packaging will be shipped with a **new no brand eco-friendly box**.

## Change description

Change type	Packaging	
	Improved and more environmentally friendly packaging box	
	Old single packaging version: <input type="checkbox"/>	New single packaging version: <input type="checkbox"/>
Detailed description	<b>Dimensions:</b> 165 (W) x 145 (D) x 35 (H)	<b>Dimensions:</b> 175 (W) x 150 (D) x 35 (H)
	Old group packaging version: <input type="checkbox"/>	New group packaging version: <input type="checkbox"/>
	<b>Dimensions:</b> 355 (W) x 175 (D) x 60 (H)	<b>Dimensions:</b> 355 (W) x 175 (D) x 60 (H)
Change reasons	The new box is better for the environment	
Product release date	Devices with new packaging will be released in manufacturing from September with 2 months of transition period. Over this period devices with white packaging can be delivered as well as devices with the new eco boxes.	

## Affected products

Model	Affected order codes	Order code changes
FMB001, FMB010, FMB100, FMB110, FMB120, FMB122, FMB125, FMB202, FMB204, FMB900, FMB920, FMB964, FMT100, FMB130, MTB100.	FMB001*****, FMB010*****, FMB100*****, FMB110*****, FMB120*****, FMB122*****, FMB125*****, FMB202*****, FMB204*****, FMB900*****, FMB920*****, FMB964*****, FMT100*****, FMB130*****, MTB100*****	No changes

## Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to the new look of boxes we strongly recommend to update your marketing materials. Because of the new color of the packaging box, if necessary, update your branding materials (stickers, logo layouts).

## Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above