

# FMC001 Product Change Notifications

[Main Page](#) > [OBD Trackers](#) > [FMC001](#) > **FMC001 Product Change Notifications**

**Product change notifications (PCN)** is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMC001 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).

□


## Contents

- [1 2023.04.21: Top Laser Printing Changes](#)
- [2 2022.08.16: Base firmware update](#)
- [3 2022.02.09: Base firmware update](#)
- [4 2021.11.15: Base firmware update](#)

## 2023.04.21: Top Laser Printing Changes

We would like to inform you, that laser printing of the FMC001 device was updated in the factory from April 2023.

### Change description

Change type	External/visual	
Detailed description	Top laser printing design was changed, additional IMEI/SN QR sticker on the top part of the casing was added	
	New version: 	
Change reasons	In order to improve the effectiveness of QR scanning additional IMEI/SN QR sticker on the top part of casing was added	
Product release date	April 2023	

### Affected products

Model	Affected order codes	Order code changes
FMC001	FMC001 *****	New casing

### Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process

### Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above

## 2022.08.16: Base firmware update

We would like to inform you about the base firmware update for FMC001 starting from August 16th, 2022. New production firmware version will be **03.27.13.Rev.03**

### Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: <a href="https://wiki.teltonika-gps.com/view/FMC001_firmware_errata">https://wiki.teltonika-gps.com/view/FMC001_firmware_errata</a>	
	Old version: FMC001 03.27.12.Rev.00	New version: FMC001 03.27.13.Rev.03
Change reasons	FMC001 base firmware version update	
Product release date	2022 August	

### Affected products

Model	Affected order codes	Order code changes
FMC001	FMC001***** order codes with base Firmware	Update firmware

### Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	Current CE and E-mark certificates are valid. Also, current purchase codes remain the same.	
	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

## 2022.02.09: Base firmware update

We would like to inform you about the base firmware update for FMC001 starting from February 9th, 2022. The new production firmware version will be **03.27.12.Rev.00**

### Change description

Change type	Hardware and Firmware change	
Detailed description	OBD data processor of an alternative manufacturer is introduced in the production process. Key improvements from last production firmware are listed in errata: <a href="https://wiki.teltonika-gps.com/view/FMC001_firmware_errata">https://wiki.teltonika-gps.com/view/FMC001_firmware_errata</a>	
	Old version: FMC001 03.27.07.Rev.00	New version: FMC001 03.27.12.Rev.00
Change reasons	Response to the global situation in component market and streamlining our product portfolio.	
Product release date	2022 February	

### Affected products

Model	Affected order codes	Order code changes
FMC001	FMC001***** order codes with base Firmware	OBD processor analog

### Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	Current CE and E-mark certificates are valid. Also, current purchase codes remain the same.	
	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

## 2021.11.15: Base firmware update

We would like to inform you about the base firmware update for FMC001 starting from December 2021. New production firmware version will be **03.27.07.Rev.00**

### Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: <a href="https://wiki.teltonika-gps.com/view/FMB_firmware_errata">https://wiki.teltonika-gps.com/view/FMB_firmware_errata</a>	
	Old version: FMC001 03.25.15.Rev.88	New version: FMC001 03.27.07.Rev.00
Change reasons	FMC001 base firmware version update	
Product release date	2021 December	

### Affected products

Model	Affected order codes	Order code changes
FMC001	FMC001***** order codes with base Firmware	Update firmware

### Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	