

FMM003 firmware errata

[Main Page](#) > [OBD Trackers](#) > [FMM003](#) > **FMM003 firmware errata**



Contents

- [1 Introduction](#)
- [2 Firmware versioning](#)
- [3 Firmware versions](#)

Introduction

We are always improving our devices performance, stability and reliability. That's why Teltonika is one of the leading GNSS trackers manufacturers in the world.

This document describes **FMC003 and FMM003** devices firmware improvements, changes, new features implementations as well as current firmware release version.

FIRMWARE VERSION	SUPPORTED HARDWARE
03.28.XX	FMC003, FMM003

Firmware versioning

- Structure

FMB(T).VER.[XX].[YY].[ZZ].Rev.[##]_[ID###]

- Syntax description
 - XX – major FW version.
 - YY – branch number, shows major changes in firmware, i.e. new module support added or new major feature added.
 - ZZ – major changes like bigger fixes, improvements and new features addition.
 - ## – minor changes like small fixes and improvements.
 - ID[###] – Spec ID KEY – Specific clients FW changes.

Firmware versions

FIRMWARE VERSION	RELEASE DATE	CHANGES
03.28.03.Rev.97	2023.04.12	• Performance improvements and bug fixes
03.28.03.Rev.94	2022.08.30	• Added OEM Reset button • FMM003 BG95-M6 modem support • Port COLD/WARM/HOT fix tests via SMS
03.28.00.Rev.107	2022.06.28	• Added FMC003 support • Added FMM003 support • Initial release