

FMM125 Product Change Notifications

[Main Page](#) > [Professional Trackers](#) > [FMM125](#) > **FMM125 Product Change Notifications**

Product change notifications (PCN) is the way of informing customers of upcoming changes related to Teltonika products. This includes outward appearance adjustments, hardware improvements, firmware changes, changes to package contents, etc. This page stores information regarding changes to the FMM125 tracking device. Below you will find a list of both upcoming and already implemented changes sorted from newest to oldest (top to bottom).



Contents

- [1 2023.02.02: Changes in side frame for the battery placement](#)
- [2 2022.08.17: Base firmware update](#)
- [3 2021.08.19: Base firmware update](#)
- [4 2021.03.16: Base firmware update](#)
- [5 2019.11.28: Top Device Marking Changes](#)

2023.02.02: Changes in side frame for the battery placement

We would like to inform you that the side frame for the battery placement is included, helping to determine the exact location of the battery. Also, minor design changes are made to improve both case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices. The updates in the factory are being implemented in February, 2023.

Change description

Change type	Internal	
Detailed description	The side frame for the battery placement is included, helping to determine the exact location of the battery. Also, minor design changes are made to improve both case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices.	
Change reasons	The battery placement is improved with a side frame, helping to determine the exact location of the battery. Minor design changes are made for case production and case assembly. These changes affect FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, and FMM150 devices.	
Product release date	February, 2023	
Affected products		
Model	Affected order codes	Order code changes
FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, FMM150	FMB110, FMB120, FMB122, FMB125, FMC125, FMM125, FMB130, FMC130, FMM130, FMB140, FMB150, FMC150, FMM150 all codes	Updated the battery placement with the side frame as well as minor design changes for case production and assembly
Change impact		
Risk assessment	During the transition period clients might receive devices with old case design used in manufacture	
Suggested implementation plan	Due to changes in device appearance we strongly recommend to contact your customs agent with our change log information, to avoid any unexpected delays in customs clearance process.	

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has tactically accepted and can implement the change as indicated above.

2022.08.17: Base firmware update

We would like to inform you about the base firmware update for FMM125 starting from August 17th, 2022. New production firmware version will be **03.27.14.Rev.00**

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMM125_firmware_errata	
	Old version:	New version:
	-	FMM125 03.27.14.Rev.00
Change reasons	FMM125 base firmware version update	
Product release date	2022 August	

Affected products

Model	Affected order codes	Order code changes
FMM125	FMM125***** order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2021.08.19: Base firmware update

We would like to inform you about the base firmware update for FMM125 starting from August 19th, 2021. New production firmware version will be **03.27.07.Rev.00**

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMM125_firmware_errata	
	Old version:	New version:
	FMM125 03.27.04.Rev.01	FMM125 03.27.07.Rev.00
Change reasons	FMM125 base firmware version update	
Product release date	2021 August	

Affected products

Model	Affected order codes	Order code changes
FMM125	FMM125***** order codes with base Firmware	Update firmware

Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically. During the transition period clients might receive devices with previous Firmware version used in manufacture.	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2021.03.16: Base firmware update

We would like to inform you about the base firmware update for FMM125 starting from March 16th, 2021. The new production firmware version will be **03.27.04.Rev.01**.

Change description

Change type	Firmware update	
Detailed description	Key improvements from last production firmware are listed in errata: https://wiki.teltonika-gps.com/view/FMM125_firmware_errata	
	Old version:	New version:
	FMM125 03.25.10.Rev.175	FMM125 03.27.04.Rev.01
Change reasons	FMM125 base firmware version update	
Product release date	2021 March 16th.	

Affected products

Model	Affected order codes	Order code changes
FMM125	FMM125***** order codes with base Firmware	Update firmware



Change impact

Risk assessment	Client's special firmware versions or order codes with special firmware will not be updated to latest base firmware automatically	
Suggested implementation plan	If you are using special firmware version and would like an upgrade to new features of latest base firmware, please contact your Teltonika sales manager.	

2019.11.28: Top Device Marking Changes

We would like to inform you, that tampography of the FMM125 device was updated to engraving in the factory.

Change description

Change type	External/visual	
Detailed description	Device marking changed from tampography to laser printing. Information provided on module will remain the same	
Change reasons	Old Version: 	New Version: 
Product release date	Planned date: 2019 December	

Affected products

Model	all codes with standard marking	Order code changes
FMM125	FMM125*****	No changes

Change impact

Risk assessment	No risk factors encountered with this change
Suggested implementation plan	No implementation plan needed

Acknowledgement of PCN receipt

If no feedback is received within two weeks after the issue date of this notification - Teltonika may accept that this change has been tacitly accepted and can implement the change as indicated above