

FMM230 firmware errata

[Main Page](#) > [Advanced Trackers](#) > [FMC230](#) > **FMM230 firmware errata**

□

Contents

- [1 Introduction](#)
- [2 Firmware versioning](#)
- [3 Firmware versions](#)

Introduction

We are always improving our devices performance, stability and reliability. That's why Teltonika is one of the leading GNSS trackers manufacturers in the world. This document describes **FMCXXX, FMUXXX, FMMXXX platform** devices firmware improvements, changes, new features implementations as well as current firmware release version.

FIRMWARE VERSION	SUPPORTED HARDWARE
03.25.XX	FMC1YX, FMU1YX, FMM1YX
03.27.XX	FMB0YX, FMB9X0, FMB96X, FMB1YX, FMU1YX, FMM1YX, FMC1YX, FMM001, FMC001, FM30XY, FMB2YX, FMT100

Firmware versioning

- Structure

FMB(T).VER.[XX].[YY].[ZZ].Rev.[##]_[ID###]

- Syntax description
 - XX - major FW version.
 - YY - branch number, shows major changes in firmware, i.e. new module support added or new major feature added.
 - ZZ - major changes like bigger fixes, improvements and new features addition.
 - ## - minor changes like small fixes and improvements.
 - ID[###] - Spec ID KEY - Specific clients FW changes.

Firmware versions

FIRMWARE VERSION	RELEASE DATE	CHANGES
-------------------------	---------------------	----------------

03.27.13.Rev.03 (recommended for FMB230, FMB225, FMB240, FMM230)	2022.09.12	<ul style="list-style-type: none"> • Improved system stability and fixed general bugs • Manufacture testing improvements
03.27.13.Rev.57 (recommended for FMC225)	2022.05.11	<ul style="list-style-type: none"> • Added SMS via LTE support for hardware`s with SLM320 modules • Added Jamming support for FMC225 hardware • Fixed NITZ time synchronization with SLM320 modules • Fixed connection to operator issue • Improved system stability and fixed general bugs
03.27.12.Rev.00 (recommended for FMM230, FMB230, FMB225, FMB240)	2022.02.17	<ul style="list-style-type: none"> • Added FMM230, FMC230, FMC225, FMB230, FMB225, FMB240 support • Fixed manual frequency bands configuration for FMMx30 devices • Improved system stability and fixed general bugs