

# FTC921 firmware change log

[Main Page](#) > [Basic Trackers](#) > [FTC921](#) > **FTC921 firmware change log**

□

## Contents

- [1 Introduction](#)
- [2 Firmware versioning](#)
- [3 Firmware versions](#)

## Introduction

We are always improving our device's performance, stability, and reliability. That's why Teltonika is one of the leading GNSS trackers manufacturers in the world.

This document describes **FTCXXX platform** devices firmware improvements, changes, new features implementations as well as current firmware release version.

## Firmware versioning

- Structure

[X].[YY].[Z].rc.[##]

- Syntax description
  - X - major FW version.
  - YY - branch number, shows major changes in firmware, i.e. new module support added or new major feature added.
  - ZZ - major changes like bigger fixes, improvements and new features addition.
  - ## - minor changes like small fixes and improvements.

## Firmware versions

<b>FIRMWARE VERSION</b>	<b>SUPPORTED HARDWARE</b>	
<b>00.2X.Y-rc.Z</b>	FTC9XY, FTC8XY	

  

<b>FIRMWARE VERSION</b>	<b>RELEASE DATE</b>	<b>CHANGES</b>
<b>0.26.0-rc.6</b>	<b>2023-07-20</b>	<ul style="list-style-type: none"><li>• SMS sending timeout fix</li><li>• modem IMEI recognition in roaming mode fix</li></ul>
<b>0.26.0-rc.5</b>	<b>2023-07-04</b>	<ul style="list-style-type: none"><li>• SMS command "setparam" stability improvements</li></ul>
<b>0.26.0-rc.4</b>	<b>2023-06-28</b>	<ul style="list-style-type: none"><li>• accelerometer initialization improvements</li></ul>
<b>0.26.0-rc.3</b>	<b>2023-06-26</b>	<ul style="list-style-type: none"><li>• fatal SMS with unsupported symbol fix</li></ul>
<b>0.26.0-rc.2</b>	<b>2023-06-20</b>	<ul style="list-style-type: none"><li>• modem stability improvements</li></ul>

<b>0.26.0-rc.1</b>	<b>2023-06-08</b>	<ul style="list-style-type: none"> <li>• <b>NEW</b> added the SMS "getrecord"</li> <li>• <b>NEW</b> added the SMS "web_connect"</li> <li>• <b>NEW</b> added the SMS "getinfo"</li> <li>• <b>NEW</b> added accelerometer test command</li> <li>• <b>NEW</b> added roaming mode change event</li> <li>• accelerometer data validation improvements</li> <li>• record sending improvements</li> <li>• ignition check spam without timesync fix</li> <li>• <b>NEW</b> added SMS password</li> <li>• <b>NEW</b> added the SMS "extformat"</li> <li>• <b>NEW</b> added the SMS "getver"</li> </ul>
<b>0.22.0-rc.4</b>	<b>2023-05-26</b>	<ul style="list-style-type: none"> <li>• Power management (sleep) improvements</li> <li>• Subsequent connection to server failure timeout increase feature added</li> <li>• DOUT stability improvements</li> </ul>
<b>0.22.0-rc.1</b>	<b>2023-05-17</b>	<ul style="list-style-type: none"> <li>• initial FTC881 release</li> </ul>