

FTC961 firmware change log

[Main Page](#) > [Basic Trackers](#) > [FTC961](#) > **FTC961 firmware change log**

□

Contents

- [1 Introduction](#)
- [2 Firmware versioning](#)
- [3 Firmware versions](#)

Introduction

We are always improving our device's performance, stability, and reliability. That's why Teltonika is one of the leading GNSS trackers manufacturers in the world.

This document describes **FTCXXX platform** devices firmware improvements, changes, new features implementations as well as current firmware release version.

Firmware versioning

- Structure

[X].[YY].[Z].rc.[##]

- Syntax description
 - X - major FW version.
 - YY - branch number, shows major changes in firmware, i.e. new module support added or new major feature added.
 - ZZ - major changes like bigger fixes, improvements and new features addition.
 - ## - minor changes like small fixes and improvements.

Firmware versions

FIRMWARE VERSION	SUPPORTED HARDWARE	
00.2X.Y-rc.Z	FTC9XY, FTC8XY	

FIRMWARE VERSION	RELEASE DATE	CHANGES
0.26.0-rc.6	2023-07-20	<ul style="list-style-type: none">• SMS sending timeout fix• modem IMEI recognition in roaming mode fix
0.26.0-rc.5	2023-07-04	<ul style="list-style-type: none">• SMS command "setparam" stability improvements
0.26.0-rc.4	2023-06-28	<ul style="list-style-type: none">• accelerometer initialization improvements
0.26.0-rc.3	2023-06-26	<ul style="list-style-type: none">• fatal SMS with unsupported symbol fix
0.26.0-rc.2	2023-06-20	<ul style="list-style-type: none">• modem stability improvements

0.26.0-rc.1	2023-06-08	<ul style="list-style-type: none"> • NEW added the SMS "getrecord" • NEW added the SMS "web_connect" • NEW added the SMS "getinfo" • NEW added accelerometer test command • NEW added roaming mode change event • accelerometer data validation improvements • record sending improvements • ignition check spam without timesync fix • NEW added SMS password • NEW added the SMS "extformat" • NEW added the SMS "getver"
0.22.0-rc.4	2023-05-26	<ul style="list-style-type: none"> • Power management (sleep) improvements • Subsequent connection to server failure timeout increase feature added • DOUT stability improvements
0.22.0-rc.1	2023-05-17	<ul style="list-style-type: none"> • initial FTC961 release