

# January 22 Change Log

[Teltonika wiki change log](#) > **January 22 Change Log**

## GENERAL INFORMATION

1. Updated DUAL CAM web page – a new table was added for scenario triggered to get a photo:

[https://wiki.teltonika-gps.com/view/Teltonika\\_DualCam#Image\\_sending\\_trigger](https://wiki.teltonika-gps.com/view/Teltonika_DualCam#Image_sending_trigger)

## AVL/PARAMETER ID UPDATES

2. Updated parameter list for OBD devices. Added accelerometer features parameters, split Bluetooth® parameters into two sections: Bluetooth® and Bluetooth® 4.0, added iBeacon list parameters. Also updated OBD parameters template with OEM Total Mileage and OEM Fuel Level parameters:

[https://wiki.teltonika-gps.com/view/FMB001\\_Parameter\\_list](https://wiki.teltonika-gps.com/view/FMB001_Parameter_list)

## CREATED PAGES

3. Created new pages on new devices FMX2XY (IP67):

<https://wiki.teltonika-gps.com/view/FMB230>

<https://wiki.teltonika-gps.com/view/FMM230>

<https://wiki.teltonika-gps.com/view/FMC230>

<https://wiki.teltonika-gps.com/view/FMB240>

<https://wiki.teltonika-gps.com/view/FMC225>

<https://wiki.teltonika-gps.com/view/FMB225>