

October Change Log

[Teltonika wiki change log](#) > **October Change Log**

AVL/PARAMETER ID UPDATES

1. Description column of Dallas Temperature x parameters have been updated:

https://wiki.teltonika-gps.com/view/FMB640_Teltonika_Data_Sending_Parameters_ID

https://wiki.teltonika-gps.com/view/FMC640_Teltonika_Data_Sending_Parameters_ID

https://wiki.teltonika-gps.com/view/FMM640_Teltonika_Data_Sending_Parameters_ID

2. FMx640 AVL ID list updated, new value description according to ISO 16844 document added for Driver ½ Time Related States elements:

https://wiki.teltonika-gps.com/view/FMB640_Teltonika_Data_Sending_Parameters_ID#Tachograph_data_elements

CERTIFICATES

3. RoHS3 certificate added for FMB910 device:

https://wiki.teltonika-gps.com/view/FMB910_RoHS

FIRMWARE ERRATA / CONFIGURATOR

4. Firmware errata update for FMB640:

https://wiki.teltonika-gps.com/view/FMB640_Product_Change_Notifications

5. Firmware errata update for FMC640:

https://wiki.teltonika-gps.com/view/FMC640_Product_Change_Notifications

6. Firmware errata update for FMM640:

https://wiki.teltonika-gps.com/view/FMM640_Product_Change_Notifications

7. FMB640 errata updated, a notification about downgrading to older versions added:

https://wiki.teltonika-gps.com/view/FMB640_firmware_errata

8. Updated FMB140 firmware errata:

https://wiki.teltonika-gps.com/view/FMB140_firmware_errata

9. Update configurator versions for FMB140, FMU1YX/FMC1YX/FMM1YX, FMB640 products:

https://wiki.teltonika-gps.com/view/Teltonika_Configurator_versions

PRODUCT CHANGE NOTIFICATIONS (PCN)

10. FMB640 Product Change Notifications update:

https://wiki.teltonika-gps.com/view/FMB640_Product_Change_Notifications#2020.10.11%3A_Base_firmware_update

11. FMC640 Product Change Notifications update:

https://wiki.teltonika-gps.com/view/FMC640_Product_Change_Notifications#2020.10.11%3A_Base_firmware_update

12. FMM640 Product Change Notifications update:

https://wiki.teltonika-gps.com/view/FMM640_Product_Change_Notifications#2020.10.11%3A_Base_firmware_update

13. Added FMB140 base firmware update PCN:

https://wiki.teltonika-gps.com/view/FMB140_Product_Change_Notifications

14. FMB140 and FMB640 configurator download links have been updated:

https://wiki.teltonika-gps.com/view/Teltonika_Configurator_versions

CREATED PAGES

15. New page created FMC640 BLE module update:

https://wiki.teltonika-gps.com/view/FMC640_BLE_module_update

16. New page created FMM640 BLE module update:

https://wiki.teltonika-gps.com/view/FMM640_BLE_module_update

17. Added connection and configuration description of the sensor Technoton DUT-E S7 Fuel Level Sensor:

https://wiki.teltonika-gps.com/view/Technoton_DUT-E_S7_Fuel_Level_Sensor

18. Added connection and configuration description of the sensor Technoton DFM D S7 Differential Fuel Flow Meter:

https://wiki.teltonika-gps.com/view/Technoton_DFM_D_S7_Differential_Fuel_Flow_Meter

19. Added connection and configuration description of the sensor Technoton GNOM DDE/DP S7 Axle Load Sensors:

https://wiki.teltonika-gps.com/view/Technoton_GNOM_DDE/DP_S7_Axle_Load_Sensors

PROMOTIONAL MATERIAL

20. Updated FMC001 Promotional Material:

https://wiki.teltonika-gps.com/view/FMC001_Promotional_Material

21. Updated FMM001 Promotional Material:

https://wiki.teltonika-gps.com/view/FMM001_Promotional_Material