TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Cars | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars



256) CITROEN C4 CACTUS	year: **2014=>**	program № **12184**	from **2020-03-24**
257) CITROEN C4 GRAND PICASSO (EXCLUSIVE) (Keyless)	year: **2013=>**	program № **11495**	from **2020-03-24**
258) CITROEN C4 GRAND PICASSO (INTENSIVE) (Keyless)	year: **2013=>**	program № **11495**	from **2020-03-24**
259) CITROEN C4 PICASSO (EXCLUSIVE) (Keyless)	year: **2013=>**	program № **11495**	from **2020-03-24**
260) CITROEN C4 PICASSO (INTENSIVE) (Keyless)	year: **2013=>**	program № **11495**	from **2020-03-24**
261) CITROEN C4 PICASSO	year: **2007=>**	program № **11143**	from **2020-03-24**
262) CITROEN C4 PICASSO	year: **2007=>**	program № **11193**	from **2020-03-24**
263) CITROEN C5	year: **2011=>**	program № **13451**	from **2020-10-27**
264) CITROEN C5	year: **2008=>**	program № **11143**	from **2020-03-24**
265) CITROEN C5	year: **2008=>**	program № **11193**	from **2020-03-24**
266) CITROEN C5	year: **2008=>**	program № **11192**	from **2017-09-01**
267) CITROEN C5	year: **2004=>**	program № **11143**	from **2020-03-24**
268) CITROEN C5	year: **2004=>**	program № **11193**	from **2020-03-24**
269) CITROEN C5 AIRCROSS	year: **2019=>**	program № **13172**	from **2020-04-28**
270) CITROEN C6	year: **2005=>**	program № **11143**	from **2017-09-01**
271) CITROEN C6	year: **2005=>**	program № **11193**	from **2017-09-01**
272) CITROEN C8	year: **2002=>**	program № **11143**	from **2017-09-01**
273) CITROEN C8	year: **2002=>**	program № **11193**	from **2017-09-01**
274) CITROEN DS3	year: **2010=>**	program № **11143**	from **2017-09-01**
275) CITROEN DS3	year: **2010=>**	program № **11193**	from **2017-09-01**
276) CITROEN DS4	year: **2011=>**	program № **12298**	from **2020-03-24**
277) CITROEN DS4 CROSSBACK	year: **2016=>**	program № **12317**	from **2020-03-24**
278) CITROEN DS5	year: **2015=>**	program № **12315**	from **2020-03-24**
279) CITROEN DS5	year: **2012=>**	program № **14262**	from **2022-06-23**
280) CITROEN JUMPER (EURO 6)	year: **2017=>**	program № **12314**	from **2020-05-18**
281) CITROEN JUMPER (EURO 5 PLUS)	year: **2014=>**	program № **13167**	from **2020-04-27**
282) CITROEN JUMPER	year: **2011=>**	program № **13168**	from **2020-04-27**
283) CITROEN JUMPER (RussianMarket)	year: **2011=>**	program № **11129**	from **2017-09-01**
284) CITROEN JUMPER	year: **2006=>**	program № **11129**	from **2017-09-01**
285) CITROEN JUMPY	year: **2016=>**	program № **13169**	from **2020-04-27**
286) CITROEN JUMPY	year: **2007=>**	program № **11143**	from **2017-09-01**
287) CITROEN JUMPY	year: **2007=>**	program № **11193**	from **2017-09-01**
288) CITROEN NEMO	year: **2008=>**	program № **12966**	from **2020-01-15**
289) CITROEN SPACETOURER	year: **2017=>**	program № **11949**	from **2020-03-24**
290) CITROEN XSARA PICASSO	year: **2004=>**	program № **11292**	from **2017-09-01**
291) CUPRA FORMENTOR (KM)	year: **2021=>**	program № **13486**	from **2022-01-14**

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars



| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars



759) KIA CEED (ED) — year: **2009=>** — program № **11236** — from **2017-09-01**

760) KIA CERATO (IV) — year: **2018=>** — program № **12642** — from **2019-04-17**

761) KIA CERATO (III) (Keyless) — year: **2013=>** — program № **11344** — from **2017-09-01**

762) KIA CERATO (III) — year: **2013=>** — program № **11412** — from **2017-09-01**

763) KIA CERATO (II) — year: **2010=>** — program № **11479** — from **2017-09-01**

764) KIA K3 (BD) (KoreanMarket) — year: **2018=>** — program № **13559** — from **2021-03-18**

765) KIA K5 (DL3) (Hybrid) — year: **2021=>** — program № **13671** — from **2021-05-11**

766) KIA K5 (DL3) (Keyless) — year: **2020=>** — program № **13232** — from **2020-06-18**

767) KIA K7 (YG) (KoreanMarket) — year: **2020=>** — program № **13226** — from **2020-08-24**

768) KIA K900 (RJ) — year: **2018=>** — program № **12646** — from **2020-06-19**

769) KIA MAGENTIS — year: **2009=>** — program № **11236** — from **2017-09-01**

770) KIA MOHAVE (HM2) — year: **2018=>** — program № **12645** — from **2021-07-16**

771) KIA MOHAVE (HM) (Keyless) — year: **2011=>** — program № **11478** — from **2017-09-01**

772) KIA MOHAVE (HM) — year: **2009=>** — program № **11232** — from **2017-09-01**

773) KIA MORNING (JA) (BETA) — year: **2018=>** — program № **13313** — from **preliminary**

774) KIA NIRO (DE) (Hybrid) — year: **2020=>** — program № **13285** — from **2020-08-18**

775) KIA NIRO (DE) (Hybrid) — year: **2016=>** — program № **11813** — from **2020-02-03**

776) KIA OPIRUS — year: **2004=>** — program № **11234** — from **2017-09-01**

777) KIA OPTIMA (JF) (Keyless) — year: **2018=>** — program № **13283** — from **2020-08-17**

778) KIA OPTIMA (JF) (Keyless) — year: **2016=>** — program № **12367** — from **2019-09-20**

779) KIA OPTIMA (JF) — year: **2016=>** — program № **12368** — from **2019-09-20**

780) KIA OPTIMA (TF) (Keyless) (SlovakianMarket) — year: **2014=>** — program № **11344** — from **2017-09-01**

781) KIA OPTIMA (TF) (Keyless) — year: **2014=>** — program № **11344** — from **2017-09-01**

782) KIA OPTIMA (TF) — year: **2014=>** — program № **11564** — from **2017-09-01**

783) KIA OPTIMA (TF) (Keyless) — year: **2012=>** — program № **11344** — from **2017-09-01**

784) KIA OPTIMA (TF) (Hybrid) — year: **2012=>** — program № **14184** — from **2022-04-01**

785) KIA PICANTO (JA) — year: **2021=>** — program № **13568** — from **2021-03-08**

786) KIA PICANTO GT LINE — year: **2018=>** — program № **12177** — from **2018-01-02**

787) KIA PICANTO (TA) — year: **2014=>** — program № **11299** — from **2017-09-01**

788) KIA PICANTO (TA) (Keyless) — year: **2011=>** — program № **11299** — from **2017-09-01**

789) KIA PROCEED (CD) — year: **2019=>** — program № **13284** — from **2020-08-17**

790) KIA QUORIS (Keyless) — year: **2015=>** — program № **11413** — from **2017-09-01**

791) KIA QUORIS (Keyless) — year: **2013=>** — program № **11413** — from **2017-09-01**

792) KIA RAY — year: **2018=>** — program № **13557** — from **2021-03-15**

793) KIA RIO — year: **2020=>** — program № **13277** — from **2020-08-12**

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars



794) KIA RIO (Keyless) — year: **2020=>** — program № **13321** — from **2020-08-28**

795) KIA RIO — year: **2017=>** — program № **11979** — from **2017-09-01**

796) KIA RIO (RussianMarket) — year: **2017=>** — program № **12194** — from **2018-02-01**

797) KIA RIO (Hatchback) (RussianMarket) (Keyless) — year: **2016=>** — program № **11416** — from **2017-09-01**

798) KIA RIO (Sedan) (RussianMarket) (Keyless) — year: **2016=>** — program № **11416** — from **2017-09-01**

799) KIA RIO (Hatchback) (RussianMarket) — year: **2016=>** — program № **11479** — from **2017-09-01**

800) KIA RIO (Sedan) (RussianMarket) — year: **2016=>** — program № **11479** — from **2017-09-01**

801) KIA RIO (Sedan) (RussianMarket) — year: **2016=>** — program № **11479** — from **2017-09-01**

802) KIA RIO (Hatchback) (RussianMarket) — year: **2016=>** — program № **11479** — from **2017-09-01**

803) KIA RIO (Sedan) (RussianMarket) (Keyless) — year: **2013=>** — program № **11416** — from **2017-09-01**

804) KIA RIO (Hatchback) (RussianMarket) (Keyless) — year: **2013=>** — program № **11416** — from **2017-09-01**

805) KIA RIO (Sedan) (RussianMarket) — year: **2013=>** — program № **11479** — from **2017-09-01**

806) KIA RIO (Hatchback) (RussianMarket) — year: **2013=>** — program № **11479** — from **2017-09-01**

807) KIA RIO (Sedan) (RussianMarket) — year: **2013=>** — program № **11479** — from **2017-09-01**

808) KIA RIO (Hatchback) (RussianMarket) — year: **2013=>** — program № **11479** — from **2017-09-01**

809) KIA RIO — year: **2011=>** — program № **11244** — from **2017-09-01**

810) KIA RIO — year: **2005=>** — program № **11236** — from **2017-09-01**

811) KIA SORENTO (MQ4) (Hybrid) — year: **2021=>** — program № **13431** — from **2020-12-02**

812) KIA SORENTO (MQ4) — year: **2021=>** — program № **13581** — from **2021-03-10**

813) KIA SORENTO (UM) (Keyless) — year: **2018=>** — program № **13268** — from **2020-07-16**

814) KIA SORENTO (UM) — year: **2015=>** — program № **11621** — from **2021-05-21**

815) KIA SORENTO (XM) (Keyless) — year: **2012=>** — program № **11411** — from **2017-09-01**

816) KIA SORENTO (XM) — year: **2012=>** — program № **11411** — from **2017-09-01**

817) KIA SORENTO (XM) — year: **2010=>** — program № **11231** — from **2017-09-01**

818) KIA SORENTO PRIME (UM) — year: **2015=>** — program № **12285** — from **2018-04-17**

819) KIA SOUL — year: **2020=>** — program № **12794** — from **2019-09-03**

820) KIA SOUL (Keyless) — year: **2014=>** — program № **11498** — from **2017-12-05**

821) KIA SOUL — year: **2014=>** — program № **11514** — from **2017-12-05**

822) KIA SOUL — year: **2012=>** — program № **11343** — from **2017-09-01**

823) KIA SOUL (Keyless) — year: **2012=>** — program № **11481** — from **2017-09-01**

824) KIA SPORTAGE — year: **2019=>** — program № **12433** — from **2021-07-16**

825) KIA SPORTAGE — year: **2016=>** — program № **11812** — from **2020-04-29**

826) KIA SPORTAGE (Keyless) — year: **2016=>** — program № **11669** — from **2021-09-21**

827) KIA SPORTAGE — year: **2014=>** — program № **11244** — from **2017-09-01**

828) KIA SPORTAGE (Keyless) — year: **2011=>** — program № **11244** — from **2017-09-01**

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars



1082) MINI COOPER (F55)	year: **2015=>**	program № **11724**	from **2020-11-19**
1083) MINI COOPER (F56)	year: **2015=>**	program № **11724**	from **2020-11-19**
1084) MINI COOPER (F57)	year: **2015=>**	program № **11724**	from **2020-11-19**
1085) MINI COOPER (R56)	year: **2006=>**	program № **11118**	from **2020-11-19**
1086) MINI COOPER (R56) (Keyless)	year: **2006=>**	program № **11137**	from **2020-11-19**
1087) MINI COOPER D (F55)	year: **2015=>**	program № **11724**	from **2020-11-19**
1088) MINI COOPER S (R56)	year: **2013=>**	program № **11118**	from **2020-11-19**
1089) MINI COOPER S (R56) (Keyless)	year: **2013=>**	program № **11137**	from **2020-11-19**
1090) MINI COUNTRYMAN (F60)	year: **2017=>**	program № **12683**	from **2021-07-20**
1091) MINI COUNTRYMAN (R60)	year: **2010=>**	program № **11118**	from **2020-11-19**
1092) MINI COUNTRYMAN (R60) (Keyless)	year: **2010=>**	program № **11137**	from **2020-11-19**
1093) MINI JCW (F56)	year: **2016=>**	program № **13263**	from **2021-07-20**
1094) MINI ONE (R56)	year: **2007=>**	program № **11118**	from **2020-11-19**
1095) MINI ONE (R56) (Keyless)	year: **2007=>**	program № **11137**	from **2020-11-19**
1096) MINI PACEMAN (R61)	year: **2013=>**	program № **11118**	from **2020-11-19**
1097) MINI PACEMAN (R61) (Keyless)	year: **2013=>**	program № **11137**	from **2020-11-19**
1098) MITSUBISHI ASX	year: **2017=>**	program № **13731**	from **2021-06-15**
1099) MITSUBISHI ASX	year: **2014=>**	program № **13412**	from **2020-10-20**
1100) MITSUBISHI ASX	year: **2010=>**	program № **13387**	from **2020-10-19**
1101) MITSUBISHI COLT	year: **2008=>**	program № **11394**	from **2017-09-01**
1102) MITSUBISHI ECLIPSE CROSS (Keyless)	year: **2018=>**	program № **12655**	from **2020-10-12**
1103) MITSUBISHI L200	year: **2015=>**	program № **11712**	from **2018-04-11**
1104) MITSUBISHI L200	year: **2006=>**	program № **11179**	from **2017-09-01**
1105) MITSUBISHI LANCER (X)	year: **2011=>**	program № **11451**	from **2017-09-01**
1106) MITSUBISHI LANCER (CY)	year: **2008=>**	program № **14183**	from **2022-03-29**
1107) MITSUBISHI OUTLANDER (Keyless)	year: **2018=>**	program № **12643**	from **2020-10-12**
1108) MITSUBISHI OUTLANDER (Keyless)	year: **2015=>**	program № **11393**	from **2020-10-12**
1109) MITSUBISHI OUTLANDER	year: **2015=>**	program № **13373**	from **2020-10-12**
1110) MITSUBISHI OUTLANDER (Keyless)	year: **2013=>**	program № **11393**	from **2020-10-12**
1111) MITSUBISHI OUTLANDER	year: **2013=>**	program № **11393**	from **2020-10-12**
1112) MITSUBISHI OUTLANDER (XL)	year: **2007=>**	program № **11142**	from **2017-09-01**
1113) MITSUBISHI OUTLANDER SPORT (RHD)	year: **2010=>**	program № **12546**	from **2018-11-14**
1114) MITSUBISHI PAJERO	year: **2012=>**	program № **11178**	from **2017-09-01**
1115) MITSUBISHI PAJERO	year: **2007=>**	program № **11178**	from **2017-09-01**
1116) MITSUBISHI PAJERO SPORT	year: **2016=>**	program № **12161**	from **2017-11-16**
1117) MITSUBISHI PAJERO SPORT	year: **2013=>**	program № **11179**	from **2017-09-01**

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars



1299) PORSCHE CAYMAN	year: 2006=>	program № 11153	from 2022-06-15
1300) PORSCHE CAYMAN S	year: 2006=>	program № 11153	from 2022-06-15
1301) PORSCHE MACAN (95)	year: 2019=>	program № 13372	from 2020-10-07
1302) PORSCHE MACAN (95)	year: 2014=>	program № 13279	from 2020-08-14
1303) PORSCHE PANAMERA (971)	year: 2017=>	program № 12749	from 2022-05-31
1304) PORSCHE PANAMERA (970)	year: 2009=>	program № 13599	from 2021-04-15
1305) RAM 1000	year: 2022=>	program № 13937	from 2021-12-31
1306) RAM 1500	year: 2019=>	program № 12526	from 2021-03-25
1307) RAM 1500	year: 2013=>	program № 11332	from 2017-09-01
1308) RAM 1500 CLASSIC	year: 2018=>	program № 13593	from 2021-03-23
1309) RAM 1500 PROMASTER	year: 2020=>	program № 13258	from 2022-06-22
1310) RAM 1500 PROMASTER	year: 2017=>	program № 12668	from 2019-05-16
1311) RAM 1500 PROMASTER	year: 2014=>	program № 12667	from 2019-05-29
1312) RAM 2500 PROMASTER	year: 2020=>	program № 13258	from 2022-06-22
1313) RAM 2500 PROMASTER	year: 2017=>	program № 12668	from 2019-05-29
1314) RAM 2500 PROMASTER	year: 2014=>	program № 12667	from 2019-05-29
1315) RAM 3500 PROMASTER	year: 2020=>	program № 13258	from 2022-06-22
1316) RAM 3500 PROMASTER	year: 2017=>	program № 12668	from 2019-05-29
1317) RAM 3500 PROMASTER	year: 2014=>	program № 12667	from 2019-05-29
1318) RAM 700	year: 2021=>	program № 13935	from 2021-12-09
1319) RAM PROMASTER CITY	year: 2017=>	program № 12674	from 2019-05-21
1320) RAM PROMASTER CITY	year: 2015=>	program № 12669	from 2019-05-29
1321) RENAULT ARKANA	year: 2022=>	program № 13715	from 2022-04-20
1322) RENAULT ARKANA (Hybrid)	year: 2022=>	program № 14188	from 2022-05-10
1323) RENAULT ARKANA (RussianMarket)	year: 2020=>	program № 13398	from 2020-12-17
1324) RENAULT CAPTUR II	year: 2020=>	program № 12984	from 2022-05-10
1325) RENAULT CAPTUR II (Hybrid)	year: 2020=>	program № 14194	from 2022-07-08
1326) RENAULT CAPTUR I	year: 2017=>	program № 12343	from 2018-05-21
1327) RENAULT CAPTUR I	year: 2013=>	program № 11372	from 2017-09-01
1328) RENAULT CLIO V	year: 2020=>	program № 12853	from 2022-05-10
1329) RENAULT CLIO V (Hybrid) (Keyless)	year: 2020=>	program № 13445	from 2022-04-20
1330) RENAULT CLIO IV	year: 2017=>	program № 12344	from 2018-05-29
1331) RENAULT CLIO IV	year: 2012=>	program № 11372	from 2017-09-01
1332) RENAULT CLIO III	year: 2005=>	program № 11174	from 2021-09-09
1333) RENAULT DOKKER	year: 2012=>	program № 11574	from 2017-09-01
1334) RENAULT DUSTER	year: 2014=>	program № 11283	from 2017-09-01

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| | Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars



1657) TOYOTA YARIS CROSS (Start-button) (Hybrid)	year: 2021=>	program № 13888	from 2022-04-25
1658) TOYOTA YARIS CROSS (Regular-key) (Hybrid)	year: 2021=>	program № 14181	from 2022-03-25
1659) UAZ PATRIOT	year: 2016=>	program № 11845	from 2022-06-01
1660) VOLVO C30	year: 2007=>	program № 11123	from 2017-09-01
1661) VOLVO C70	year: 2007=>	program № 11123	from 2017-09-01
1662) VOLVO S40	year: 2005=>	program № 11123	from 2017-09-01
1663) VOLVO S40	year: 2004=>	program № 11123	from 2017-09-01
1664) VOLVO S60	year: 2019=>	program № 13228	from 2022-05-20
1665) VOLVO S60	year: 2011=>	program № 11294	from 2017-09-01
1666) VOLVO S60	year: 2005=>	program № 11124	from 2017-09-01
1667) VOLVO S60	year: 2003=>	program № 11134	from 2017-09-01
1668) VOLVO S80	year: 2012=>	program № 11295	from 2017-09-01
1669) VOLVO S80	year: 2007=>	program № 11144	from 2017-09-01
1670) VOLVO S80	year: 2005=>	program № 11124	from 2017-09-01
1671) VOLVO S80	year: 2003=>	program № 11134	from 2017-09-01
1672) VOLVO S90	year: 2021=>	program № 14211	from 2022-05-20
1673) VOLVO S90	year: 2017=>	program № 12414	from 2022-05-20
1674) VOLVO V40 CROSS COUNTRY	year: 2015=>	program № 11565	from 2017-09-01
1675) VOLVO V40 (CROSS COUNTRY) (Keyless)	year: 2013=>	program № 11414	from 2017-09-01
1676) VOLVO V40 CROSS COUNTRY	year: 2013=>	program № 11414	from 2017-09-01
1677) VOLVO V50	year: 2005=>	program № 11123	from 2017-09-01
1678) VOLVO V50	year: 2004=>	program № 11123	from 2017-09-01
1679) VOLVO V60	year: 2019=>	program № 13377	from 2022-05-20
1680) VOLVO V60	year: 2011=>	program № 11294	from 2017-09-01
1681) VOLVO V70	year: 2008=>	program № 11144	from 2017-09-01
1682) VOLVO V70	year: 2005=>	program № 11124	from 2017-09-01
1683) VOLVO V70	year: 2003=>	program № 11134	from 2017-09-01
1684) VOLVO V90	year: 2021=>	program № 14214	from 2022-05-20
1685) VOLVO V90	year: 2017=>	program № 11956	from 2022-05-20
1686) VOLVO XC40	year: 2019=>	program № 13434	from 2022-05-20
1687) VOLVO XC60	year: 2021=>	program № 13621	from 2022-05-20
1688) VOLVO XC60	year: 2018=>	program № 13229	from 2022-05-20
1689) VOLVO XC60	year: 2014=>	program № 11294	from 2017-09-01
1690) VOLVO XC60	year: 2012=>	program № 11294	from 2017-09-01
1691) VOLVO XC60	year: 2010=>	program № 11144	from 2017-09-01
1692) VOLVO XC60	year: 2008=>	program № 11144	from 2017-09-01

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • AdBlue level (in liters) | • Acceleration pedal position | • Engine torque | • Retarder torque | • Distance to service | • Distance exceed service | • Distance after service | • Time to service | • Time exceed service | • Time after service | • Service - distance to next oil service | • Service - time to next oil service | • HV battery temperature | • HV battery level | • Outside temperature | • Battery voltage | • Total CNG consumption - (counted) | • CNG level (in percent) | • Vehicle range | • Gross comb. vehicle weight | • Vehicle's range on CNG | • Brake pedal position | • Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Cars

| Ignition | Key inserted | Webasto | Engine working | Ready to drive (READY) | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on LPG | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Glow plug indicator | Particulate filter (FAP/DPF) | Electronic Power Control | Alarm coolant level | Air filter is plugged | Fuel filter is plugged | Water in fuel | Washer fluid level indicator turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Battery voltage | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Vehicle's range on CNG | Brake pedal position | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Electric cars

| Ignition | Key inserted | Engine working | Ready to drive (READY) | Vehicle working mode | No operator! | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Charging cable connected | HV battery charging | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Electronic Power Control | Alarm coolant level | Fuel filter is plugged | Washer fluid level indicator turned on | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Acceleration pedal position | Engine torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Vehicle range | Vehicle's range on HV battery |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Electric cars

| Ignition | Key inserted | Engine working | Ready to drive (READY) | Vehicle working mode | No operator! | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Charging cable connected | HV battery charging | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Electronic Power Control | Alarm coolant level | Fuel filter is plugged | Washer fluid level indicator turned on | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Acceleration pedal position | Engine torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Vehicle range | Vehicle's range on HV battery |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Electric cars

| Ignition | Key inserted | Engine working | Ready to drive (READY) | Vehicle working mode | No operator! | Handbrake | Foodbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Charging cable connected | HV battery charging | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Electronic Power Control | Alarm coolant level | Fuel filter is plugged | Washer fluid level indicator turned on | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Acceleration pedal position | Engine torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Vehicle range | Vehicle's range on HV battery |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Electric cars

| Ignition | Key inserted | Engine working | Ready to drive (READY) | Vehicle working mode | No operator! | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Charging cable connected | HV battery charging | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Electronic Power Control | Alarm coolant level | Fuel filter is plugged | Washer fluid level indicator turned on | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Acceleration pedal position | Engine torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Vehicle range | Vehicle's range on HV battery |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Electric cars

| Ignition | Key inserted | Engine working | Ready to drive (READY) | Vehicle working mode | No operator! | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Engine cover (Hood) | Charging cable connected | HV battery charging | Electric engine working | Car locked with the factory remote | Central locking status | Factory alarm | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | The original remote of the car - Open trunk | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | AC turned on | Cruise control | Driver's seat belt | Passenger's seat belt | Left rear seat belt | Right rear seat belt | Middle rear seat belt | Passenger's presence | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Electronic Power Steering System (EPS) | Warning | Lights failure | Low tire pressure | Wear of brake pads | Low fuel | Maintenance required | Electronic Power Control | Alarm coolant level | Fuel filter is plugged | Washer fluid level indicator turned on | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Acceleration pedal position | Engine torque | Distance to service | Distance exceed service | Distance after service | Time to service | Time exceed service | Time after service | Service - distance to next oil service | Service - time to next oil service | HV battery temperature | HV battery level | Outside temperature | Vehicle range | Vehicle's range on HV battery |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks

| Ignition | Key inserted | Webasto | Engine working | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Car locked with the factory remote | Central locking status | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on dual fuel | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Rear light ON | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Warning | Lights failure | Low fuel | Glow plug indicator | Particulate filter (FAP/DPF) | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Time to service | Time exceed service | Outside temperature | Battery voltage | Cargo weight | Total CNG use | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Brake pedal position | CNG level (in bars) | Engine work time on CNG | Total LNG use | Total LNG use - (counted) | LNG level (in percent) | Engine work time on primary fuel since gas system has been installed | Engine work time on dual fuel since gas system has been installed | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks

| | Ignition | Key inserted | Webasto | Engine working | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Car locked with the factory remote | Central locking status | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on dual fuel | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Rear light ON | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Warning | Lights failure | Low fuel | Glow plug indicator | Particulate filter (FAP/DPF) | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Time to service | Time exceed service | Outside temperature | Battery voltage | Cargo weight | Total CNG use | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Brake pedal position | CNG level (in bars) | Engine work time on CNG | Total LNG use | Total LNG use - (counted) | LNG level (in percent) | Engine work time on primary fuel since gas system has been installed | Engine work time on dual fuel since gas system has been installed | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks

| | Ignition | Key inserted | Webasto | Engine working | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Car locked with the factory remote | Central locking status | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on dual fuel | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Rear light ON | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Warning | Lights failure | Low fuel | Glow plug indicator | Particulate filter (FAP/DPF) | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Time to service | Time exceed service | Outside temperature | Battery voltage | Cargo weight | Total CNG use | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Brake pedal position | CNG level (in bars) | Engine work time on CNG | Total LNG use | Total LNG use - (counted) | LNG level (in percent) | Engine work time on primary fuel since gas system has been installed | Engine work time on dual fuel since gas system has been installed | Tacho Level 1 |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks

| | Ignition | Key inserted | Webasto | Engine working | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Car locked with the factory remote | Central locking status | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on dual fuel | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Rear light ON | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Warning | Lights failure | Low fuel | Glow plug indicator | Particulate filter (FAP/DPF) | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Time to service | Time exceed service | Outside temperature | Battery voltage | Cargo weight | Total CNG use | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Brake pedal position | CNG level (in bars) | Engine work time on CNG | Total LNG use | Total LNG use - (counted) | LNG level (in percent) | Engine work time on primary fuel since gas system has been installed | Engine work time on dual fuel since gas system has been installed | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks



103) MAN TGX (EURO 6) year: **2016=>** program № **11219** from **2022-01-11**

104) MAN TGX (EURO 5) (TACHO SIMPLE) year: **2013=>** program № **11219** from **2022-01-11**

105) MAN TGX (EURO 5) year: **2013=>** program № **11219** from **2022-01-11**

106) MAN TGX (EURO 4) (TACHO SIMPLE) year: **2007=>** program № **11219** from **2022-01-11**

107) MAN TGX (EURO 4) year: **2007=>** program № **11219** from **2022-01-11**

108) MAN TGX EFFICIENT LINE (EURO 6) year: **2017=>** program № **12438** from **2022-04-19**

109) MAZ 6310 (EURO 4) year: **2014=>** program № **12143** from **2017-09-28**

110) MAZ 6430B9 (EURO 4) year: **2015=>** program № **13235** from **2020-08-06**

111) MAZ 6430C9 (EURO 4) year: **2020=>** program № **13236** from **2020-08-06**

112) MAZ 6501B5 (EURO 4) year: **2014=>** program № **11639** from **2017-09-01**

113) MERCEDES ACTROS MP5 (EURO 6) year: **2022=>** program № **14178** from **2022-04-20**

114) MERCEDES ACTROS MP5 (EURO 6) year: **2019=>** program № **12761** from **2019-12-10**

115) MERCEDES ACTROS MP5 (EURO 6) (FMS) year: **2019=>** program № **13274** from **2020-10-14**

116) MERCEDES ACTROS MP3 (TACHO SIMPLE) year: **2013=>** program № **11347** from **2020-10-15**

117) MERCEDES ACTROS MP4 (EURO 6) year: **2011=>** program № **11862** from **2019-10-28**

118) MERCEDES ACTROS MP3 (TACHO SIMPLE) year: **2008=>** program № **11347** from **2020-10-15**

119) MERCEDES ACTROS MP3 year: **2008=>** program № **11148** from **2020-10-15**

120) MERCEDES ACTROS MP2 (TACHO SIMPLE) year: **2003=>** program № **11347** from **2020-10-15**

121) MERCEDES ACTROS MP2 year: **2003=>** program № **11148** from **2020-10-15**

122) MERCEDES ACTROS MP1 year: **1997=>** program № **11148** from **2020-10-15**

123) MERCEDES ANTOS (EURO 6) year: **2013=>** program № **11861** from **2019-10-28**

124) MERCEDES AROCS (EURO 6) year: **2019=>** program № **13675** from **2021-12-21**

125) MERCEDES AROCS (EURO 6) year: **2013=>** program № **11857** from **2019-10-28**

126) MERCEDES ATEGO (EURO 6) year: **2016=>** program № **12135** from **2022-01-11**

127) MERCEDES ATEGO (EURO 5) year: **2009=>** program № **11148** from **2020-10-15**

128) MERCEDES ATEGO (TACHO SIMPLE) year: **2004=>** program № **11347** from **2020-10-15**

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks



129) MERCEDES ATEGO — year: **2004=>** — program № **11148** — from **2020-10-15**

130) MERCEDES AXOR (TACHO SIMPLE) — year: **2014=>** — program № **11347** — from **2020-10-15**

131) MERCEDES AXOR (EURO 5) (TACHO SIMPLE) — year: **2009=>** — program № **12287** — from **2020-10-15**

132) MERCEDES AXOR (TACHO SIMPLE) — year: **2006=>** — program № **11347** — from **2020-10-15**

133) MERCEDES AXOR — year: **2006=>** — program № **11148** — from **2020-10-15**

134) MERCEDES AXOR (JK3 option) — year: **2002=>** — program № **11148** — from **2020-10-15**

135) MERCEDES UNIMOG U400 — year: **2006=>** — program № **11148** — from **2017-09-01**

136) MERCEDES UNIMOG U400 (TACHO SIMPLE) — year: **2006=>** — program № **11347** — from **2020-10-15**

137) MERCEDES UNIMOG U500 (EURO 4) — year: **2006=>** — program № **11854** — from **2020-10-15**

138) MITSUBISHI FUSO CANTER — year: **2016=>** — program № **12473** — from **2018-09-20**

139) MITSUBISHI FUSO CANTER (RussianMarket) — year: **2015=>** — program № **12149** — from **2017-10-04**

140) MITSUBISHI FUSO CANTER (IndonesianMarket) — year: **2012=>** — program № **13437** — from **2021-01-12**

141) MITSUBISHI FUSO CANTER — year: **2012=>** — program № **11499** — from **2017-09-01**

142) NAVECO C300 — year: **2015=>** — program № **12244** — from **2018-03-01**

143) NISSAN CABSTAR — year: **2007=>** — program № **11289** — from **2021-09-09**

144) RENAULT C (EURO 6) — year: **2013=>** — program № **13962** — from **2021-12-14**

145) RENAULT D (EURO 6) — year: **2014=>** — program № **13714** — from **2021-07-01**

146) RENAULT K (EURO 6) — year: **2018=>** — program № **12672** — from **2022-01-11**

147) RENAULT KERAX 420 (dCi) (EURO3) — year: **2005=>** — program № **14152** — from **2022-03-18**

148) RENAULT KERAX DCi (633) — year: **2005=>** — program № **11223** — from **2017-09-01**

149) RENAULT MAGNUM DCi (611) — year: **2004=>** — program № **11223** — from **2017-09-01**

150) RENAULT MAGNUM DXi (617) (TACHO SIMPLE) — year: **2006=>** — program № **11418** — from **2019-03-18**

151) RENAULT MAGNUM DXi (617) — year: **2006=>** — program № **11418** — from **2017-09-01**

152) RENAULT MASCOTT — year: **2004=>** — program № **12281** — from **2018-04-16**

153) RENAULT MIDLUM DCi (642) — year: **2005=>** — program № **11223** — from **2017-09-01**

154) RENAULT MIDLUM DCi — year: **2002=>** — program № **11223** — from **2017-09-01**

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks

| Ignition | Key inserted | Webasto | Engine working | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Car locked with the factory remote | Central locking status | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on dual fuel | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Rear light ON | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Warning | Lights failure | Low fuel | Glow plug indicator | Particulate filter (FAP/DPF) | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Time to service | Time exceed service | Outside temperature | Battery voltage | Cargo weight | Total CNG use | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Brake pedal position | CNG level (in bars) | Engine work time on CNG | Total LNG use | Total LNG use - (counted) | LNG level (in percent) | Engine work time on primary fuel since gas system has been installed | Engine work time on dual fuel since gas system has been installed | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks

| | Ignition | Key inserted | Webasto | Engine working | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Car locked with the factory remote | Central locking status | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on dual fuel | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Rear light ON | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Warning | Lights failure | Low fuel | Glow plug indicator | Particulate filter (FAP/DPF) | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Time to service | Time exceed service | Outside temperature | Battery voltage | Cargo weight | Total CNG use | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Brake pedal position | CNG level (in bars) | Engine work time on CNG | Total LNG use | Total LNG use - (counted) | LNG level (in percent) | Engine work time on primary fuel since gas system has been installed | Engine work time on dual fuel since gas system has been installed | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Trucks

| | Ignition | Key inserted | Webasto | Engine working | Engine is working on CNG | Vehicle working mode | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | Front left door | Front right door | Rear left door | Rear right door | Trunk cover | Car locked with the factory remote | Central locking status | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | The original remote of the car - Rearming | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Engine is working on dual fuel | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Rear light ON | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | ABS | Electronics Stability Control (ESP) | Electronic stability program off (ESP OFF) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | AIRBAG | Warning | Lights failure | Low fuel | Glow plug indicator | Particulate filter (FAP/DPF) | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | Distance to service | Distance exceed service | Time to service | Time exceed service | Outside temperature | Battery voltage | Cargo weight | Total CNG use | Total CNG consumption - (counted) | CNG level (in percent) | Vehicle range | Gross comb. vehicle weight | Brake pedal position | CNG level (in bars) | Engine work time on CNG | Total LNG use | Total LNG use - (counted) | LNG level (in percent) | Engine work time on primary fuel since gas system has been installed | Engine work time on dual fuel since gas system has been installed | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Buses

| Ignition | Key inserted | Webasto | Engine working | Vehicle working mode | Handbrake | Footbrake | Clutch | Front left door | Front right door | Rear left door | Rear right door | Car locked with the factory remote | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | Low fuel | Glow plug indicator | Total engine work time (dashboard) • | Total engine work time - (counted) • | Total mileage of the vehicle (dashboard) • | Vehicle mileage - (counted) • | Total fuel consumption • | Total fuel consumption - (counted) • | Fuel level (in percent) • | Engine speed (RPM) • | Engine temperature • | Vehicle speed • | Axle 1 load • | Axle 2 load • | Axle 3 load • | Axle 4 load • | Axle 5 load • | Fuel rate • | AdBlue level (in percent) • | AdBlue level (in liters) • | Acceleration pedal position • | Engine torque • | Retarder torque • | Outside temperature • | Battery voltage • | Cargo weight • | Gross comb. vehicle weight • | Brake pedal position • | Tacho Level 1 • |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Buses

| Ignition | Key inserted | Webasto | Engine working | Vehicle working mode | Handbrake | Footbrake | Clutch | Front left door | Front right door | Rear left door | Rear right door | Car locked with the factory remote | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | Low fuel | Glow plug indicator | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Outside temperature | Battery voltage | Cargo weight | Gross comb. vehicle weight | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Buses

| Ignition | Key inserted | Webasto | Engine working | Vehicle working mode | Handbrake | Footbrake | Clutch | Front left door | Front right door | Rear left door | Rear right door | Car locked with the factory remote | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | Low fuel | Glow plug indicator | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Outside temperature | Battery voltage | Cargo weight | Gross comb. vehicle weight | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Buses

| Ignition | Key inserted | Webasto | Engine working | Vehicle working mode | Handbrake | Footbrake | Clutch | Front left door | Front right door | Rear left door | Rear right door | Car locked with the factory remote | Emulated alarm | Original remote - CLOSE | Original remote - OPEN | UCMD_SLEEP | Original remote - 3x arm | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | Low fuel | Glow plug indicator | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | Fuel rate | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Outside temperature | Battery voltage | Cargo weight | Gross comb. vehicle weight | Brake pedal position | Tacho Level 1 |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery - Grain harvester

| | Ignition | Engine working | Vehicle working mode | No operator! | Handbrake | Footbrake | Status of the hazard warning lights switch | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Front light ON | Rear light ON | Light signal turned on | AC turned on | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | Low fuel | Maintenance required | Oil filter of engine is plugged | Alarm oil pressure in engine | Engine oil temperature too high | Alarm coolant level | Drain filter in is plugged | Low hydraulic system pressure | Low hydraulic oil level | Too high hydraulic system oil temp. | Overflow chamber of hydraulic unit | Air filter is plugged | Fuel filter is plugged | Water in fuel | Filter of brakes system is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Mowing | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Cleaning fan control turned off | Threshing drum control turned off | Straw walker is plugged | Excessive clearance under the threshing drum | Feeder belt turned on | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • AdBlue level (in percent) | • Harvesting time | • Harvested area | • Mowing efficiency | • Grain mown volume | • Grain moisture | • Acceleration pedal position | • Engine torque | • Threshing drum RPM | • Gap under threshing drum | • Outside temperature | • Battery voltage |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery - Grain harvester

| | Ignition | Engine working | Vehicle working mode | No operator! | Handbrake | Footbrake | Status of the hazard warning lights switch | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Front light ON | Rear light ON | Light signal turned on | AC turned on | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | Low fuel | Maintenance required | Oil filter of engine is plugged | Alarm oil pressure in engine | Engine oil temperature too high | Alarm coolant level | Drain filter in is plugged | Low hydraulic system pressure | Low hydraulic oil level | Too high hydraulic system oil temp. | Overflow chamber of hydraulic unit | Air filter is plugged | Fuel filter is plugged | Water in fuel | Filter of brakes system is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Mowing | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Cleaning fan control turned off | Threshing drum control turned off | Straw walker is plugged | Excessive clearance under the threshing drum | Feeder belt turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Grain mown volume | Grain moisture | Acceleration pedal position | Engine torque | Threshing drum RPM | Gap under threshing drum | Outside temperature | Battery voltage |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery - Grain harvester

| | Ignition | Engine working | Vehicle working mode | No operator! | Handbrake | Footbrake | Status of the hazard warning lights switch | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Front light ON | Rear light ON | Light signal turned on | AC turned on | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | Low fuel | Maintenance required | Oil filter of engine is plugged | Alarm oil pressure in engine | Engine oil temperature too high | Alarm coolant level | Drain filter in is plugged | Low hydraulic system pressure | Low hydraulic oil level | Too high hydraulic system oil temp. | Overflow chamber of hydraulic unit | Air filter is plugged | Fuel filter is plugged | Water in fuel | Filter of brakes system is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Mowing | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Cleaning fan control turned off | Threshing drum control turned off | Straw walker is plugged | Excessive clearance under the threshing drum | Feeder belt turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Grain mown volume | Grain moisture | Acceleration pedal position | Engine torque | Threshing drum RPM | Gap under threshing drum | Outside temperature | Battery voltage |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery - Grain harvester

| | Ignition | Engine working | Vehicle working mode | No operator! | Handbrake | Footbrake | Status of the hazard warning lights switch | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Front light ON | Rear light ON | Light signal turned on | AC turned on | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Handbrake system | Low fuel | Maintenance required | Oil filter of engine is plugged | Alarm oil pressure in engine | Engine oil temperature too high | Alarm coolant level | Drain filter in is plugged | Low hydraulic system pressure | Low hydraulic oil level | Too high hydraulic system oil temp. | Overflow chamber of hydraulic unit | Air filter is plugged | Fuel filter is plugged | Water in fuel | Filter of brakes system is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Mowing | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Cleaning fan control turned off | Threshing drum control turned off | Straw walker is plugged | Excessive clearance under the threshing drum | Feeder belt turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Grain mown volume | Grain moisture | Acceleration pedal position | Engine torque | Threshing drum RPM | Gap under threshing drum | Outside temperature | Battery voltage |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Right joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Right joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| | Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| | Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| | Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Agricultural machinery

| Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Lights failure | Low fuel | Maintenance required | Engine oil temperature too high | Alarm coolant level | Low hydraulic system pressure | Low hydraulic oil level | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Front TPL turned on | Rear TPH turned on | Front PTO turned on | Rear PTO turned on | Moving | Threshing | Grain release from hopper | Grain tank is 100% full | Grain tank is 70% full | Grain tank is open | Unloading tube pivot is in idle position | Spreading turned on | Liquid pump turned on | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | AdBlue level (in percent) | Harvesting time | Harvested area | Mowing efficiency | Acceleration pedal position | Engine torque | Threshing drum RPM | Time to service | Outside temperature | Battery voltage | Gross comb. vehicle weight | The total amount of bales | Number of bales | Number of cut bales | The number of bale pieces | Total treated area | Level of liquid in tank | Spray pressure | Actual dose | Area that can be treated until tank is empty | Distance remaining until tank is empty | Rear PTO rotational speed | Front PTO rotational speed |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

| Construction machinery | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

TELTONIKA

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | • Total engine work time (dashboard) | • Total engine work time - (counted) | • Total mileage of the vehicle (dashboard) | • Vehicle mileage - (counted) | • Total fuel consumption | • Total fuel consumption - (counted) | • Fuel level (in percent) | • Fuel level (in liters) | • Engine speed (RPM) | • Engine temperature | • Vehicle speed | • Fuel rate | • AdBlue level (in percent) | • Acceleration pedal position | • Engine torque | • Retarder torque | • The slope of the arm | • Rotation of the arm | • Eject of the arm | • Distance between arm and vehicle | • Outside temperature | • Drill RPM | • Battery voltage | • Cargo weight | • Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| | Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Construction machinery

| Ignition | Webasto | Engine working | Vehicle working mode | No operator! | Permission to work hydraulics | Handbrake | Footbrake | Clutch | Status of the hazard warning lights switch | UCMD_SLEEP | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Rear fog lights | Front fog lights | Front light ON | Rear light ON | Light signal turned on | AC turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | STOP | Oil pressure / level | Coolant temperature / level | Battery charging | Warning | Low fuel | Maintenance required | Glow plug indicator | Alarm oil pressure in engine | Engine oil temperature too high | Drain filter in is plugged | Low hydraulic oil level | Too high hydraulic system oil temp. | Air filter is plugged | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Fuel level (in liters) | Engine speed (RPM) | Engine temperature | Vehicle speed | Fuel rate | AdBlue level (in percent) | Acceleration pedal position | Engine torque | Retarder torque | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Outside temperature | Drill RPM | Battery voltage | Cargo weight | Brake pedal position |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Forest machinery

Ignition	Engine working	Vehicle working mode	Permission to work hydraulics	Handbrake	Footbrake	Front left door	Reverse	Neutral	Drive	Parking lights	Dipped headlights	Full beam headlights	Front light ON	Right joystick moved right	Right joystick moved left	Right joystick moved front	Right joystick moved back	Left joystick moved right	Left joystick moved left	Left joystick moved front	Left joystick moved back	First front hydraulic	Second front hydraulic	Third front hydraulic	Fourth front hydraulic	Total engine work time (dashboard)	Total engine work time - (counted)	Vehicle mileage - (counted)	Total fuel consumption	Total fuel consumption - (counted)	Fuel level (in percent)	Engine speed (RPM)	Engine temperature	Vehicle speed	AdBlue level (in percent)	Acceleration pedal position	Engine torque	Outside temperature
•	•	BUSINESS DRIVE					R	N	D					R	R	R	R	L	L	L	L	F1	F2	F3	F4	•	•	•	•	•	•	•	•	•	•	•	•	•
1) JOHN DEERE 1010D (Forwarder) year: **2008=>** program № **11329** from **2017-09-01**																																				
+	+			+																						+	+	+	+	+	+	+	+	+				
2) JOHN DEERE 1010D (Forwarder) year: **2003=>** program № **11329** from **2017-09-01**																																				
+	+			+																						+	+	+	+	+	+	+	+	+				
3) JOHN DEERE 1010E (Forwarder) year: **2009=>** program № **11441** from **2017-09-01**																																				
+	+			+	+																					+	+	+	+	+	+	+	+	+		+	+	
4) JOHN DEERE 1070D (Harvester) year: **2007=>** program № **11329** from **2017-09-01**																																				
+	+			+																						+	+	+	+	+	+	+	+	+				
5) JOHN DEERE 1070E (Harvester) year: **2009=>** program № **11441** from **2017-09-01**																																				
+	+			+	+																					+	+	+	+	+	+	+	+	+		+	+	
6) JOHN DEERE 1210E (Forwarder) year: **2009=>** program № **11441** from **2017-09-01**																																				
+	+			+	+																					+	+	+	+	+	+	+	+	+		+	+	
7) JOHN DEERE 1270D (Harvester) year: **2006=>** program № **11329** from **2017-09-01**																																				
+	+			+																						+	+	+	+	+	+	+	+	+				
8) JOHN DEERE 1270G (Harvester) year: **2016=>** program № **12912** from **2020-02-06**																																				
+	+	+		+			+	+	+	+	+	+	+	+	+	+	+	+	+	+	+					+	+		+	+	+	+		+	+	+	
9) JOHN DEERE 1490D (Harvester) year: **2008=>** program № **11329** from **2017-09-01**																																				
+	+			+																						+	+	+	+	+	+	+	+	+				
10) JOHN DEERE 1510G (Forwarder) year: **2018=>** program № **12913** from **2020-02-06**																																				
+	+	+		+			+	+	+	+	+	+	+	+	+	+	+	+	+	+	+					+	+		+	+	+	+		+	+	+	
11) JOHN DEERE 770D (Harvester) year: **2006=>** program № **11329** from **2017-09-01**																																				
+	+			+																						+	+	+	+	+	+	+	+	+				
12) KOMATSU 845 (Forwarder) year: **2016=>** program № **12466** from **2018-09-19**																																				
+	+	+		+		+	+	+	+					+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
13) KOMATSU 855 (Forwarder) year: **2017=>** program № **12467** from **2018-09-19**																																				
+	+	+	+	+		+	+	+	+					+	+	+	+	+	+	+	+					+	+	+	+	+	+	+	+	+	+	+	+	+
14) KOMATSU 860.4 (Forwarder) year: **2008=>** program № **11839** from **2017-09-01**																																				
+	+			+																						+	+		+	+		+	+			+		
15) KOMATSU 865 (Forwarder) year: **2012=>** program № **12468** from **2018-09-19**																																				
+	+	+		+		+	+	+	+					+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
16) KOMATSU 890.3 (Forwarder) year: **2006=>** program № **11839** from **2017-09-01**																																				
+	+																									+	+		+	+		+	+			+		
17) KOMATSU 911.5 (Harvester) year: **2011=>** program № **11839** from **2017-09-01**																																				
+	+			+			+	+																		+	+		+	+	+	+	+			+		

[en]=> P/N 24673Fxx (ALL-CAN300)

Forest machinery

Ignition	Engine working	Vehicle working mode	Permission to work hydraulics	Handbrake	Footbrake	Front left door	Reverse	Neutral	Drive	Parking lights	Dipped headlights	Full beam headlights	Front light ON	Right joystick moved right	Right joystick moved left	Right joystick moved front	Right joystick moved back	Left joystick moved right	Left joystick moved left	Left joystick moved front	Left joystick moved back	First front hydraulic	Second front hydraulic	Third front hydraulic	Fourth front hydraulic	Total engine work time (dashboard)	Total engine work time - (counted)	Vehicle mileage - (counted)	Total fuel consumption	Total fuel consumption - (counted)	Fuel level (in percent)	Engine speed (RPM)	Engine temperature	Vehicle speed	AdBlue level (in percent)	Acceleration pedal position	Engine torque	Outside temperature
•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
18) KOMATSU 931.1 (Harvester)																						year: **2011=>**									program № **11839**				from **2017-09-01**
+	+			+			+	+																	+	+		+	+	+	+	+		+		
19) PRIME TECH PT 300 (Mulcher)																						year: **2012=>**									program № **11442**				from **2017-09-01**
+	+																									+	+		+	+		+	+		+		
20) SAMPO ROSENLEW SR 1046X (Harvester)																						year: **2006=>**									program № **11442**				from **2017-09-01**
+	+																									+	+		+	+		+	+				
21) VALMET 840.3 (Forwarder)																						year: **2006=>**									program № **11442**				from **2017-09-01**
+	+																									+	+		+	+		+	+				

+	This parameter is available depending on vehicle's equipment
+	This parameter is available on the client's request
+	This parameter is available depending on vehicle's VIN number
+	This parameter may be unavailable using P400 or U400 contactless reader

[en]=> P/N 24673Fxx (ALL-CAN300)

Utility machinery

| Ignition | Key inserted | Engine working | Standalone engine working | Vehicle working mode | Handbrake | Footbrake | Parking | Reverse | Drive | Rear fog lights | Light signal turned on | Automatic retarder | Oil pressure / level | Battery charging | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | First front hydraulic | Spreading turned on | Chemistry supply turned on | Feeder belt turned on | Driving wheel lifted | Brushes turned on | Vacuum cleaner | Water supply turned on | High pressure washer (Karcher) | Unloading from the hopper | Low salt (sand) level | Low water level | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | Acceleration pedal position | Engine torque | The amount of spread salt per square meter | The amount of spread fine-grained salt | The amount of spread coarse-grained salt | The amount of spread DiMix | The amount of spread coarse-grained calcium | The amount of spread calcium chloride | The amount of spread sodium chloride | The amount of spread magnesium chloride | The amount of spread gravel | The amount of spread sand | Spread width to the left | Spread width to the right | Salt spreader work hours | Distance covered during salting |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Utility machinery

| Ignition | Key inserted | Engine working | Standalone engine working | Vehicle working mode | Handbrake | Footbrake | Parking | Reverse | Drive | Rear fog lights | Light signal turned on | Automatic retarder | Oil pressure / level | Battery charging | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | First front hydraulic | Spreading turned on | Chemistry supply turned on | Feeder belt turned on | Driving wheel lifted | Brushes turned on | Vacuum cleaner | Water supply turned on | High pressure washer (Karcher) | Unloading from the hopper | Low salt (sand) level | Low water level | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | Acceleration pedal position | Engine torque | The amount of spread salt per square meter | The amount of spread fine-grained salt | The amount of spread coarse-grained salt | The amount of spread DiMix | The amount of spread coarse-grained calcium | The amount of spread calcium chloride | The amount of spread sodium chloride | The amount of spread magnesium chloride | The amount of spread gravel | The amount of spread sand | Spread width to the left | Spread width to the right | Salt spreader work hours | Distance covered during salting |
|---|---|---

Utility machinery

| Ignition | Key inserted | Engine working | Standalone engine working | Vehicle working mode | Handbrake | Footbrake | Parking | Reverse | Drive | Rear fog lights | Light signal turned on | Automatic retarder | Oil pressure / level | Battery charging | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | First front hydraulic | Spreading turned on | Chemistry supply turned on | Feeder belt turned on | Driving wheel lifted | Brushes turned on | Vacuum cleaner | Water supply turned on | High pressure washer (Karcher) | Unloading from the hopper | Low salt (sand) level | Low water level | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | AdBlue level (in percent) | Acceleration pedal position | Engine torque | The amount of spread salt per square meter | The amount of spread fine-grained salt | The amount of spread coarse-grained salt | The amount of spread DiMix | The amount of spread coarse-grained calcium | The amount of spread calcium chloride | The amount of spread sodium chloride | The amount of spread magnesium chloride | The amount of spread gravel | The amount of spread sand | Spread width to the left | Spread width to the right | Salt spreader work hours | Distance covered during salting |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Special machinery

| | Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Interlock system | Permission to work hydraulics | Handbrake | Footbrake | Status of the hazard warning lights switch | Front left door | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Front light ON | Rear light ON | Light signal turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | Oil pressure / level | Coolant temperature / level | Battery charging | Glow plug indicator | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Spreading turned on | Liquid pump turned on | Chemicals | Compressor | Cabin up | Cabin down | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Time to service | HV battery level | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Height of the arm above the ground | Level of water for fire fighting | Level of fire fighting foam | Pressure in fire fighting pump | Wind speed | Outside temperature | The amount of spread salt per square meter | Battery voltage | Spread width to the left | Spread width to the right | Cargo weight | Gross comb. vehicle weight | Brake pedal position | Water valve |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Special machinery

| | Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Interlock system | Permission to work hydraulics | Handbrake | Footbrake | Status of the hazard warning lights switch | Front left door | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Front light ON | Rear light ON | Light signal turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | Oil pressure / level | Coolant temperature / level | Battery charging | Glow plug indicator | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Spreading turned on | Liquid pump turned on | Chemicals | Compressor | Cabin up | Cabin down | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Time to service | HV battery level | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Height of the arm above the ground | Level of water for fire fighting | Level of fire fighting foam | Pressure in fire fighting pump | Wind speed | Outside temperature | The amount of spread salt per square meter | Battery voltage | Spread width to the left | Spread width to the right | Cargo weight | Gross comb. vehicle weight | Brake pedal position | Water valve |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Special machinery

| | Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Interlock system | Permission to work hydraulics | Handbrake | Footbrake | Status of the hazard warning lights switch | Front left door | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Front light ON | Rear light ON | Light signal turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | Oil pressure / level | Coolant temperature / level | Battery charging | Glow plug indicator | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Spreading turned on | Liquid pump turned on | Chemicals | Compressor | Cabin up | Cabin down | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Time to service | HV battery level | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Height of the arm above the ground | Level of water for fire fighting | Level of fire fighting foam | Pressure in fire fighting pump | Wind speed | Outside temperature | The amount of spread salt per square meter | Battery voltage | Spread width to the left | Spread width to the right | Cargo weight | Gross comb. vehicle weight | Brake pedal position | Water valve |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Special machinery

| | Ignition | Key inserted | Engine working | Vehicle working mode | No operator! | Interlock system | Permission to work hydraulics | Handbrake | Footbrake | Status of the hazard warning lights switch | Front left door | Parking | Reverse | Neutral | Drive | Parking lights | Dipped headlights | Full beam headlights | Front light ON | Rear light ON | Light signal turned on | Cruise control | Automatic retarder | Manual retarder | Driver's seat belt | CHECK ENGINE (MIL) | Oil pressure / level | Coolant temperature / level | Battery charging | Glow plug indicator | Right joystick moved right | Right joystick moved left | Right joystick moved front | Right joystick moved back | Left joystick moved right | Left joystick moved left | Left joystick moved front | Left joystick moved back | First rear hydraulic | Second rear hydraulic | Third rear hydraulic | Fourth rear hydraulic | First front hydraulic | Second front hydraulic | Third front hydraulic | Fourth front hydraulic | Spreading turned on | Liquid pump turned on | Chemicals | Compressor | Cabin up | Cabin down | Total engine work time (dashboard) | Total engine work time - (counted) | Total mileage of the vehicle (dashboard) | Vehicle mileage - (counted) | Total fuel consumption | Total fuel consumption - (counted) | Fuel level (in percent) | Engine speed (RPM) | Engine temperature | Vehicle speed | Axle 1 load | Axle 2 load | Axle 3 load | Axle 4 load | Axle 5 load | AdBlue level (in percent) | AdBlue level (in liters) | Acceleration pedal position | Engine torque | Retarder torque | Time to service | HV battery level | The slope of the arm | Rotation of the arm | Eject of the arm | Distance between arm and vehicle | Height of the arm above the ground | Level of water for fire fighting | Level of fire fighting foam | Pressure in fire fighting pump | Wind speed | Outside temperature | The amount of spread salt per square meter | Battery voltage | Spread width to the left | Spread width to the right | Cargo weight | Gross comb. vehicle weight | Brake pedal position | Water valve |
|---|---|---

[en]=> P/N 24673Fxx (ALL-CAN300)

Tankers

Section 1 - the presence of fluid in the downpipe	Section 1 - full	Section 1 - overfill	Section 2 - the presence of fluid in the downpipe	Section 2 - full	Section 2 - overfill	Section 3 - the presence of fluid in the downpipe	Section 3 - full	Section 3 - overfill	Section 4 - the presence of fluid in the downpipe	Section 4 - full	Section 4 - overfill	Section 5 - the presence of fluid in the downpipe	Section 5 - full	Section 5 - overfill	Section 6 - the presence of fluid in the downpipe	Section 6 - full	Section 6 - overfill
1	1	1	2	2	2	3	3	3	4	4	4	5	5	5	6	6	6
1) OPTOLEVEL GATEWAY (v10)									year: **2009=>**						program № **11863**		from **2017-09-01**
+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+

+	This parameter is available depending on vehicle's equipment
+	This parameter is available on the client's request
+	This parameter is available depending on vehicle's VIN number
+	This parameter may be unavailable using P400 or U400 contactless reader